Ideagen? RISK MANAGEMENT REPORT

HAMMER

ТҮРЕ	Excavator - Medium (10 - 19.9 Tonne)
MAKE	Kobelco
MODEL	SK135SR-7
CHASSIS / VIN	YY09047237
PLANT NUMBER	AHSH123
Report Number	AHH 20241211-1106
Date	11-Dec-2024
Created By	AHSH Service
Assessor	AHSH Service
Assist. Assessor(s)	
Completed By	AHSH Service
Owner	Australian Hammer Supplies Hire Pty Ltd
Assessment Purpose	Hire
State	NSW

TABLE OF CONTENTS

SECTION 1	IMPORTANT INFORMATION Contains information outlining the scope and any limitations applicable to this Risk Management Report
SECTION 2	MACHINE DETAILS Contains standard machine specifications and details of any extras fitted
SECTION 3	RISK ANALYSIS, RISK EVALUATION & RISK TREATMENT Contains details of the technique used to calculate risk ratings, time frame and risk treatments. Please refer to this information when reviewing and interpreting the information in section 4 & 5
SECTION 4	RISK TREATMENTS REQUIRED Contains detailed information regarding the risk treatments to be implemented including hazard, risk rating, time frame, relevant standards & legislative references
SECTION 5	RISK TREATMENTS IN PLACE Contains detailed information regarding the risk treatments in place including hazard, risk rating, relevant standards & legislative references
SECTION 6	IMAGES AND NOTES Contains images & any relevant information entered by the assessor





SECTION 1 IMPORTANT INFORMATION

This report generated by Plant Assessor™ © Online Safety Systems on Wednesday, 11 Dec 2024 11:08 AM

This report pertains to this item of plant as it appeared on the day of inspection.

It is the responsibility of the hirer to conform with the instructions and information contained within this report. Any change in condition of this item of plant should be reported to the hire company immediately.

Any information relating to the standard features have been supplied via the manufacturer and should be used as a guide only until verified.

For further information regarding this report contact Online Safety Systems on 1300 72 88 52

SECTION 2 MACHINE DETAILS

		4. Manufactures and sife during laught DA	
S I		1. Manufacturers specified noise level dBA	
<u> </u>		2. Ambient noise level dBA	
DETAILS		3. Noise level - Operator position (high idle) dBA	
	- NOISE TEST RESULTS	4. Noise level - Operator position (low idle) dBA	
öl		5. Noise level LHS dBA @ m (high idle)	
		6. Noise level Front dBA @ m (high idle)	
ΖI		7. Noise level RHS dBA @ m (high idle)	
루니		8. Noise level Rear dBA @ m (high idle)	
Ö	BUCKET	Standard bucket capacity, SAE rated (m3)	
MACHINE		Standard bucket width (mm)	
Σ	CAPACITIES	Fuel Tank Capacity (Litres)	186
		Dig depth to cut 2.44 m level bottom (mm)	5290
\smile		Digging depth (mm)	5520
		Dump height (mm)	6750
		Ground clearance (mm)	400
		Max depth of vertical wall (mm)	4500
	DIMENSIONS/WEIGHTS	Maximum Reach Height (mm)	
		Operating weight (kg)	14500
		Tailswing radius (mm)	1490
		Transport Height (mm)	2860
		Transport Length (mm)	8070
		Width (mm)	2490
		Engine Displacement (Litres)	2.999
		Engine Hours	
	ENGINE	Engine Make & Model	Isuzu 4JJ1XDRAC
	ENGINE	Engine Number	
		Engine Power (kW@rpm)	78.6@2200 (with fan)
		Number of Cylinders	4
	EXTRAS	Spare spool for attachments? Yes/No	
		Quick Hitch Make	
	HITCH	Quick Hitch Model	
		Quick Hitch Serial No.	
		Flow of main pumps (L/Min)	
		Hydraulic Oil Reservoir Capacity (Litres)	89.9
	HYDRAULICS	Pump Types	2 x Variable displacement piston pumps
		Relief valve pressure, main pumps (Bar)	343
		Class	
	PLANT CLASSIFICATIONS	Year	
		FOPS Compliance No.	
		FOPS Serial No.	
	SAFETY STRUCTURES	ROPS Compliance No.	
		ROPS Serial No.	
		Track length on ground (mm)	3580
	TRACKS	Track pad width (mm)	500
	TRANSMISSION	Speed (km/h)	3.4/5.6 km/h
	WORK CAPABILITIES	Arm breakout (kgf)	
		1	





YY09047237

Bucket breakout (kgf)	
Gradeability - Degrees/(%)	
Reach @ ground level (mm)	8210





SECTION 3 RISK ANALYSIS / RISK EVALUATION

RI	RISK ANALYSIS							
		CONSEQUENCE						
		1. INSIGNIFICANT Dealt with by in house first aid	2. MINOR Treated by medical professionals, hospital out patients	3. MODERATE Significant non permanent injury overnight hospital stay	4. MAJOR Extensive permanent injury eg. Loss of fingers, extended hospital stay	5. CATASTROPHIC Death, permanent disabling injury eg. Loss of hand, quadriplegia		
	A. Almost certain to occur in most circumstances	MEDIUM 8	HIGH 16	HIGH 18	CRITICAL 23	CRITICAL 25		
Ļ	B. Likely to occur frequently	MEDIUM 7	MEDIUM 10	HIGH 17	HIGH 20	CRITICAL 24		
	C. Possibly and likely to occur at sometime	LOW 3	MEDIUM 9	MEDIUM 12	HIGH 19	HIGH 22		
	D. Unlikely to occur but could happen	LOW 2	LOW 5	MEDIUM 11	MEDIUM 14	HIGH 21		
	E. May occur but only in rare circumstances	LOW 1	LOW 4	LOW 6	MEDIUM 13	MEDIUM 15		

LUATION	CRITICAL	Act immediately to mitigate risk. Implement risk treatment(s) in accordance with the risk treatment table below.
		Act immediately to mitigate risk. Implement risk treatment(s) in accordance with the risk treatment table below. If the appropriate risk treatments are not immediately accessible establish interim risk treatment strategies. Permanent risk treatments must be implemented within one week.
	MEDIUM	Take reasonable steps to mitigate and monitor the risk. Implement risk treatment(s) in accordance with the risk treatment table below. Permanent risk treatments must be implemented within one month.
	LOW	Take reasonable steps to mitigate and monitor the risk. Implement risk treatment(s) in accordance with the risk treatments must be implemented within three months.

RISKTREATMENT

EATMENT		st appropriate risk treatment option involves balancing the costs and efforts of implementation against the benefits ard to legal, regulatory and other requirements. (source AS/NZS ISO 31000-2009)
TREAT	Eliminate	Eliminate the risk source.
RISKI	Substitute	Provide an alternative that is capable of performing the same task which is safer.
\square	Engineering	Provide or construct a physical barrier or guard.
Administration Develop policies, procedures, practices and guidelines in consultation with employees to mitigate the Provide training, instruction and supervision about the risk source.		Develop policies, procedures, practices and guidelines in consultation with employees to mitigate the risk. Provide training, instruction and supervision about the risk source.
	Personal protective	Provide personal protective equipment to protect the individual from the risk source.



SECTION 4 RISK TREATMENTS REQUIRED

This section of the report pertains to hazards created by use of this item of plant which currently do not have risk treatments in place. The risk treatments recommended in this section have been developed based on relevant Australian Standards, health & safety legislation, the hierarchy of risk treatment in accordance with the guidelines set forth in AS/NZS ISO 31000 – Risk Management and various other sources. The recommended risk treatment measures must be developed, implemented and validated as effective prior to the operation, maintenance or testing of this item of plant. Treatments applied must be dated and initialled adjacent the recommendations. All operators must read and understand the entire contents of this section prior to operating this item of plant.

		HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating	Time Frame	Due Date	Date Rectified	Initial
ATION	NOMINATED OPERATOR ONLY	INCORRECT OPERATION	CRITICAL 24	MEDIUM 15	Immediate	11-Dec-24		
Risk Treatment Required: Operator Competency Only persons who are qualified, trained and experienced and/or hold the relevant certification/license can operate this item of p competent/licensed person available for operation of this item of plant then only persons who are supervised by a competent/license operate this item of plant.								
	Legislation: State Health & Safety Legislation & Regulation							
	References: Work Health & Safety Act & Regulations- , Occupational Health & Safety Act & Regulations							
	Assessor Comments: HIRER OF ATTACHMENT MUST ENSURE ON SITE OPERATORS OF EQUIPMENT MEET THESE REQUIREMENTS							

SECTION 5 RISK TREATMENTS IN PLACE

This section of the report pertains to risk treatments currently in place on this item of plant. This section must be read in conjunction with the safety section of the manufacturers handbook. All operators must read and understand the entire contents of this section prior to operating this item of plant. These treatments or equivalent must remain in place at all times whilst this item of plant is in operation.

MEDIUM 15					
ruck or trailer, low loader or					
MEDIUM 15					
Risk Treatments in Place: SWMS Load Restraint Ensure that all operators follow the approved SWMS/SOP when restraining this machine for transport. References: Work Health & Safety Act & Regulations-, Occupational Health & Safety Act & Regulations					
MEDIUM 15					





HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating					
INCORRECT OPERATION	HIGH 22	MEDIUM 15					
Risk Treatments in Place: Operation Handbook The manufacturer's operation handbook has been supplied for this item of plant.							
This handbook must be available at all times to all potential operators and supervisory staff. this handbook prior to operating.	All potential operators must r	ead and be familiar with					
A complete risk assessment/Job Safety Analysis must be undertaken covering all operating processes and environments associated with this item of plant. SWMS should be produced for specific tasks associated with use of this item of plant.							
References: Work Health & Safety Act & Regulations- , Occupational Health & Safety Act	& Regulations	1					
	HIGH 22	MEDIUM 15					
Risk Treatments in Place: Quick Hitch Operation Handbook The manufacturer's operation handbook has been supplied for this quick hitch.							
This handbook must be available at all times to all potential operators and supervisory staff. this handbook prior to operating.	All potential operators must r	ead and be familiar with					
A complete risk assessment/Job Safety Analysis must be undertaken covering all operating hitch. SWMS should be produced for specific tasks associated with use of this quick hitch.	processes and environments	associated with this quick					
References: AS13031							
	HIGH 22	MEDIUM 15					
Risk Treatments in Place: Pre-op Checklist Excavator A pre-operation checklist is available for this Excavator. This checklist must be completed by	all operators prior to operati	ng this Excavator.					
References: Work Health & Safety Act & Regulations- , Occupational Health & Safety Act	& Regulations						
	HIGH 22	MEDIUM 15					
Risk Treatments in Place: SOP Excavator	'						
Safe Operation Procedures are available for this Excavator. The information in the Safe Ope	ration Procedures must be fo	llowed at all times whilst					
operating this Excavator.							
References: Work Health & Safety Act & Regulations- , Occupational Health & Safety Act	& Regulations	1					
	HIGH 22	MEDIUM 15					
Risk Treatments in Place: Control Labels All controls including all levers, buttons, pedals, switches etc. are clearly labelled as to their maintained in a clean and serviceable condition at all times.	purpose and method of opera	tion. These labels must be					
References: AS/NZS4024.1905	r	r					
CRUSHING, FALLING	HIGH 22	MEDIUM 15					
Risk Treatments in Place: Passenger Seat Label							
This item of plant is fitted with a clear hazard warning label re: Operator only, No passengers. Passengers must not be carried at anytime. This label must be clear and legible at all times whilst this item of plant is in operation.							
Legislation: State Health & Safety Legislation & Regulation							
References: AS1319-							
	HIGH 22	MEDIUM 15					
Risk Treatments in Place: ROPS Label The warning label stating that the ROPS must not be damaged at any time (including cuts, drill holes and welds) must be present, clean and legible							
at all times. References: ISO3471							



AHSH Service

11-Dec-2024

HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating				
	HIGH 22	MEDIUM 15				
Risk Treatments in Place: ROPS seat belt label This item of plant is fitted with a ROPS and has an advisory label stating that "seatbelts must be worn". This label must be present, clean and legible at all times. All operators and passengers must wear seatbelts whilst on this item of plant.						
References: AS2294, ISO3471						
	HIGH 22	MEDIUM 15				
Risk Treatments in Place: Electrical Approach Distances This item of plant has a hazard warning label re: overhead electrical hazards and minimum a adhered to strictly. These labels and tables must be present, clear and legible at all times.	approach distances fitted. The	se distances must be				
Spotters are required when working within 5 metres of the minimum approach distance of an	ny live electrical apparatus.					
Any encroach within the minimum approach distances must only occur if the following provis 1. The machine is designed to work within the minimum approach distances 2. Permission has been granted by the electricity company and 3. Safe systems of work have been documented and approved.	sions have been met -					
References: ISO31000	7					
	HIGH 22	MEDIUM 15				
Risk Treatments in Place: Before You Dig (AUS) This item of plant is fitted with a clear hazard warning label re: underground services and ad operator work area. This advice must be adhered to strictly. Digging into an electricity cable a pipe or cable may also lead to isolating a community from emergency services such as fire and legible at all times. References: ISO31000	or gas pipe can cause serious	s injury or death. Damaging				
References. ISOS 1000						
	HIGH 22	MEDIUM 15				
Risk Treatments in Place: Phone Use label This item of plant is fitted with an instruction label advising that mobile phones must not be u operators must not use a mobile phone at any time whilst operating machine. If phone use is configuration in a safe position prior to phone use. Operators MUST adhere to this advice at This label must be clear and legible at all times whilst this item of plant is in operation.	s necessary then operator mu	•••				
References: AS1319-, ISO31000						
References : A51315-, 13031000						
	HIGH 22	MEDIUM 15				
Risk Treatments in Place: Tank ID Label						
The tank(s) on this item of plant have clear, legible label(s) identifying their contents, and if a These must be present, clear and legible at all times. (this includes radiator, hydraulic, water		itrols re: the contents.				
References: Work Health & Safety Act & Regulations- , Occupational Health & Safety Act						
	HIGH 22	MEDIUM 15				
Risk Treatments in Place: Left Hand Drive Label This item of plant has a hazard warning label re: left hand drive, at the rear. It must be present, clear and legible at all times.						
References: ISO31000						
FIRE	HIGH 21	MEDIUM 15				
Risk Treatments in Place: Fire Extinguisher This item of plant is fitted with an approved and maintained fire extinguisher. Fire extinguisher(s) must be present and fully functional at all times. They must be readily accessible to the operator. Regular inspections must also be carried out in accordance with the manufacturer's requirements and AS 1851 – 1995 References: AS1851						



HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating					
INSTABILITY, CRUSHING	HIGH 21	MEDIUM 15					
Risk Treatments in Place: Boom Rated Capacity Label This item of plant has a rated capacity label fitted to each side of the boom. Ensure that these labels are clear and legible at all times whilst this item of plant is in operation. Operators must not exceed this rated capacity at any time during operation.							
References: AS1418.8	,						
INSTABILITY, CRUSHING HIGH 21 MEDIUM 15							
Risk Treatments in Place: Boom Lifting Point Table This item of plant has a lifting point fitted to the boom, accordingly a load/distance table is present at the operator work area. This must be clear and legible at all times. This item of plant must comply with the relevant parts of AS 1418 at all times. All operators must be appropriately trained to use this item of plant and licenced where necessary.							
References: AS1418.8	i	i					
CRUSHING, INCORRECT OPERATION	HIGH 21	MEDIUM 15					
Risk Treatments in Place: Quick Hitch Information This hydraulic quick hitch has the following information marked upon it -							
1. The manufacturer's name and address 2. Model							
 Serial number The year of manufacture 							
5. The mass of the hitch in kilograms							
6. The lift point capacity (if fitted) in kilograms							
This information must be considered by all operators when assessing the suitability of the hi this information could lead to serious injury or death.	tch for any task. Failure to co	nsider and or comply with					
References: AS13031							
CRUSHING, STRIKING, COLLISION	HIGH 19	MEDIUM 14					
Risk Treatments in Place: Tail Swing Label The rear of this item of plant has a hazard warning label re: general plant movement, tail swi and serviceable at all times.	ing, keep clear. It must be pre	esent and fully functional					
References: ISO20474-							
	MEDIUM 14	MEDIUM 13					
Risk Treatments in Place: Front Grader Blade Label The front blade on this item of plant is fitted with a hazard warning label re: crush zone, keep	o clear. This label must be pre	esent and fully functional					
and serviceable at all times.							
References: AS1319- , ISO20474-	1	1					
ENTANGLEMENT, SHEARING, BURNS	MEDIUM 14	MEDIUM 13					
Risk Treatments in Place: Engine Guard Label							
The engine fan and alternator belts, pulleys and gears are guarded. These guards have clea							
remove guards while engine is running. These labels must be present, legible and easily seen at all times whilst this item of plant is in operation.							
References: AS/NZS4024.1201, AS1319-							
	MEDIUM 12	LOW 6					
Risk Treatments in Place: Warning Device (horn) This item of plant is fitted with a fully functional audible warning device such as a horn. This must be easily accessed by the operator, and easily identifiable by nearby pedestrians.							
All operators should ensure the warning devices are functional at the start of each shift, by c pre-start checklists. Warning devices should operate automatically where appropriate (eg re							
References: ISO7731, ISO9533	References: ISO7731, ISO9533						



YY09047237 AHSH Service 11-Dec-2024

	HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating			
	COLLISION	MEDIUM 9	LOW 5			
	Risk Treatments in Place: Recovery Point Label This item of plant is fitted with a hazard warning label adjacent the recovery tow point which states "Recovery tow point – Read manufacturer's towing instructions before towing". Failure to do so could result in DEATH or SERIOUS INJURY.					
	This label must be clear and legible at all times whilst this item of plant is in operation.					
	References: ISO31000					
	CRUSHING	CRITICAL 24	MEDIUM 15			
	Risk Treatments in Place: Fully Automatic Quick Hitch This item of plant is fitted with a fully automatic quick hitch.					
	References: AS13031					
	CRUSHING	CRITICAL 24	MEDIUM 15			
	Risk Treatments in Place: Automatic(Quick) Hitch This item of plant is fitted with a quick hitch that is fitted with a primary retention device and s	safety system that meet the fo	ollowing requirements -			
	 Must be intentionally disengaged to remove attachments The safety system is automatically activated as part of the engagement process Has means of verifying engagement of both the primary retention device and the safety sy 	stem from the operator posit	ion.			
	These requirements must be met at all times whilst this item of plant is in operation.					
	References: AS13031					
		CRITICAL 24	LOW 1			
Risk Treatments in Place: Closed Eye Lifting Point The lifting point fitted to this item of plant is the closed eye type. Hooks with out latching devices must not be used as a lifting point at any						
	References: AS13031					
	CRUSHING	CRITICAL 24	LOW 1			
	Risk Treatments in Place: Closed Eye Lifting Point With Latch The lifting point fitted to this item of plant is the open hook with latch type. Hooks with out latching devices must not be used as a lifting point at any time.					
	References: AS13031	1	1			
		HIGH 22	MEDIUM 15			
	Risk Treatments in Place: Hydraulic Hoses This item of plant has hydraulic hoses. These hoses must be inspected each day or before each use for wear and tear. If there are visible signs of wear, immediate action must be taken to control the risk arising from this wear. These inspections must be documented. Hydraulic fluid at high pressure can penetrate the skin, never use any part of your body to check for leaks. If oil penetrates the skin seek medical advice immediately. Always use a piece of cardboard or similar to check for suspected leaks. Always wear appropriate gloves when handling					
	hydraulic hoses.					
	Hydraulic pressure can be stored and is a hazard. Always connect and disconnect hydraulic hoses as per the manufacturer's manual.					
	References: AS4024, AS2671					
		HIGH 22	MEDIUM 15			
	Risk Treatments in Place: Loose Items - Operator Work Area All items that could cause harm to the operator in the event of a collision or rollover are securely restrained.					
	References: ISO31000					

DESIGN COMPLIANCE

Ideagen⁷ Plant Assessor



HAZARD(S) Prelim. Risk Rating Residual Risk Rating				
	HIGH 22	MEDIUM 15		
Risk Treatments in Place: Control Lock out The primary operator controls are fitted with an isolation device which meets the following requirements - a) Must be engaged to allow entry & exit of the machine b) Is not easily bypassed.				
This device deactivates the primary operator controls. This must be employed during entry, e plant. This device must be fully functional at all times whilst this item of plant is in operation.	exit and while performing mai	ntenance on this item of		
References: ISO10968				
CRUSHING, ENTANGLEMENT, STRIKING, COLLISION	HIGH 22	MEDIUM 15		
Risk Treatments in Place: Neutral Start This item of plant has neutral start control in place. It must be fully functional and serviceable	e at all times whilst this item o	f plant is in operation.		
References: AS4024.1603	1	1		
CRUSHING	HIGH 22	MEDIUM 15		
Risk Treatments in Place: Seat Belt This item of plant is fitted with an operator seat belt. This seat belt must be free from damage whilst this item of plant is in operation. Operators must use this seat belt at all times during operators		ily attached at all times		
References: ISO6683	ĺ	İ		
ICANT SEE YOU	HIGH 22	MEDIUM 15		
Risk Treatments in Place: Operator Mirrors The operator rear view mirrors fitted to this item of plant must be fully functional and kept clear on each side to provide rear vision to the operator to avoid striking bystanders and objects.	an at all times. There must al	ways be at least one mirror		
References: AS/NZS4024.1201, ISO14401.1	1	ì		
CRUSHING	HIGH 22	MEDIUM 15		
Risk Treatments in Place: Movement Awareness Alarm An automatic movement awareness alarm is fitted to this item of plant. This alarm is automatic must be fully functional and serviceable at all times whilst this item of plant is in operation.	tically activated when travel in	n any direction occurs. It		
References: ISO7731, ISO9533	1	1		
	HIGH 22	MEDIUM 15		
Risk Treatments in Place: Quick Hitch Controls The quick hitch operation control is fitted with a device/method to prevent accidental operation. This device must be fully functional at all times whilst this item of plant is in operation.				
References: AS13031				
	HIGH 22	MEDIUM 15		
Risk Treatments in Place: Hydraulic Hose Failure Shield This item of plant is fitted with a sturdy, permanent shield(s) between the hydraulic hoses and any body parts of the operator to provide protection during a hose or component failure. This shield(s) must be present and fully functional at all times whilst this item of plant is in operation.				
References: AS4024, ISO4413, AS2671				
	HIGH 22	MEDIUM 15		
Risk Treatments in Place: Quick Hitch Operation Alarm This item of plant is fitted with a quick hitch with a fully functional audible alarm fitted to the operator work area to alert the operator that the host machine is in the mode that allows for the controls to be operated to engage or disengage attachments. This alarm must be fully functional at all times whilst this item of plant is in operation.				
References: AS13031				



AHSH Service

11-Dec-2024

Page 10 of 16

POOR VISIBILITY, COLLISION HIGH 22 MEDIUM 15 Risk Treatments in Place: Machine Lights This item of plant is fitted with self contained lighting. All of these lights must be fully functional and serviceable whilst this item of plant is in operation in areas of reduced light. If any of these lights stop working the operation must cease immediately and the faulty light be repaired before operation can continue in the areas of reduced light. References: ISO20474-				
This item of plant is fitted with self contained lighting. All of these lights must be fully functional and serviceable whilst this item of plant is in operation in areas of reduced light. If any of these lights stop working the operation must cease immediately and the faulty light be repaired before operation can continue in the areas of reduced light.				
STRIKING HIGH 22 MEDIUM 15				
Risk Treatments in Place: Forestry OPS This item of plant is fitted with an Operator Protective Structure (OPS = Devices intended to provide reasonable protection from penetrating object to the front, side and top of the operator station e.g heavy duty mesh). This guard must be present and fully functional at all times whilst his item of plant is in operation. If the OPS is damaged all forestry operations muccease until the guard is either repaired or certified safe for use by a competent person. References: AS2294, ISO3449, ISO3471				
ENTANGLEMENT HIGH 22 MEDIUM 15				
Risk Treatments in Place: Engine Guards The engine fan and alternator belts, pulleys and gears are guarded. These guards must be present and fully functional and serviceable at all times whilst this item of plant is in operation. References: AS/NZS4024.1601				
INSTABILITY, CRUSHING, TIP OVER HIGH 22 MEDIUM 15				
Risk Treatments in Place: Levelness Device This item of plant is fitted with a level indicator. This device indicates the "levelness" of the machine chassis. During operation operators must ensure the machine is within the manufacturers guidelines for levelness. The rated capacity chart fitted for lifting operations has a maximum level angle which must never be exceeded during lifting operations. This level indicator must be present and fully functional at all times whilst this item of plant is in operation. References: AS1418.8				
Nerences. AS 1410.0				
FALLING HIGH 22 MEDIUM 15				
Risk Treatments in Place: Handrails All operator work platforms are either - a) above 0.5m and below 2.0m from the ground or nearest platform and have three points of contact which can be constantly maintained by any person on the platform performing expected tasks or b) are above 2.0m from the ground or nearest platform and have an approved guardrail which meets the following requirements: 1. All guardrails are at least 1.1m high 2. All guardrails have a mid rail 3. All sides and ends have a kick plate which is at least 100mm high.				
These work platforms and/or access points must have guardrails present that are fully functional and serviceable at all times whilst this item of plant is in operation.				
References: AS5327				
COLLISION HIGH 22 MEDIUM 15				
Risk Treatments in Place: Beacon This item of plant is fitted with a safety beacon. This beacon must meet the following criteria at all times whilst this item of plant fitted is in operation -				
 - Is visible up to 200m in all directions (allowing for intermittent obstruction from the plant structure whilst the plant is in operation) - Is fitted in the most appropriate location on machine to maximise visibility without risking continual damage NOTE: more than one beacon may be fitted to meet these criteria. 				
References: ISO20474-				





AHSH Service

11-Dec-2024

HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating			
	HIGH 22	LOW 2			
Risk Treatments in Place: Plant Modification					
The plant is in original condition. References: ISO31000					
References. ISOS 1000					
	HIGH 21	MEDIUM 15			
Risk Treatments in Place: Two Operator Exits					
The operator cabin/work area on this item of plant has a minimum of two (2) possible exits.	These must be functional and	accessible at all times			
whenever the item of plant is manned, whether during operation or maintenance activities.					
References: AS5327					
	HIGH 21	MEDIUM 15			
Risk Treatments in Place: Emergency Exits					
The emergency exits for this item of plant meet the following requirements -					
1. Clearly and legibly labelled					
2. Instructions for use are clear and legible and located adjacent the exit					
3. Any required tools required for use are available e.g. Emergency hammers					
These exits must be legibly labelled and fully functional at all times whenever the item of pla	ant is manned. whether during	operation or maintenance			
activities.					
References: ISO31000					
POOR VISIBILITY, COLLISION	HIGH 21	MEDIUM 15			
Risk Treatments in Place: Windscreen Wipers					
The windscreen wipers and washers fitted to this item of plant must be fully functional at all	times.				
References: AS/NZS4024.1201					
ROPS FITTED CRUSHING	HIGH 21	MEDIUM 15			
Risk Treatments in Place: ROPS					
A Roll Over Protective Structure (ROPS) to ISO 3471, ISO 12117.1 or 2, AS 2294 or AS 49					
this standard must be attached to the structure at all times. This structure provides a safety					
seat belts at all times whilst this item of plant is in operation and accordingly seat belts must	be worn at all times during op	beration.			
References: AS2294, ISO3471					
	HIGH 21	LOW 5			
Risk Treatments in Place: FOPS Level II					
This item of plant is fitted with a level II Falling Objects Protective Structure (FOPS). This structure is designed to protect the operator from heavy					
falling objects (e.g. trees, rocks). Care should still be exercised when operating in an area with a risk of falling objects.					
References: AS2294, ISO3449, ISO10262					
CRUSHING	HIGH 21	MEDIUM 15			
Risk Treatments in Place: 1T Controlled Lowering Device					
This item of plant is fitted with a controlled lowering device which is activated in the event of hydraulic failure. If this device is not fully functional then					
lifting of freely suspended loads in excess of 1T must not occur until this controlled lowering device is repaired. The requirements of AS 1418.8 must					
also be met prior to lifting freely suspended loads in excess of 1T.					
Freely suspended loads regardless of weight must never be lifted over any personnel.					
References: ISO8643, AS1418.8					





	HAZARD(S) Prelim. Risk Rating Residual Risk Rating				
¢.	INCORRECT OPERATION	HIGH 20	MEDIUM 14		
Risk Treatm	ents in Place: Intuitive Controls				
The controls fi	itted to this item of plant are orientated so that the movement of the control is o	consistent with the action of th	e machine e.g. moving a		
control lever to	o the left results in the machine turning to the left. This design feature must be	maintained at all times whilst	this item of plant is in		
operation.					
References:	: AS/NZS4024.1906				
	STRAINS	HIGH 19	LOW 5		
Risk Treatm	ents in Place: Controls Ergonomics				
All controls inc	cluding all levers, buttons, pedals, switches etc, are placed near the operator w	ork position and are easy to	reach and operate during		
the execution	of the operator's normal duties. This applies for all persons within the 95th per	centile of the normal population	on distribution.		
References:	: AS/NZS4024.1901				
0 -					
	INCORRECT OPERATION, SLIPPING	HIGH 17	LOW 6		
프 ()					
Risk Treatm	ents in Place: Control Levers/Pedals/Buttons				
All controls ind	cluding all levers, buttons, pedals, switches etc. must be kept non-slip and free	from damage at all times.			
References:	: AS/NZS4024.1901				
. P					
h	SLIPPING	MEDIUM 12	LOW 6		
O ~					
Risk Treatm	ents in Place: Operator Work Area Access/Egress				
Safe access a	and egress to the cabin/work area(s) must be maintained at all times whilst this	item of plant is in operation.	It must be non slip, free		
from damage,	located at a height so as to not cause undue body stresses and strains with the	nree points of contact availabl	e to personnel at all times.		
All personnel					
	e the item of plant during access and egress.				
	Intain three points of contact during access and egress.				
4. Never jump	an object(s) in his/her hand(s) during access and egress.				
References:					
TREFERENCES.					
×	FALLING, SLIPPING	MEDIUM 12	LOW 6		
Risk Treatm	ents in Place: Access/Egress Instruction Label				
An instruction	label is fitted adjacent access/egress areas to advise all personnel of the follow	wing -			
1. Always face	e the item of plant during access and egress.				
2. Always mai	ntain three points of contact during access and egress.				
3. Ensure the	steps are clean.				
4. Never jump	off machine.				
This label mus	st be clear and legible at all times whilst this item of plant is in operation.				
References:	: ISO31000				
, P					
み	FALLING, SLIPPING, TRIPPING	MEDIUM 12	LOW 6		
۲ × ۲ × ۲ × ۲ × ۲ × ۲ × ۲ × ۲ × ۲ × ۲ ×					
Risk Treatments in Place: Engine Bay Access					
	and egress to the engine bay/work area(s) must be maintained at all times while				
free from damage, located at a height so as to not cause undue body stresses and strains with three points of contact available to personnel at all					
times.					
All personnel					
	1. Always face the item of plant during access and egress.				
2. Always maintain three points of contact during access and egress.					
3. Never carry an object(s) in his/her hand(s) during access and egress.					
4. Never jump off machine.					
References: AS5327					



YY09047237 AHSH Service 11-Dec-2024

		HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating			
	BATTERY COVER	ELECTRIC SHOCK, BURNS	MEDIUM 12	LOW 6			
	All batteries f The constrain	Risk Treatments in Place: Battery Cover All batteries fitted to this item of plant are constrained to prevent displacement & fitted with a permanent sturdy cover which allows for ventilation. The constraint and cover must be present and fully functional and serviceable at all times whilst this item of plant is in operation.					
	References	References: AS/NZS4024.1201					
	*	INCORRECT OPERATION, SLIPPING	MEDIUM 9	LOW 4			
		Risk Treatments in Place: Work Area Floors All work area floors are non-slip and free from damage & debris.					
	Floor area m use.	Floor area must remain non-slip and free from damage & debris, including rubbish, tools and other items, at all times whilst this item of plant is in use.					
	References	: AS/NZS4024.1201, ISO20474-					
	G t	NON COMPLIANCE, STRAINS	MEDIUM 9	LOW 1			
	The operator	Risk Treatments in Place: Operator Seat The operator seat fitted to this item of plant must remain free from damage and tears, and be permanently and securely fitted at all times. References: AS/NZS4024.1401, ISO20474-					
	\square	HEAT STROKE, DEHYDRATION	MEDIUM 9	LOW 4			
	This item of p	nents in Place: Air Conditioning blant is fitted with an air conditioned cabin. This air conditioned cabin helps cont s shade from the sun. The air conditioner must be fully functional and serviceab s: ISO31000	. , .				
	~	BURNS	MEDIUM 9	LOW 5			
	Risk Treatments in Place: Exhaust The engine exhaust on this item of plant is fitted with a guard to prevent injury to any person and control the risk of initiating a fire. It n and fully functional and serviceable at all times whilst this item of plant is in operation.						
	References	References: AS/NZS4024.1201					
	*	CURRENT OR PREVIOUS STRUCTURAL DAMAGE	CRITICAL 25	MEDIUM 15			
	Risk Treatments in Place: Structural Integrity Regular checks for structural damage must be undertaken. Look for cracks in frames/chassis (current or repaired), bends or damage to structural components, etc. References: ISO31000						
			HIGH 22	MEDIUM 15			
_	The manufac	nents in Place: Maintenance Manual cturer's maintenance manual(s) has been supplied for this item of plant					
		al(s) must be available at all times to all users and maintenance staff of this iten ith these handbook(s) prior to maintaining or repairing this item of plant.	n of plant. All users and maint	tenance staff must read and			
	A complete r of plant prior	isk assessment/JSEA must be undertaken covering all inspection, maintenance to use.	, servicing and transportation	requirements of this piece			
	A full assessment of the competence of people using the book(s) must also be undertaken References: Work Health & Safety Act & Regulations-, Occupational Health & Safety Act & Regulations						





AHSH Service

11-Dec-2024

	HAZARD(S)	Prelim. Risk Rating	Residual Risk Ra
Ţ	STRIKING, BURNS	HIGH 22	MEDIUM 15
The hydrau that hoses and protec	tments in Place: Hydraulic Damage lic hoses to this item of plant are free from damage and protected against dama are free from damage and that protection is in place at all times whilst this item tion system should be conducted regularly and documented as part of your plan	of plant is in operation. Inspec	
Reference	es: AS4024, ISO4413, AS2671		
	CRUSHING	HIGH 22	MEDIUM 15
	tments in Place: ROPS Damage ver Protective Structure (ROPS) fitted to this item of plant must remain free from	n damage at all times whilst this	s item of plant is in
Reference	es: AS2294, ISO3471		
Ţ	OPERATIONAL MALFUNCTION	HIGH 22	LOW 2
Risk Treatments in Place: Major Fluid Leaks This item of plant must remain free from leaks at all times whilst in operation (this includes engine, transmission, cooling system, air, fuel, driv wheel hubs, steering and hydraulics). Development of a major leak will require this item of plant to be stood-down until repaired. Minor leaks detected must be repaired within 1-14 days.			
Reference	es: ISO31000		
	OPERATIONAL MALFUNCTION	HIGH 21	MEDIUM 15
Service and	tments in Place: Service Records d maintenance records are available for this item of plant.		
includes the	ords must continue to be managed and available at all times as part of your service of undertaking of regular inspections of the item of plant with specific reference to a maintenance requirements).		· · •
Reference	es: Work Health & Safety Act & Regulations- , Occupational Health & Safety Ac	t & Regulations	
*	POOR VISIBILITY, COLLISION	HIGH 21	MEDIUM 15
Risk Trea	tments in Place: Windows & Screens		
Ensure the	cabin/work area safety glass windows and screens are kept clean and free from use.	n cracks and other damage at	all times whilst this iter
plant is in u			
plant is in u	es: AS/NZS4024.1201, ISO20474-		
plant is in u	es: AS/NZS4024.1201, ISO20474-	MEDIUM 9	LOW 4
plant is in u Reference		MEDIUM 9	LOW 4
Plant is in u Reference Risk Trea	INSTABILITY tments in Place: Tracks and track components must be inspected as part of a "pre start" checklist. Thes		

IMAGES

- No Images Available -

NOTES



- No Notes Available -





Ideagen? RISK MANAGEMENT REPORT Plant Assessor

TYPE	Excavator - Medium (10 - 19.9 Tonne)	Report Number	AHH 20241211-1106
MAKE	Kobelco	Date	11-Dec-2024
MODEL	SK135SR-7	Created By	AHSH Service
CHASSIS / VIN	YY09047237	Assessor	AHSH Service
PLANT NUMBER	AHSH123	Assist. Assessor(s)	
		Owner	Australian Hammer Supplies Hire Pty Ltd
		Owner Assessment Purpose	Pty Ltd

OPERATOR ACKNOWLEDGEMENT

I the undersigned acknowledge that I have read and understand the risk management report described above. I also acknowledge that I have received a copy of this risk management report.

DATE	NAME	COMPANY/POSITION	SIGNATURE



Wednesday, 11 Dec 2024 11:08 AM



Chassis / VIN Assessed By Date

YY09047237 AHSH Service 11-Dec-2024