Ideagen RISK MANAGEMENT REPORT

ТҮРЕ	Excavator - Small (0 - 9.9 Tonne)
MAKE	Kubota
MODEL	U17-3HG
SERIAL NUMBER	54890
PLANT NUMBER	AHSH139
Report Number	AHH 20250603-0742
Date	03-Jun-2025
Created By	AHSH Service
Assessor	Mitchell Pennells
Assist. Assessor(s)	Mitchell Pennells
Completed By	AHSH Service
Owner	Australian Hammer Supplies Hire Pty Ltd
Assessment Purpose	Hire
State	NSW





TABLE OF CONTENTS

SECTION 1	IMPORTANT INFORMATION Contains information outlining the scope and any limitations applicable to this Risk Management Report
SECTION 2	MACHINE DETAILS Contains standard machine specifications and details of any extras fitted
SECTION 3	RISK ANALYSIS, RISK EVALUATION & RISK TREATMENT Contains details of the technique used to calculate risk ratings, time frame and risk treatments. Please refer to this information when reviewing and interpreting the information in section 4 & 5
SECTION 4	RISK TREATMENTS REQUIRED Contains detailed information regarding the risk treatments to be implemented including hazard, risk rating, time frame, relevant standards & legislative references
SECTION 5	RISK TREATMENTS IN PLACE Contains detailed information regarding the risk treatments in place including hazard, risk rating, relevant standards & legislative references
SECTION 6	IMAGES AND NOTES Contains images & any relevant information entered by the assessor



Serial Number Assessed By Date

SECTION 1 IMPORTANT INFORMATION

This report generated by Plant Assessor™ © Online Safety Systems on Tuesday, 3 Jun 2025 7:45 AM

This report pertains to this item of plant as it appeared on the day of inspection.

It is the responsibility of the hirer to conform with the instructions and information contained within this report. Any change in condition of this item of plant should be reported to the hire company immediately.

Any information relating to the standard features have been supplied via the manufacturer and should be used as a guide only until verified.

For further information regarding this report contact Online Safety Systems on 1300 72 88 52

SECTION 2 MACHINE DETAILS

ഗ		1. Manufacturers specified noise level dBA	78 dBA
Ľ.		2. Ambient noise level dBA	
MACHINE DETAILS		3. Noise level - Operator position (high idle) dBA	81
	- NOISE TEST RESULTS	4. Noise level - Operator position (low idle) dBA	65
8 1		5. Noise level LHS dBA @ m (high idle)	
		6. Noise level Front dBA @ m (high idle)	
<u>ا ج</u>		7. Noise level RHS dBA @ m (high idle)	
≣L		8. Noise level Rear dBA @ m (high idle)	
- ㅎ	BUCKET	Standard bucket capacity, SAE rated (m3)	
Ă	BOOKET	Standard bucket width (mm)	
ΞI	CAPACITIES	Fuel Tank Capacity (Litres)	19
_ [SAI AOITIES	Hydraulic Oil Tank Capacity (Litres)	20.4
		Dig depth to cut 2.44 m level bottom (mm)	1910
		Digging depth (mm)	2310
		Dump height (mm)	2440
		Ground clearance (mm)	150
		Max depth of vertical wall (mm)	1910
	DIMENSIONS/WEIGHTS	Maximum Reach Height (mm)	
		Operating weight (kg)	1680
		Tailswing radius (mm)	
		Transport Height (mm)	2340
		Transport Length (mm)	2950
		Width (mm)	990-1240
	ENGINE	Engine Displacement (Litres)	0.898
		Engine Hours	
		Engine Make & Model	Kubota
		Engine Number	
		Engine Power (kW@rpm)	12kW@2300rpm
		Number of Cylinders	3
	EXTRAS	Spare spool for attachments? Yes/No	
		Quick Hitch Make	
	НІТСН	Quick Hitch Model	
		Quick Hitch Serial No.	
		Flow of main pumps (L/Min)	45L/Min
	HYDRAULICS	Pump Types	2 x Variable Displacement, 1 x Gear Pump
		Relief valve pressure, main pumps (Bar)	215
	PLANT CLASSIFICATIONS	Class	
	PLANT CLASSIFICATIONS	Year	
		FOPS Compliance No.	
		FOPS Serial No.	
	SAFETY STRUCTURES	ROPS Compliance No.	
		ROPS Serial No.	
	TDAOKO	Track length on ground (mm)	1585
	TRACKS	Track pad width (mm)	230
	TRANSMISSION	Speed (km/h)	2.1 / 4.1
	WORK CAPABILITIES	Arm breakout (kgf)	870
	WORK CAPADILITIES	Bucket breakout (kgf)	1550





Gradeability - Degrees/(%)	20
Reach @ ground level (mm)	3840





Serial Number Assessed By Date

SECTION 3 RISK ANALYSIS / RISK EVALUATION

RI	RISK ANALYSIS						
			CONS	EQUENCE			
		1. INSIGNIFICANT Dealt with by in house first aid	2. MINOR Treated by medical professionals, hospital out patients	3. MODERATE Significant non permanent injury overnight hospital stay	4. MAJOR Extensive permanent injury eg. Loss of fingers, extended hospital stay	5. CATASTROPHIC Death, permanent disabling injury eg. Loss of hand, quadriplegia	
	A. Almost certain to occur in most circumstances	MEDIUM 8	HIGH 16	HIGH 18	CRITICAL 23	CRITICAL 25	
Ļ	B. Likely to occur frequently	MEDIUM 7	MEDIUM 10	HIGH 17	HIGH 20	CRITICAL 24	
	C. Possibly and likely to occur at sometime	LOW 3	MEDIUM 9	MEDIUM 12	HIGH 19	HIGH 22	
	D. Unlikely to occur but could happen	LOW 2	LOW 5	MEDIUM 11	MEDIUM 14	HIGH 21	
	E. May occur but only in rare circumstances	LOW 1	LOW 4	LOW 6	MEDIUM 13	MEDIUM 15	

NUTION	CRITICAL	Act immediately to mitigate risk. Implement risk treatment(s) in accordance with the risk treatment table below.
RISK EVA	HIGH	Act immediately to mitigate risk. Implement risk treatment(s) in accordance with the risk treatment table below. If the appropriate risk treatments are not immediately accessible establish interim risk treatment strategies. Permanent risk treatments must be implemented within one week.
	MEDIUM	Take reasonable steps to mitigate and monitor the risk. Implement risk treatment(s) in accordance with the risk treatment table below. Permanent risk treatments must be implemented within one month.
	LOW	Take reasonable steps to mitigate and monitor the risk. Implement risk treatment(s) in accordance with the risk treatments must be implemented within three months.

ATME

TREATMENT		st appropriate risk treatment option involves balancing the costs and efforts of implementation against the benefits ard to legal, regulatory and other requirements. (source AS/NZS ISO 31000:2018)	
REAT	Eliminate	Eliminate the risk source.	
RISK T	Substitute	Provide an alternative that is capable of performing the same task which is safer.	
Isolate Isolate people from the hazard.			
	Engineering	Provide or construct a physical barrier or guard.	
Administration Develop policies, Provide training,		Develop policies, procedures, practices and guidelines in consultation with employees to mitigate the risk. Provide training, instruction and supervision about the risk source.	
	Personal protective	Provide personal protective equipment to protect the individual from the risk source.	



 Make
 Kubota

 Model
 U17-3HG

 Type
 Excavator - Small (0 - 9.9 Tonne)

Serial Number Assessed By Date

SECTION 4 RISK TREATMENTS REQUIRED

This section of the report pertains to hazards created by use of this item of plant which currently do not have risk treatments in place. The risk treatments recommended in this section have been developed based on relevant Australian Standards, health & safety legislation, the hierarchy of risk treatment in accordance with the guidelines set forth in AS/NZS ISO 31000 – Risk Management and various other sources. The recommended risk treatment measures must be developed, implemented and validated as effective prior to the operation, maintenance or testing of this item of plant. Treatments applied must be dated and initialled adjacent the recommendations. All operators must read and understand the entire contents of this section prior to operating this item of plant.

	HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating	Time Frame	Due Date	Date Rectified	Initial
OPERATION	NOMINATED OPERATOR ONLY	CRITICAL 24	MEDIUM 15	Immediate	3-Jun-25		
	Risk Treatment Required: Operator Competency Only persons who are qualified, trained and experienced and/or hold the relevant certification/license can operate this item of plant. If there is not a competent/licensed person available for operation of this item of plant then only persons who are supervised by a competent/licensed person can operate this item of plant.						
Č	Legislation: State Health & Safety Legislation & R	egulation					
	Legislation: State Health & Safety Legislation & R References: Work Health & Safety Act & Regula	0	Health & Safety Act	& Regulations			

SECTION 5 RISK TREATMENTS IN PLACE

This section of the report pertains to risk treatments currently in place on this item of plant. This section must be read in conjunction with the safety section of the manufacturers handbook. All operators must read and understand the entire contents of this section prior to operating this item of plant. These treatments or equivalent must remain in place at all times whilst this item of plant is in operation.

	HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating				
DELIVERY	CRUSHING	HIGH 22	MEDIUM 15				
≥	Risk Treatments in Place: SWMS Loading/Unloading						
	Ensure that all operators follow approved SWMS/SOP when loading and unloading this machine to and from a flat top truck or trailer, low loader or tilt tray.						
	References: Work Health & Safety Act & Regulations- , Occupational Health & Safety Act & Regulations						
	CRUSHING	HIGH 22	MEDIUM 15				
	Risk Treatments in Place: SWMS Load Restraint						
	Ensure that all operators follow the approved SWMS/SOP when restraining this machine for	r transport.					
	References: Work Health & Safety Act & Regulations- , Occupational Health & Safety Act	& Regulations					
NOI	INCORRECT OPERATION	HIGH 22	MEDIUM 15				
PERATION	Risk Treatments in Place: Operation Handbook The manufacturer's operation handbook has been supplied for this item of plant.						
Ö	This handbook must be available at all times to all potential operators and supervisory staff this handbook prior to operating.	All potential operators must r	ead and be familiar with				
	A complete risk assessment/Job Safety Analysis must be undertaken covering all operating	processes and environments	associated with this item of				
	plant. SWMS should be produced for specific tasks associated with use of this item of plant						
	References: Work Health & Safety Act & Regulations- , Occupational Health & Safety Act	& Regulations					
	INCORRECT OPERATION	HIGH 22	MEDIUM 15				
	Risk Treatments in Place: Pre-op Checklist Excavator A pre-operation checklist is available for this Excavator. This checklist must be completed b	y all operators prior to operati	ng this Excavator.				
	References: Work Health & Safety Act & Regulations- , Occupational Health & Safety Act	& Regulations					



 Make
 Kubota

 Model
 U17-3HG

 Type
 Excavator - Small (0 - 9.9 Tonne)

Serial Number Assessed By Date

HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating				
	HIGH 22	MEDIUM 15				
Risk Treatments in Place: SOP Excavator Safe Operation Procedures are available for this Excavator. The information in the Safe Operation Procedures must be followed at all times whilst operating this Excavator.						
References: Work Health & Safety Act & Regulations- , Occupational Health & Safety Act	& Regulations					
HIGH 22 MEDIUM 15						
Risk Treatments in Place: Control Labels All controls including all levers, buttons, pedals, switches etc. are clearly labelled as to their p maintained in a clean and serviceable condition at all times.	purpose and method of opera	tion. These labels must be				
References: AS/NZS4024.1905						
	HIGH 22	MEDIUM 15				
Risk Treatments in Place: Passenger Seat Label This item of plant is fitted with a clear hazard warning label re: Operator only, No passengers must be clear and legible at all times whilst this item of plant is in operation. Legislation: State Health & Safety Legislation & Regulation	s. Passengers must not be ca	rried at anytime. This label				
References: AS1319-						
CRUSHING	HIGH 22	MEDIUM 15				
Risk Treatments in Place: ROPS Label The warning label stating that the ROPS must not be damaged at any time (including cuts, d at all times.	Irill holes and welds) must be	present, clean and legible				
References: ISO3471	r	r				
	HIGH 22	MEDIUM 15				
Risk Treatments in Place: ROPS seat belt label This item of plant is fitted with a ROPS and has an advisory label stating that "seatbelts must This label must be present, clean and legible at all times. All operators and passengers must wear seatbelts whilst on this item of plant.	t be worn".					
References: AS2294, ISO3471						
	HIGH 22	MEDIUM 15				
Risk Treatments in Place: Electrical Approach Distances This item of plant has a hazard warning label re: overhead electrical hazards and minimum a adhered to strictly. These labels and tables must be present, clear and legible at all times.	approach distances fitted. The	ese distances must be				
Spotters are required when working within 5 metres of the minimum approach distance of an	ny live electrical apparatus.					
Any encroach within the minimum approach distances must only occur if the following provisions have been met - 1. The machine is designed to work within the minimum approach distances 2. Permission has been granted by the electricity company and 3. Safe systems of work have been documented and approved.						
References: ISO31000						
	HIGH 22	MEDIUM 15				
Risk Treatments in Place: Before You Dig (AUS) This item of plant is fitted with a clear hazard warning label re: underground services and advice "Before You Dig, visit www.byda.com.au" to the operator work area. This advice must be adhered to strictly. Digging into an electricity cable or gas pipe can cause serious injury or death. Damaging a pipe or cable may also lead to isolating a community from emergency services such as fire, police or ambulance. This label must be present, clear and legible at all times. References: ISO31000						



HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating			
COLLISION	HIGH 22	MEDIUM 15			
Risk Treatments in Place: Phone Use label This item of plant is fitted with an instruction label advising that mobile phones must not be used whilst operating this machine. Accordingly all operators must not use a mobile phone at any time whilst operating machine. If phone use is necessary then operator must place machine in park configuration in a safe position prior to phone use. Operators MUST adhere to this advice at all times.					
This label must be clear and legible at all times whilst this item of plant is in operation. References: AS1319-, ISO31000					
POISONING, EXPLOSION, BURNS	HIGH 22	MEDIUM 15			
Risk Treatments in Place: Tank ID Label The tank(s) on this item of plant have clear, legible label(s) identifying their contents, and if a These must be present, clear and legible at all times. (this includes radiator, hydraulic, wate References: Work Health & Safety Act & Regulations-, Occupational Health & Safety Act	r and petrol/diesel tanks etc.)	ntrols re: the contents.			
FIRE FIRE	HIGH 21	MEDIUM 15			
Risk Treatments in Place: Fire Extinguisher This item of plant is fitted with an approved and maintained fire extinguisher. Fire extinguish They must be readily accessible to the operator. Regular inspections must also be carried o and AS 1851 – 1995 References: AS10896.1, AS1851					
INSTABILITY, CRUSHING	HIGH 21	MEDIUM 15			
Risk Treatments in Place: Boom Rated Capacity Label This item of plant has a rated capacity label fitted to each side of the boom. Ensure that these of plant is in operation. Operators must not exceed this rated capacity at any time during op		at all times whilst this item			
References: AS1418.8	1	1			
INSTABILITY, CRUSHING	HIGH 21	MEDIUM 15			
Risk Treatments in Place: Boom Lifting Point Table This item of plant has a lifting point fitted to the boom, accordingly a load/distance table is plegible at all times. This item of plant must comply with the relevant parts of AS 1418 at all this item of plant and licenced where necessary.	-				
References: AS1418.8					
	HIGH 21	MEDIUM 15			
Risk Treatments in Place: Swing Boom Crush Label This item of plant has clear hazard warning labels re: pinch point/crush zone, keep clear, that point. These must be present, clear and legible at all times whilst this item of plant is in oper Performance (ACM/25004 4004 4004		f the boom swing/pivot			
References: AS/NZS4024.1201, AS1319-					
HEARING LOSS	HIGH 19	MEDIUM 14			
Risk Treatments in Place: Hearing Protection Label - Operator The hazard warning label(s) re: wearing of hearing protection attached to this item of plant r damage will result if hearing protection is not worn. These labels must be present, clear and References: AS3781-, AS/NZS1269		Ũ			
CRUSHING, STRIKING, COLLISION	HIGH 19	MEDIUM 14			
Risk Treatments in Place: Tail Swing Label The rear of this item of plant has a hazard warning label re: general plant movement, tail swing, keep clear. It must be present and fully functional and serviceable at all times. References: ISO20474-					



	HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating			
	CRUSHING	MEDIUM 14	MEDIUM 13			
	Risk Treatments in Place: Front Grader Blade Label					
	The front blade on this item of plant is fitted with a hazard warning label re: crush zone, keep clear. This label must be present and fully func-					
	and serviceable at all times.					
	References: AS1319- , ISO20474-					
	ENTANGLEMENT, SHEARING, BURNS MEDIUM 14 MEDIUM 13					
	Risk Treatments in Place: Engine Guard Label The engine fan and alternator belts, pulleys and gears are guarded. These guards have cle	ar legible bazard warning labe	ls re do not open or			
	remove guards while engine is running. These labels must be present, legible and easily se					
	References: AS/NZS4024.1201, AS1319-					
	CRUSHING, COLLISION	MEDIUM 12	LOW 6			
	Risk Treatments in Place: Warning Device (horn) This item of plant is fitted with a fully functional audible warning device such as a horn. This identifiable by nearby pedestrians.	must be easily accessed by th	ne operator, and easily			
	All operators should ensure the warning devices are functional at the start of each shift, by pre-start checklists. Warning devices should operate automatically where appropriate (eg meters) ISO7731, ISO9533					
	References. 130/731, 1309333					
	BURNS	MEDIUM 12	MEDIUM 12			
	Dust, exhaust fumes, chemical fumes, sunstroke and sunburn pose serious risk to the oper for all of these hazards must always be available whilst this item of plant is in operation. If t not available then operation of this item of plant must cease until these are made available References: ISO31000	nese controls e.g. hats, sunscr				
NCE	CRUSHING	CRITICAL 24	LOW 1			
MPLIANCE	Risk Treatments in Place: Closed Eye Lifting Point The lifting point fitted to this item of plant is the closed eye type. Hooks with out latching de References: AS13031	vices must not be used as a lif	ting point at any time.			
רכ גר	CRUSHING	CRITICAL 24	LOW 1			
NENGN	Risk Treatments in Place: Closed Eye Lifting Point With Latch The lifting point fitted to this item of plant is the open hook with latch type. Hooks with out latime.	tching devices must not be us	ed as a lifting point at any			
	References: AS13031	1				
		HIGH 22	MEDIUM 15			
	Risk Treatments in Place: Hydraulic Hoses This item of plant has hydraulic hoses. These hoses must be inspected each day or before each use for wear and tear. If there are visible signs of wear, immediate action must be taken to control the risk arising from this wear. These inspections must be documented.					
	Hydraulic fluid at high pressure can penetrate the skin, never use any part of your body to check for leaks. If oil penetrates the skin seek medical advice immediately. Always use a piece of cardboard or similar to check for suspected leaks. Always wear appropriate gloves when handling hydraulic hoses.					
	Hydraulic pressure can be stored and is a hazard. Always connect and disconnect hydraulic hoses as per the manufacturer's manual.					
	References: AS4024, AS2671					





HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating	
	HIGH 22	MEDIUM 15	
Risk Treatments in Place: Loose Items - Operator Work Area All items that could cause harm to the operator in the event of a collision or rollover are secu	rely restrained.		
References: ISO31000			
	HIGH 22	MEDIUM 15	
Risk Treatments in Place: Control Lock out The primary operator controls are fitted with an isolation device which meets the following re a) Must be engaged to allow entry & exit of the machine b) Is not easily bypassed.	quirements -		
This device deactivates the primary operator controls. This must be employed during entry, e plant. This device must be fully functional at all times whilst this item of plant is in operation.	exit and while performing mai	ntenance on this item of	
References: ISO10968			
CRUSHING, ENTANGLEMENT, STRIKING, COLLISION	HIGH 22	MEDIUM 15	
Risk Treatments in Place: Neutral Start This item of plant has neutral start control in place. It must be fully functional and serviceable References: AS4024.1603	e at all times whilst this item o	f plant is in operation.	
	HIGH 22	MEDIUM 15	
Risk Treatments in Place: Seat Belt This item of plant is fitted with an operator seat belt. This seat belt must be free from damage, and permanently and sturdily attached at all times whilst this item of plant is in operation. Operators must use this seat belt at all times during operation.			
References: ISO6683	1		
CRUSHING	HIGH 22	MEDIUM 15	
Risk Treatments in Place: Movement Awareness Alarm An automatic movement awareness alarm is fitted to this item of plant. This alarm is automatically activated when travel in any direction occurs. It must be fully functional and serviceable at all times whilst this item of plant is in operation.			
References: ISO7731, ISO9533		-	
	HIGH 22	MEDIUM 15	
Risk Treatments in Place: Hydraulic Hose Failure Shield This item of plant is fitted with a sturdy, permanent shield(s) between the hydraulic hoses and any body parts of the operator to provide protection during a hose or component failure. This shield(s) must be present and fully functional at all times whilst this item of plant is in operation.			
CRUSHING, ENTANGLEMENT, SHEARING, BURNS, PINCHING	HIGH 22	MEDIUM 15	
Risk Treatments in Place: Safe Operator Location This machine is designed so that the operator is isolated from all danger zones whilst at the operator position. This condition must exist at all times whilst this item of plant is in operation.			
References: AS/NZS4024.1201			
POOR VISIBILITY, COLLISION	HIGH 22	MEDIUM 15	
Risk Treatments in Place: Machine Lights This item of plant is fitted with self contained lighting. All of these lights must be fully functional and serviceable whilst this item of plant is in operation in areas of reduced light. If any of these lights stop working the operation must cease immediately and the faulty light be repaired before operation can continue in the areas of reduced light. References: ISO20474-			



HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating		
ENTANGLEMENT	HIGH 22	MEDIUM 15		
Risk Treatments in Place: Engine Guards The engine fan and alternator belts, pulleys and gears are guarded. These guards must be present and fully functional and serviceable at all times whilst this item of plant is in operation.				
References: AS/NZS4024.1601				
INSTABILITY, CRUSHING, TIP OVER	HIGH 22	MEDIUM 15		
Risk Treatments in Place: Levelness Device This item of plant is fitted with a level indicator. This device indicates the "levelness" of the m During operation operators must ensure the machine is within the manufacturers guidelines The rated capacity chart fitted for lifting operations has a maximum level angle which must m This level indicator must be present and fully functional at all times whilst this item of plant is References: AS1418.8	for levelness. never be exceeded during liftir	ng operations.		
Neierences. Ao 1410.0				
	HIGH 22	MEDIUM 15		
Risk Treatments in Place: Beacon				
This item of plant is fitted with a safety beacon. This beacon must meet the following criteria	at all times whilst this item of	plant fitted is in operation -		
 Is visible up to 200m in all directions (allowing for intermittent obstruction from the plant str Is fitted in the most appropriate location on machine to maximise visibility without risking co 		eration)		
NOTE: more than one beacon may be fitted to meet these criteria.				
References: ISO20474-				
OPERATIONAL MALFUNCTION	HIGH 22	LOW 2		
Risk Treatments in Place: Plant Modification				
The plant is in original condition.				
References: ISO31000				
ENTRAPMENT	HIGH 21	MEDIUM 15		
Risk Treatments in Place: Two Operator Exits The operator cabin/work area on this item of plant has a minimum of two (2) possible exits. These must be functional and accessible at all times whenever the item of plant is manned, whether during operation or maintenance activities.				
References: AS5327				
	HIGH 21	MEDIUM 15		
Risk Treatments in Place: Emergency Exits The emergency exits for this item of plant meet the following requirements -				
 Clearly and legibly labelled Instructions for use are clear and legible and located adjacent the exit Any required tools required for use are available e.g. Emergency hammers 				
These exits must be legibly labelled and fully functional at all times whenever the item of plant is manned, whether during operation or maintenance				
activities.				
References: ISO31000				
ROPS FITTED CRUSHING	HIGH 21	MEDIUM 15		
Risk Treatments in Place: ROPS A Roll Over Protective Structure (ROPS) to ISO 3471, ISO 12117.1 or 2, AS 2294 or AS 4987 is fitted to this item of plant. A permanent label stating this standard must be attached to the structure at all times. This structure provides a safety envelope during a rollover. A warning label re: wearing of seat belts at all times whilst this item of plant is in operation and accordingly seat belts must be worn at all times during operation. References: AS4987, AS2294, ISO3471				



MakeKubotaModelU17-3HGTypeExcavator - Small (0 - 9.9 Tonne)

Serial Number Assessed By Date

HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating		
CRUSHING	HIGH 21	LOW 5		
Risk Treatments in Place: FOPS General This item of plant is fitted with a Level I Falling Objects Protective Structure (FOPS). This structure is designed to protect the operator from small falling objects (e.g. bricks, small concrete blocks, hand tools)				
Before operating this item of plant a task based risk assessment must be conducted to determine the level of FOPS required. Level I - withstands 1,365 joules (e.g. 20kgs @ 7m drop, 70kgs @ 2m drop) - operations such as highway maintenance, landscaping and other construction site services Level II - withstands 11,600 joules (e.g. 200kgs @ 6m drop, 394kgs @ 3m drop) - operations such as site clearing, overhead demolition or forestry				
This task risk assessment must be undertaken before each operation, in particular when the within the same site. References: ISO10262	item of plant is moved to a ne	ew location, even if it is		
	HIGH 20	MEDIUM 14		
Risk Treatments in Place: Intuitive Controls The controls fitted to this item of plant are orientated so that the movement of the control is consistent with the action of the machine e.g. moving a control lever to the left results in the machine turning to the left. This design feature must be maintained at all times whilst this item of plant is in operation.				
References: AS/NZS4024.1906				
STRAINS	HIGH 19	LOW 5		
Risk Treatments in Place: Controls Ergonomics All controls including all levers, buttons, pedals, switches etc, are placed near the operator work position and are easy to reach and operate during the execution of the operator's normal duties. This applies for all persons within the 95th percentile of the normal population distribution. References: AS/NZS4024.1901				
	HIGH 17	LOW 6		
Risk Treatments in Place: Control Levers/Pedals/Buttons All controls including all levers, buttons, pedals, switches etc. must be kept non-slip and free from damage at all times.				
References: AS/NZS4024.1901	1	1		
	MEDIUM 12	LOW 6		
Risk Treatments in Place: Operator Work Area Access/Egress Safe access and egress to the cabin/work area(s) must be maintained at all times whilst this item of plant is in operation. It must be non slip, free from damage, located at a height so as to not cause undue body stresses and strains with three points of contact available to personnel at all times.				
All personnel must - 1. Always face the item of plant during access and egress. 2. Always maintain three points of contact during access and egress. 3. Never carry an object(s) in his/her hand(s) during access and egress. 4. Never jump off machine.				
References: AS5327				
FALLING, SLIPPING	MEDIUM 12	LOW 6		
Risk Treatments in Place: Access/Egress Instruction Label An instruction label is fitted adjacent access/egress areas to advise all personnel of the following -				
 Always face the item of plant during access and egress. Always maintain three points of contact during access and egress. Ensure the steps are clean. Never jump off machine. 				
This label must be clear and legible at all times whilst this item of plant is in operation. References: ISO31000				



MakeKubotaModelU17-3HGTypeExcavator - Small (0 - 9.9 Tonne)

Serial Number Assessed By Date

HAZARD(S)		Prelim. Risk Rating	Residual Risk Rating
If you car? see my micros I CAN'T SEE YDU POOR VISIBILITY, COLLISION		MEDIUM 12	MEDIUM 11
Risk Treatments in Place: Operator Mirror This item of plant is fitted with at least one rear vision operation.	mirror. This mirror must be fully functio	nal and clean at all times whi	slt this item of plant is in
References: ISO5006			
ELECTRIC SHOCK, BURNS		MEDIUM 12	LOW 6
Risk Treatments in Place: Battery Cover All batteries fitted to this item of plant are constrained The constraint and cover must be present and fully fur References: AS/NZS4024.1201			
		MEDIUM 9	LOW 4
Risk Treatments in Place: Work Area Floors All work area floors are non-slip and free from damage Floor area must remain non-slip and free from damage		l other items, at all times whils	st this item of plant is in
use.			
References: AS/NZS4024.1201, ISO20474-			
MON COMPLIANCE, STRAINS		MEDIUM 9	LOW 1
Risk Treatments in Place: Operator Seat			
The operator seat fitted to this item of plant must rema	ain free from damage and tears, and be	e permanently and securely fi	tted at all times.
References: AS/NZS4024.1401 , ISO20474-		1	1
BURNS		MEDIUM 9	LOW 5
Risk Treatments in Place: Exhaust The engine exhaust on this item of plant is fitted with a and fully functional and serviceable at all times whilst		and control the risk of initiatir	ng a fire. It must be present
References: AS/NZS4024.1201			
CURRENT OR PREVIOUS STRUCTUR	RAL DAMAGE	CRITICAL 25	MEDIUM 15
Risk Treatments in Place: Structural Integrity Regular checks for structural damage must be underta components, etc.	aken. Look for cracks in frames/chassis	s (current or repaired), bends	or damage to structural
References: ISO31000			
		HIGH 22	MEDIUM 15
Risk Treatments in Place: Maintenance Manual			
The manufacturer's maintenance manual(s) has been	supplied for this item of plant		
These manual(s) must be available at all times to all u be familiar with these handbook(s) prior to maintaining		n of plant. All users and maint	enance staff must read and
A complete risk assessment/JSEA must be undertake of plant prior to use.	n covering all inspection, maintenance	, servicing and transportation	requirements of this piece
A full assessment of the competence of people using	()		
References: Work Health & Safety Act & Regulation	s-, Occupational Health & Safety Act	& Regulations	





	HAZARD(S)	Prelim. Risk Rating	Residual Risk Ra
Ţ	STRIKING, BURNS	HIGH 22	MEDIUM 15
The hydrau that hoses and protec	tments in Place: Hydraulic Damage lic hoses to this item of plant are free from damage and protected against damage are free from damage and that protection is in place at all times whilst this item of tion system should be conducted regularly and documented as part of your plant	of plant is in operation. Inspec	
	CRUSHING	HIGH 22	MEDIUM 15
The Roll Ov operation.	tments in Place: ROPS Damage ver Protective Structure (ROPS) fitted to this item of plant must remain free from	damage at all times whilst this	s item of plant is in
Reference	es: AS2294, ISO3471	1	1
Ŷ	OPERATIONAL MALFUNCTION	HIGH 22	LOW 2
wheel hubs detected m	f plant must remain free from leaks at all times whilst in operation (this includes e s, steering and hydraulics). Development of a major leak will require this item of p ust be repaired within 1-14 days. es: ISO31000		
	OPERATIONAL MALFUNCTION	HIGH 21	MEDIUM 15
	tments in Place: Service Records d maintenance records are available for this item of plant.		
includes the	rds must continue to be managed and available at all times as part of your servic e undertaking of regular inspections of the item of plant with specific reference to d maintenance requirements).		
Reference	es: Work Health & Safety Act & Regulations- , Occupational Health & Safety Act	& Regulations	
*	POOR VISIBILITY, COLLISION	HIGH 21	MEDIUM 15
	tments in Place: Windows & Screens cabin/work area safety glass windows and screens are kept clean and free from use.	cracks and other damage at a	all times whilst this iter
Reference	es: AS/NZS4024.1201, ISO20474-		
*	INSTABILITY	MEDIUM 9	LOW 4
Rick Troa	tments in Place: Tracks		
The tracks safety prog	and track components must be inspected as part of a "pre start" checklist. These ramme. es: ISO20474-	e inspections must be docume	nted as part of your pl

IMAGES

- No Images Available -

NOTES



- No Notes Available -





Serial Number Assessed By Date

Ideagen? RISK MANAGEMENT REPORT

ТҮРЕ	Excavator - Small (0 - 9.9 Tonne)	Report Number	AHH 20250603-0742
MAKE	Kubota	Date	03-Jun-2025
MODEL	U17-3HG	Created By	AHSH Service
SERIAL NUMBER	54890	Assessor	Mitchell Pennells
PLANT NUMBER	AHSH139	Assist. Assessor(s)	Mitchell Pennells
		Owner	Australian Hammer Supplies Hire Pty Ltd
		Assessment Purpose	Hire
		State	NSW

OPERATOR ACKNOWLEDGEMENT

I the undersigned acknowledge that I have read and understand the risk management report described above. I also acknowledge that I have received a copy of this risk management report.

DATE	NAME	COMPANY/POSITION	SIGNATURE



