Ideagen⁷ Plant Assessor

RISK MANAGEMENT REPORT

HAMMER

E

TYPE	Rock Saw - Attachment
MAKE	Austramac
MODEL	1400 RM
SERIAL NUMBER	214102108
PLANT NUMBER	60F
Report Number	AHH 20250218-1428
Date	18-Feb-2025
Created By	AHSH Service
Assessor	Mitchell Pennells
Assist. Assessor(s)	Amanda Fotheringham
Completed By	AHSH Service
Owner	Australian Hammer Supplies Hire Pty Ltd
Assessment Purpose	Hire
State	NSW

State NSW TABLE OF CONTENTS

SECTION 1	IMPORTANT INFORMATION Contains information outlining the scope and any limitations applicable to this Risk Management Report
SECTION 2	MACHINE DETAILS Contains standard machine specifications and details of any extras fitted
SECTION 3	RISK ANALYSIS, RISK EVALUATION & RISK TREATMENT Contains details of the technique used to calculate risk ratings, time frame and risk treatments. Please refer to this information when reviewing and interpreting the information in section 4 & 5
SECTION 4	RISK TREATMENTS REQUIRED Contains detailed information regarding the risk treatments to be implemented including hazard, risk rating, time frame, relevant standards & legislative references
SECTION 5	RISK TREATMENTS IN PLACE Contains detailed information regarding the risk treatments in place including hazard, risk rating, relevant standards & legislative references
SECTION 6	IMAGES AND NOTES Contains images & any relevant information entered by the assessor



MakeAustramacModel1400 RMTypeRock Saw - Attachment

Serial Number Assessed By Date

SECTION 1 IMPORTANT INFORMATION

This report generated by Plant Assessor™ © Online Safety Systems on Tuesday, 18 Feb 2025 2:32 PM

This report pertains to this item of plant as it appeared on the day of inspection.

It is the responsibility of the hirer to conform with the instructions and information contained within this report. Any change in condition of this item of plant should be reported to the hire company immediately.

Any information relating to the standard features have been supplied via the manufacturer and should be used as a guide only until verified.

For further information regarding this report contact Online Safety Systems on 1300 72 88 52

SECTION 2 MACHINE DETAILS

BLADE	
BLADE	
CARRIER UNIT	
GENERAL	
HIDRAULICS	
WORK CAPABILITIES	
 HYDRAULICS WORK CAPABILITIES	



 \geq



SECTION 3 RISK ANALYSIS / RISK EVALUATION

RI	SK ANALYSIS					
			CONS	EQUENCE		
		1. INSIGNIFICANT Dealt with by in house first aid	2. MINOR Treated by medical professionals, hospital out patients	3. MODERATE Significant non permanent injury overnight hospital stay	4. MAJOR Extensive permanent injury eg. Loss of fingers, extended hospital stay	5. CATASTROPHIC Death, permanent disabling injury eg. Loss of hand, quadriplegia
	A. Almost certain to occur in most circumstances	MEDIUM 8	HIGH 16	HIGH 18	CRITICAL 23	CRITICAL 25
Ļ	B. Likely to occur frequently	MEDIUM 7	MEDIUM 10	HIGH 17	HIGH 20	CRITICAL 24
	C. Possibly and likely to occur at sometime	LOW 3	MEDIUM 9	MEDIUM 12	HIGH 19	HIGH 22
	D. Unlikely to occur but could happen	LOW 2	LOW 5	MEDIUM 11	MEDIUM 14	HIGH 21
	E. May occur but only in rare circumstances	LOW 1	LOW 4	LOW 6	MEDIUM 13	MEDIUM 15

NUTION	CRITICAL	Act immediately to mitigate risk. Implement risk treatment(s) in accordance with the risk treatment table below.
		Act immediately to mitigate risk. Implement risk treatment(s) in accordance with the risk treatment table below. If the appropriate risk treatments are not immediately accessible establish interim risk treatment strategies. Permanent risk treatments must be implemented within one week.
	MEDIUM	Take reasonable steps to mitigate and monitor the risk. Implement risk treatment(s) in accordance with the risk treatment table below. Permanent risk treatments must be implemented within one month.
	LOW	Take reasonable steps to mitigate and monitor the risk. Implement risk treatment(s) in accordance with the risk treatments must be implemented within three months.

RISK TREATMENT

TREATMENT		st appropriate risk treatment option involves balancing the costs and efforts of implementation against the benefits ard to legal, regulatory and other requirements. (source AS/NZS ISO 31000:2018)
REAT	Eliminate	Eliminate the risk source.
RISK T	Substitute	Provide an alternative that is capable of performing the same task which is safer.
Ľ	Isolate	Isolate people from the hazard.
	Engineering	Provide or construct a physical barrier or guard.
	Administration	Develop policies, procedures, practices and guidelines in consultation with employees to mitigate the risk. Provide training, instruction and supervision about the risk source.
	Personal protective	Provide personal protective equipment to protect the individual from the risk source.



MakeAustramacModel1400 RMTypeRock Saw - Attachment

Serial Number Assessed By Date

SECTION 4 RISK TREATMENTS REQUIRED

This section of the report pertains to hazards created by use of this item of plant which currently do not have risk treatments in place. The risk treatments recommended in this section have been developed based on relevant Australian Standards, health & safety legislation, the hierarchy of risk treatment in accordance with the guidelines set forth in AS/NZS ISO 31000 – Risk Management and various other sources. The recommended risk treatment measures must be developed, implemented and validated as effective prior to the operation, maintenance or testing of this item of plant. Treatments applied must be dated and initialled adjacent the recommendations. All operators must read and understand the entire contents of this section prior to operating this item of plant.

	HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating	Time Frame	Due Date	Date Rectified	Initial
NG		HIGH 22	MEDIUM 12	1 Week	25-Feb-25		
SSION	Risk Treatment Required: Carrier Unit Ris A plant risk assessment must be available for t		this attachment.	1	1	I	
COMMISSIONING	The risk assessments should be conducted at a must be completed for each carrier unit with wh References: ISO31000	o		vailable to the	operator of the	e unit. A risk as	sessment
Assessor Comments: RESPONSIBILTY OF CARRIER RISK ASSESSMENT LIES WITH CARRIER OWNER - IF HIRING EXCAN ATTACHMENT, RISK ASSESSMENT WILL BE PROVIDED ON REQUEST Revised Date/Control Not Required Comments: RESPONSIBILTY OF CARRIER RISK ASSESSMENT LIES WITH CARRIER HIRING EXCAVATOR WITH ATTACHMENT, RISK ASSESSMENT WILL BE PROVIDED ON REQUEST							
NOL	NOMINATED OPERATOR ONLY	CRITICAL 24	MEDIUM 15	Immediate	18-Feb-25		
OPERATION	Risk Treatment Required: Operator Comp Only persons who are qualified, trained and ex- competent/licensed person available for operator operate this item of plant.	perienced and/or hold th			•	•	
OPERAI	Only persons who are qualified, trained and ex competent/licensed person available for operat	perienced and/or hold th ion of this item of plant t Regulation	hen only persons wh	o are supervise	•	•	



	HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating	Time Frame	Due Date	Date Rectified	Initial
	INCORRECT OPERATION	HIGH 21	MEDIUM 15	1 Week	25-Feb-25		
	tment Required: SOP Carrier Unit arrier Safe Operation Procedures, and e	nsure they include th	e following as a minir	mum:			
2. Use Fall 3. Use Fall 4. Be famili 5. Never st 6. Never ju 7. Never re 8. Keep all 9. Never be 10. Install s 11. Keep si 12. Dress p 13. Check 14. Always 15. Never v 16. Never of 17. Ensure 18. Never t	bur carrier unit, its limitations and feature I Over Protective Structures (ROPS) and ing Object Protective Structures (FOPS) iar with the terrain on which the carrier u art an engine in an enclosed environme mp off a moving carrier unit or leave it w fuel while the engine is running or hot. children off of and away from carrier un e in a hurry about anything to do with the safety equipment, such as fire extinguish afety signs clean and free from obstruction oroperly. Close fitting clothing, safety foo the work area. Identify ditches, rocks, st check for underground utilities and mar work too close to trenches or banks. The operate if anyone is standing too close, i all operators and bystanders wear hear couch working parts of the attachment or carry passengers under any circumstan	I seatbelts whenever wherever possible. nit will be used and nt. Carbon monoxide ith the engine runnir it and implements at e carrier unit or its im her, first aid kit etc ng material. Replace twear, heavy work g umps and other hazi k locations prior to b se may collapse. Nying objects are a s ing protection at all the hydraulic hoses after	and wherever possib drive safely. Use caut e is colourless, odourl ng. all times. plements. Take time e missing or damaged loves and eye protect ards before starting w ucket to break ground erious hazard. Keep v imes during operation	ble. tion on slopes. and do it right. d signs. tion are all req york, and imple d.	lly. uired as a minii ement appropria	ate controls.	
Reference	es: Work Health & Safety Act & Regula	ions- , Occupational	Health & Safety Act	& Regulations			
ATTACHM Revised I	Comments: RESPONSIBILTY OF CA ENT, RISK ASSESSMENT WILL BE PR Date/Control Not Required Comme (CAVATOR WITH ATTACHMENT, RISK	OVIDED ON REQU	EST TY OF CARRIER RI	SK ASSESSN			

SECTION 5 RISK TREATMENTS IN PLACE

This section of the report pertains to risk treatments currently in place on this item of plant. This section must be read in conjunction with the safety section of the manufacturers handbook. All operators must read and understand the entire contents of this section prior to operating this item of plant. These treatments or equivalent must remain in place at all times whilst this item of plant is in operation.

	HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating
IVERY	CRUSHING	HIGH 22	MEDIUM 15
ELIV	Risk Treatments in Place: SWMS Load Restraint Ensure that all operators follow the approved SWMS/SOP when restraining this machine for	transport.	
B	References: Work Health & Safety Act & Regulations- , Occupational Health & Safety Act	•	
SIONING		HIGH 22	MEDIUM 15
6	Risk Treatments in Place: Pre-start checklist		
SSI	The operational "pre start" checklist must be completed before the start of each operation. If commencement of operation. These inspections must be documented as part of your plant s		
COMMIS	References: Work Health & Safety Act & Regulations- , Occupational Health & Safety Act	, , , , ,	
N			
ö			
	4		



	HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating
	INCORRECT OPERATION	HIGH 22	MEDIUM 15
	tments in Place: Operation Handbook acturer's operation handbook has been supplied for this item of plant.	'	
	ook must be available at all times to all potential operators and supervisory staff. ook prior to operating.	All potential operators must re	ead and be familiar with
plant. SWM	risk assessment/Job Safety Analysis must be undertaken covering all operating IS should be produced for specific tasks associated with use of this item of plant.	-	associated with this item of
Reference	es: Work Health & Safety Act & Regulations- , Occupational Health & Safety Act	& Regulations	
	INCORRECT OPERATION	HIGH 22	MEDIUM 15
	tments in Place: SOP Rock Saw - Attachment tion Procedures are available for this Rock Saw - Attachment. The information in	the Safe Operation Procedur	es must be followed at all
	t operating this Rock Saw - Attachment.		
Reference	es: Work Health & Safety Act & Regulations- , Occupational Health & Safety Act	& Regulations	
~	ENTANGLEMENT	HIGH 22	HIGH 21
	tments in Place: Entanglement Label		
This item of times.	f plant has hazard warning labels re: Entaglement, stand clear. These labels must	t be present and fully functior	al and serviceable at all
	es: AS/NZS4024.1201, AS1319-		
	ENTANGLEMENT	HIGH 19	HIGH 19
	tments in Place: Entanglement Information potential for entanglement in the rotating components of this item of plant. Ensure	that all clothing hair and oth	er materials that can
	tangled are close fitting and or controlled to prevent entanglement. Serious injury	-	
Reference	es: Work Health & Safety Act & Regulations- , ISO31000, Occupational Health &	Safety Act & Regulations	
O	HEARING LOSS	HIGH 19	MEDIUM 14
The hazard Permanent plant is in o	•	•	•
Reference	es: AS3781- , AS/NZS1269		
	EYE DAMAGE	HIGH 19	MEDIUM 14
The hazard lodged in th and legible	tments in Place: Eye Protection Label warning labels re: wearing eye protection attached to this item of plant refer to the e eye and causing serious injury. Permanent eye damage may result if eye prote at all times.		
Reference	es: AS/NZS4024.1201, AS1319-		
00	ENTANGLEMENT, SHEARING, PINCHING	HIGH 19	MEDIUM 13
	tments in Place: Guarding Label		
	b, pulleys and gears are guarded. These guards must be present, fully functional a nd the labels re: do not open or remove while power source is running must be in		
	es: AS/NZS4024.1201	. plase and easily seen at an	





MakeAustramacModel1400 RMTypeRock Saw - Attachment

Serial Number Assessed By Date

	HAZARD(S)		Prelim. Risk Rating	Residual Risk Rating			
NCE	STRIKING, BURNS		HIGH 22	MEDIUM 15			
COMPLIANCE	Risk Treatments in Place: Hydraulic Hoses This item of plant has hydraulic hoses. These hoses must be inspected each day or before each use for wear and tear. If there are visible signs of wear, immediate action must be taken to control the risk arising from this wear. These inspections must be documented.						
DESIGN CO	Hydraulic fluid at high pressure can penetrate the skin, advice immediately. Always use a piece of cardboard o hydraulic hoses.	· · · · ·					
DES	Hydraulic pressure can be stored and is a hazard. Alwa References: AS4024, AS2671	ays connect and disconnect hydraulic	hoses as per the manufactur	er's manual.			
			HIGH 22	MEDIUM 15			
	Risk Treatments in Place: Hydraulic Hose Failure This item of plant is fitted with a sturdy, permanent shie during a hose or component failure. This shield(s) must	ld(s) between the hydraulic hoses and					
	References: AS4024, ISO4413, AS2671						
	CRUSHING, ENTANGLEMENT, SHEAF		HIGH 22	MEDIUM 15			
	Risk Treatments in Place: Safe Operator Location This machine is designed so that the operator is isolate whilst this item of plant is in operation. References: AS/NZS4024.1201		operator position. This condit	ion must exist at all times			
			HIGH 22	MEDIUM 11			
	Risk Treatments in Place: Ejection Chute Shroud This item of plant is fitted with a shroud covering all are present and fully functional and serviceable at all times References: AS/NZS4024.1201	as where objects can be ejected while		tion. These must be			
	OPERATIONAL MALFUNCTION		HIGH 22	LOW 2			
	Risk Treatments in Place: Plant Modification The plant is in original condition. References: ISO31000						
NCE	CURRENT OR PREVIOUS STRUCTUR	AL DAMAGE	CRITICAL 25	MEDIUM 15			
MAINTENANCE	Risk Treatments in Place: Structural Integrity Regular checks for structural damage must be undertal components, etc.	ken. Look for cracks in frames/chassis	s (current or repaired), bends	or damage to structural			
	References: ISO31000						
Ň			HIGH 22	MEDIUM 15			
	Risk Treatments in Place: Maintenance Manual The manufacturer's maintenance manual(s) has been s	supplied for this item of plant					
	These manual(s) must be available at all times to all us be familiar with these handbook(s) prior to maintaining		n of plant. All users and maint	enance staff must read and			
	A complete risk assessment/JSEA must be undertaken of plant prior to use.	covering all inspection, maintenance	, servicing and transportation	requirements of this piece			
	A full assessment of the competence of people using the References: Work Health & Safety Act & Regulations		& Regulations				

Ideagen[†] Plant Assessor



MakeAustramacModel1400 RMTypeRock Saw - Attachment

Serial Number Assessed By Date

HAZARD(S)	Prelim. Risk Rating	Residual Risk Rati
	HIGH 22	MEDIUM 15
Risk Treatments in Place: Hydraulic Damage		
The hydraulic hoses to this item of plant are free from damage and protected against da	mage arising from contact with th	ne plant structure. Ensur
that hoses are free from damage and that protection is in place at all times whilst this ite		ction of the hydraulic hos
and protection system should be conducted regularly and documented as part of your p	olant safety programme.	
References: AS4024, ISO4413, AS2671		
	HIGH 22	LOW 2
Risk Treatments in Place: Major Fluid Leaks		
This item of plant must remain free from leaks at all times whilst in operation (this includ	es engine, transmission, cooling	system, air, fuel, drive li
wheel hubs, steering and hydraulics). Development of a major leak will require this item	of plant to be stood-down until re	paired. Minor leaks
detected must be repaired within 1-14 days.		
References: ISO31000	1	1
	HIGH 21	MEDIUM 15
Risk Treatments in Place: Service Records		
Service and maintenance records are available for this item of plant.		
These records must continue to be managed and available at all times as part of your so		(1 0
includes the undertaking of regular inspections of the item of plant with specific reference	e to all OEM prescribed, schedul	ed and non scheduled
service and maintenance requirements).		
References: Work Health & Safety Act & Regulations- , Occupational Health & Safety	Act & Regulations	
TION 6 IMAGES AND NOTES		
GES		

- No Images Available -

NOTES

- No Notes Available -





MakeAustramacModel1400 RMTypeRock Saw - Attachment

Serial Number Assessed By Date

Ideagen⁷ Plant Assessor

RISK MANAGEMENT REPORT

ТҮРЕ	Rock Saw - Attachment	Report Number	AHH 20250218-1428
MAKE	Austramac	Date	18-Feb-2025
MODEL	1400 RM	Created By	AHSH Service
SERIAL NUMBER	214102108	Assessor	Mitchell Pennells
PLANT NUMBER	60F	Assist. Assessor(s)	Amanda Fotheringham
		Owner	Australian Hammer Supplies Hire Pty Ltd
		Assessment Purpose	Hire
		State	NSW

OPERATOR ACKNOWLEDGEMENT

I the undersigned acknowledge that I have read and understand the risk management report described above. I also acknowledge that I have received a copy of this risk management report.

DATE	NAME	COMPANY/POSITION	<u>SIGNATURE</u>

AHH 20250218-1428



 Make
 Austramac

 Model
 1400 RM

 Type
 Rock Saw - Attachment

Serial Number Assessed By Date