



## MACHINE SERVICE REPORT

RO Number: E34255 | Service Date: April 14, 2026 11:07 am

### Machine Details

<b>Customer:</b>	Australian hammer supplies	<b>Hour Meter:</b>	2531
<b>Model:</b>	Sk235sr-2	<b>Service Type:</b>	500
<b>Serial Number:</b>	Yf06005223	<b>Service Interval:</b>	500 Hour Service

Before Service Photos













### Parts Replaced/Service

Part Type	Status
Engine Oil Filters	Done
Hydraulic Return	Done
Primary Fuel	Done
Fuel /Water	Done
Outer Air	Done
Grease	Done
Brake Cleaner	Done

### Fluid Levels & Replacements

<p>Engine Oil <b>24 LTS</b></p>	<p>Final Drive Oil <b>20 LTS</b></p>
-------------------------------------	--

## System Measurements

Charge Rate

**28 V**

## Service Checklist Completed

### 500 Hour Service:

Replace Engine Oil Fluid  
Replace Engine Oil Filter  
Replace Hydraulic Filter  
Replace Primary Fuel Filters  
Check Hydraulic Oil Level  
Check Slew Reduction Oil Level  
Check Final Drive Oil Level  
Check Coolant Radiator Level  
Check Engine Fan Belts Tension  
Check A/C Belt Tension  
Check / Adjust Track Tension  
Check Upper / Lower Rollers  
Check Machine Horn Operation  
Check Radiator Hoses, No Leaks  
Check 2 Speed Travel Operation  
Check Neutral Start Working  
Check Safety Lever Operation  
Check No Fault Codes Active  
Check E-Stop Operation  
Drain Water from Fuel Tank  
Check No Visual Oil Leaks  
Clean Outer Air Filter  
Clean Cabin Air Filters  
Check Flashing Light Operation  
Check Work Light Operation  
Visual Inspection Over Machine  
Check Wiper Bottle Water Level  
Check Quick Hitch Operation  
Check Quick Hitch Pins / Bolts  
Check Radiator Cap Condition  
Grease Machine - All Pins / Slew  
Replace Fuel Water Filters  
Replace Primary Fuel Filter  
Replace Engine Outer Air Filter  
Clean Radiator Core Filters  
Replace Final Drive Reduction Oils

### Service Completion:

Reset Machine Dash Hours  
Fit Next Service Sticker to Window

### Comments:

Top up hyd oil 20ltr rh boom cylinder around burst valve looks to bel leaking from feral on hose fittings are tight

Next Service Due:

3000


After Service Photos



SPEED  
28mph (45kph)



safety.yellower.com



safety.yellower.com

**STM**  
TRUCKS & MACHINERY

Call 1300 305 420  
Or book online



Date of last service  
**14-4-26**

Hours at last service  
**2531HR**

Next service due  
**14-10-26**

Hours due for service  
**3000 HR**

**WARNING**

All attachments must be considered part of the load. Excess hook, bucket, hammer, etc. installation of Quick Hitch will reduce bucket to cabin clearance.

**WARNING**

**ROPS FITTED**  
Do not drill or weld.

**⚠ DANGER**

Contact with electrical power lines will result in severe injury or death.

Keep machine and attachment a safe distance from electrical power lines as per following instruction.

VOLTAGE(Volts)	SAFETY DISTANCE
50K or LESS	3.0M(10FT)
50K to 200K	4.5M(15FT)
200K to 350K	6.0M(20FT)
350K to 500K	7.5M(25FT)
500K to 750K	10.5M(35FT)
750K or OVER	13.5M(45FT)

**WARNING**

Read and understand operator manual before operating or performing maintenance on this machine.

Failure to follow or pay attention to













## Quick Hitch Inspection

<b>Brand:</b>	Doherty
<b>Model:</b>	Std
<b>Serial Number:</b>	M28367
<b>Inspection Interval:</b>	500

### Inspection Results:

Is the quick hitch free from oil leaks?	<b>Yes</b>
Does the quick hitch unlock correctly?	<b>Yes</b>
Does the quick hitch lock correctly?	<b>Yes</b>
Identification plate present?	<b>Yes</b>
Visual inspection for cracks?	<b>Yes</b>
Picks up attachment correctly?	<b>Yes</b>
Buzzer works?	<b>Yes</b>
Switch protected by cover/lock?	<b>Yes</b>
Hoses in good condition?	<b>Yes</b>
Free from excessive wear?	<b>Yes</b>

## Service Completion

<b>Service Date:</b>	April 14, 2026 11:07 am	<b>Report Generated:</b>	April 14, 2026 11:07 am
<b>Technician:</b>	565	<b>RO Number:</b>	E34255