



MACHINE SERVICE REPORT

RO Number: 49350 | Service Date: April 24, 2026 10:41 am

Machine Details

Customer:	Australian Hammer Supplies Hire	Hour Meter:	2467
Model:	SK380XDLC-10	Service Type:	500 hour
Serial Number:	YC14405666	Service Interval:	500 Hour Service

Parts Replaced/Service

Part Type	Status
Engine Oil Filters	Done
Hydraulic Return	Done
Primary Fuel	Done
Fuel /Water	Done
Outer Air	Done
Grease	Done
Brake Cleaner	Done

Fluid Levels & Replacements

Engine Oil 28 LTS	Final Drive Oil 15 LTS	Hydraulic Oil 25 LTS	Coolant 0 LTS	Grease 1 LTS
-----------------------------	----------------------------------	--------------------------------	-------------------------	------------------------

System Measurements

Charge Rate
28 V

Service Checklist Completed

500 Hour Service:

Replace Engine Oil Fluid
Replace Engine Oil Filter
Replace Hydraulic Filter
Check Hydraulic Oil Level
Check Slew Reduction Oil Level
Check Coolant Radiator Level
Check Engine Fan Belts Tension
Check A/C Belt Tension
Check / Adjust Track Tension
Check Upper / Lower Rollers
Check Machine Horn Operation
Check Radiator Hoses, No Leaks
Check 2 Speed Travel Operation
Check Neutral Start Working
Check Safety Lever Operation
Check No Fault Codes Active
Check E-Stop Operation
Drain Water from Fuel Tank
Check No Visual Oil Leaks
Clean Cabin Air Filters
Check Flashing Light Operation
Check Work Light Operation
Visual Inspection Over Machine
Check Wiper Bottle Water Level
Check Quick Hitch Operation
Check Quick Hitch Pins / Bolts
Check Radiator Cap Condition
Grease Machine - All Pins / Slew
Replace Fuel Water Filters
Replace Primary Fuel Filter
Replace Engine Outer Air Filter
Replace Final Drive Reduction Oils

Service Completion:

Reset Machine Dash Hours
Fit Next Service Sticker to Window

Comments:

Batteries were flat on arrival, had to jump start. Recommend removing additional wire from battery positive to eliminate parasitic drain
Top up hydraulic oil
A/C condenser damaged, looks to be from high pressure washer
1x cab light not working
Deck light on step not working
Damage to boom pipe clamp
Could do with more hydraulic oil, only had 25 litres on board, level is just above low mark

Next Service Due:

3000 hours

After Service Photos











Quick Hitch Inspection

Brand:	Attach 2
Model:	Standard
Serial Number:	Unknown
Inspection Interval:	500

Inspection Results:

Is the quick hitch free from oil leaks?	Yes
Does the quick hitch unlock correctly?	Yes
Does the quick hitch lock correctly?	Yes
Identification plate present?	No
Visual inspection for cracks?	Yes
Picks up attachment correctly?	Yes
Buzzer works?	Yes
Switch protected by cover/lock?	Yes
Hoses in good condition?	Yes
Free from excessive wear?	No

Hitch Comments/Repairs Required:

Missing retaining bolt for secondary lock pin
No ID plate

Service Completion

Service Date:	April 24, 2026 10:41 am	Report Generated:	April 24, 2026 10:41 am
Technician:	Jason	RO Number:	49350