



MACHINE SERVICE REPORT

RO Number: E33965 | Service Date: February 27, 2026 11:10 am

Machine Details

Customer:	Australian hammer supplies hire	Hour Meter:	1222
Model:	Sk135sr-7	Service Type:	1000
Serial Number:	Yy09053184	Service Interval:	1000 Hour Service













Parts Replaced/Service

Part Type	Status
Engine Oil Filters	Done
Hydraulic Return	Done
Primary Fuel	Done
Fuel /Water	Done
Fuel /Water	Done
Outer Air	Done
Inner Air	Done
Breather	Done
A/C Filter x1	Done
A/C Filter x1	Done
Oil Sample Kits	Done
Grease	Done
Brake Cleaner	Done

Fluid Levels & Replacements

Engine Oil
17 LTS

Final Drive Oil
6 LTS

System Measurements

Charge Rate
28 V

Pump 1
336 BAR

Pump 2
336 BAR

Service Checklist Completed

1000 Hour Service:

Replace Engine Oil Fluid
Replace Engine Oil Filter
Replace Hydraulic Filter
Replace Primary Fuel Filters
Check Hydraulic Oil Level
Check Slew Reduction Oil Level
Check Final Drive Oil Level
Check Coolant Radiator Level
Check Engine Fan Belts Tension
Check A/C Belt Tension
Check / Adjust Track Tension
Check Upper / Lower Rollers
Check Machine Horn Operation
Check Radiator Hoses, No Leaks
Check 2 Speed Travel Operation
Check Neutral Start Working
Check Safety Lever Operation
Check No Fault Codes Active
Check E-Stop Operation
Drain Water from Fuel Tank
Check No Visual Oil Leaks
Clean Outer Air Filter
Clean Cabin Air Filters
Check Flashing Light Operation
Check Work Light Operation
Visual Inspection Over Machine
Check Wiper Bottle Water Level
Check Quick Hitch Operation
Check Quick Hitch Pins / Bolts
Check Radiator Cap Condition
Grease Machine - All Pins / Slew
Replace Fuel Water Filters
Replace Primary Fuel Filter
Replace Engine Outer Air Filter
Clean Radiator Core Filters
Replace Final Drive Reduction Oils
Carry Out Oil Sampling - Warranty
Replace Hydraulic Return Filter
Replace Engine Inner Air Filter
Replace Cabin A/C Filters

Service Completion:

Reset Machine Dash Hours
Fit Next Service Sticker to Window

Comments:

Hyd breather broken requires replacement
Lh joystick broken is taped together
Fuel drain on water separated snapped but is not leaking
Remove broken grease nipple on dipper cylinder and replace the grease nipple

Next Service Due:

1722

After Service Photos









	4.5 m		6.0 m		At max. re	
5 m	kg					
4.0 m	kg					
3.5 m	kg					
3.0 m	kg					
1.5 m	kg					
G.L.	kg					
-1.5 m	kg					
-3.0 m	kg					

Note: Lift without Bucket, Deduct weight of Hitch, Refer to Operators Manual for additional informat

STM
TRUCKS & MACHINERY

Call 1300 905 420
Or book online



Date of last service
27-2-28

Hours at last service
1222 hr

Next service due
27-8-26

Hours due for service
1722 hr











Quick Hitch Inspection

Brand:	Gieth
Model:	Tilt
Serial Number:	58997
Inspection Interval:	1000

Inspection Results:

Is the quick hitch free from oil leaks?	No
Does the quick hitch unlock correctly?	Yes
Does the quick hitch lock correctly?	Yes
Identification plate present?	Yes
Visual inspection for cracks?	Yes
Picks up attachment correctly?	Yes
Buzzer works?	Yes
Switch protected by cover/lock?	Yes
Hoses in good condition?	Yes
Free from excessive wear?	Yes

Hitch Comments/Repairs Required:

Hitch cylinder wrapping oil

Service Completion

Service Date:	February 27, 2026 11:10 am	Report Generated:	February 27, 2026 11:10 am
Technician:	565	RO Number:	E33965