Australian Hammer Supplies Hire
Unit 3/32 Williamson Road
Ingleburn
NSW 2565

CATERPILLAR CAT336GC

Major Service

1 14 82 10


Inspection Number	RP064523	Customer No	200000
Serial Number	JFW10542	Customer Name	AUSTRALIAN HAMMER SUPPLIES HIRE
Make	CATERPILLAR	Customer Email	
Model	CAT336GC	Works Order	RP064523
Equipment Family	35.1-40T HYDRAULIC EXCAVATOR	Completed On	10/11/2026 2:04:25 PM
Asset ID	AHSH126	Inspector	Etienne Llanos
Location	AUSTRAILAN HAMMER SUPPLIES HIRE Unit 3/32 WILLIAMSON RD INGLEBURN 2565	PDF Generated On	10/11/2026
		Machine Hours	6927
		Next Meter	7250

Customer

General Info & Comments

General Info/Comments *1000hr at 7000hr*





TASK SAFETY INSTRUCTIONS

1.1 Wear Correct PPE at all times *PASS*

1.2 All isolation and safe work procedures must be followed *PASS*

1.3 Identify task hazards and controls utilising hierarchy or controls model	*PASS*
1.4 Ensure a competent operator and spotter is utilised to move mobile equipment	*PASS*
1.5 Ensure all mobile equipment is fundamentally stable	*PASS*
1.6 Ensure three points of contact is maintained during access and egress	*PASS*
1.7 Ensure acceptable housekeeping standards are maintained at all times	*PASS*

MACHINE GENERAL RUNNINGCHECKS

2.1 Check all work lights, beacon & reverse alarmfor operation	*PASS*
2.2 Test all dash warning lights, gauges and audible alarms for correct operation	*PASS*
2.3 Check idle timer for correct shut down operation	*PASS*
2.4 Check operation of all three emergency stop buttons	*PASS*
2.5 Check operation of horn	*PASS*
2.6 Check operation of reverse camera	*PASS*
2.7 Check alternator charge voltage	*PASS*
2.8 Check operation of auto grease systemby manually activating timer	*N/A*
2.9 Check fire systemcontrol panel for 'Normal'	*N/A*

PM FIRE SUPPRESSION SYSTEM

5.1 Ensure fire suppression bottle and components are securely mounted and in good condition	*N/A*
5.2 Ensure fire suppression is correctly charged	*N/A*
5.3 Inspect last charge date	*DATE:2026-11-11 T00:00:00.0000000*
5.4 Check all fire extinguishers are securely mounted and in good condition	*PASS*
5.5 Check all fire extinguishers are correctly charged	*PASS*

○	**5.6 Inspect last charge date**	*DATE:2026-11-11 T00:00:00.0000000*

PM ENGINE

○	**6.1 Performengine valve set**	*N/A*
●	**6.2 Inspect air intake systemhoses, pipes, clamps for signs of dirt ingress**	*MONITOR*
●	**6.3 Inspect engine for oil or fuel leaks**	*PASS*
●	**6.4 Inspect engine components for missing clamps**	*PASS*
●	**6.5 Inspect exhaust systemfor signs of leaks, loose bolts or missing clamps**	*PASS*
●	**6.6 Inspect turbo for security and signs of leaks**	*PASS*
●	**6.7 Inspect condition of exhaust lagging**	*PASS*
●	**6.8 Inspect engine mounts for condition and loose hardware**	*PASS*
●	**6.9 Inspect alternator mount condition and adjustment**	*PASS*
●	**6.10 Inspect wiring condition and security**	*PASS*
●	**6.11 Inspect engine belts**	*PASS*

PM ENGINE COOLINGSYSTEM

●	**7.1 Check coolant level**	*PASS*
●	**7.2 Check condition of radiator cap**	*PASS*
●	**7.3 Check condition of radiator core**	*PASS*
●	**7.4 Check cooling systemfor signs of leaks**	*PASS*
●	**7.5 Check hose and clamp condition**	*PASS*
●	**7.6 Inspect fan condition and operation**	*PASS*
●	**7.7 Inspect radiator and fan guard condition**	*PASS*

PM SWINGTRANSMISSION

8.1 Inspect swing transmission for signs of leaks	*PASS*
8.2 Inspect swing transmission oil level	*PASS*

PM HYDRAULIC SYSTEM

9.1 Check hydraulic oil level	*PASS*
9.2 Inspect hydraulic cylinders for leaks and security	*PASS*
9.3 Inspect hydraulic hoses for leaks, damage, security	*PASS*
9.4 Inspect hydraulic pump condition, leaks, security	*PASS*
9.5 Check Pilot Accumulator operation as per OEM Maintenance Procedure - Test Boom Down Functionality with engine off	*PASS*

PM FINAL DRIVES

10.1 Inspect LHS final drive mount condition for leaks and security	*PASS*
10.2 Inspect LHS oil level and mag plug condition	*PASS*
10.3 Inspect RHS final drive mount condition for leaks and security	*PASS*
10.4 Inspect RHS oil level and mag plug condition	*PASS*

PM UNDERCARRIAGE

11.1 Inspect LHS track tension	*PASS*
11.2 Inspect RHS track tension	*PASS*
11.3 Inspect tracks for loose/missing bolts	*PASS*
11.4 Inspect load and carrier rollers for signs of leaks	*PASS*
11.5 Inspect idlers for signs of leaks	*PASS*
11.6 Inspect sprocket segments condition	*PASS*
11.7 Inspect track frame for cracks, lose or missing hardware	*PASS*

PM FRAME AND BODY

●	**12.1 Check panels for damage and security**	*PASS*
●	**12.2 Check access steps and walkway condition**	*PASS*
●	**12.3 Inspect boom condition – cracks, missing clamps, damaged pipes, excessive movement, lubrication**	*PASS*
●	**12.4 Inspect stick condition – cracks, missing clamps, damaged pipes, excessive movement, lubrication**	*PASS*
●	**12.5 Inspect quick hitch condition and operation**	*PASS*
●	**12.6 Inspect bucket condition – cracks, wear, damage, mounts**	*PASS*
●	**12.7 Inspect GET condition and hardware**	*PASS*

PM ELECTRICAL SYSTEM

●	**13.1 Check battery condition**	*FAIL*
●	**13.2 Check battery terminal condition**	*PASS*
●	**13.3 Check battery security**	*PASS*
●	**13.4 Check battery box drain is clear**	*PASS*
●	**13.5 Check wiring condition and security**	*PASS*

PM GREASE SYSTEM

●	**14.1 Check all points for acceptable lubrication**	*PASS*
●	**14.2 Inspect grease systemoperation**	*N/A*
●	**14.3 Check grease line condition**	*PASS*
●	**14.4 Refill grease tank**	*N/A*
●	**14.5 Lubricate bucket linkage**	*PASS*
●	**14.6 Lubricate blade linkage**	*N/A*
●	**14.7 Lubricate boom& stick linkage**	*PASS*
●	**14.8 Lubricate swing bearing**	*PASS*

Australian Hammer Supplies Hire
Unit 3/32 Williamson Road
Ingleburn
NSW 2565

PM OPERATOR STATION

15.1 Check all doors for correct opening and closing adjustments and operation	*PASS*
15.2 Inspect condition of door seals	*PASS*
15.3 Check window glass and seal condition	*PASS*
15.4 Check mirror condition and adjustments	*PASS*
15.5 Fill window washer reservoir	*PASS*
15.6 Inspect air con vents condition	*PASS*
15.7 Inspect seat belt and mounting hardware	*PASS*
15.8 Inspect seat condition, operation and mounting	*PASS*
15.9 Replace cabin A/C filter	*PASS*

OIL SAMPLING

16.1 Engine	*PASS*

PM POST SERVICE INSPECTION CHECKS

17.1 All inspections have been completed and rectified as required	*PASS*
17.2 All safety related defects have been repaired or reported	*PASS*
17.3 All defects have been noted and reported	*PASS*
17.4 All fluids are at correct level and drain plugs tight	*PASS*
17.5 All oil samples have visually been inspected and any notable signs of contamination have been reported	*PASS*
17.6 All replaced filters have been cut and inspected and photos added to CAT Inspect and reported to supervisor	*N/A*
17.7 Machine has been recommissioned and ready for operation	*PASS*
17.8 PM service notification marked off in Vision Link	*N/A*

DEFECTS IDENTIFIED

Australian Hammer Supplies Hire
Unit 3/32 Williamson Road
Ingleburn
NSW 2565

18.1 DEFECTS IDENTIFIED	*dead cell in battery, shim required*

OIL USED

19.1 Hydraulic oil	*0*
19.2 Engine oil	*20*
19.3 Slew oil	*13*
19.4 Gear oil	*12*
19.5 Coolant	*0*

- **Site photo**
- **Site photo**
- **Site photo**
- **Site photo**
- **Site photo**
- **Site photo**
- **Site photo**
- **Site photo**