



MACHINE SERVICE REPORT

RO Number: E32277 | Service Date: July 12, 2025 9:11 am

Machine Details

Customer:	Australian hammer	Hour Meter:	1226
Model:	Sk225-7	Service Type:	1000HR
Serial Number:	YB09020021	Service Interval:	1000 Hour Service

Before Service Photos



Parts Replaced/Serviced

Part Type	Status
Engine Oil Filters	Done
Hydraulic Return	Done
Primary Fuel	Done
Fuel /Water	Done
Outer Air	Done
Inner Air	Done
Breather	Done
A/C Filter x1	Done
A/C Filter x1	Done
Grease	Done
Brake Cleaner	Done

Fluid Levels & Replacements

Engine Oil 25 LTS	Final Drive Oil 20 LTS	Hydraulic Oil 0 LTS	Coolant 0 LTS	Grease 1 LTS
----------------------	---------------------------	------------------------	------------------	-----------------

Service Checklist Completed

Service Completion: Reset Machine Dash Hours Fit Next Service Sticker to Window
--



Quick Hitch Inspection

Brand:	A2
Model:	Quick hitch
Inspection Interval:	1000

Inspection Results:

Is the quick hitch free from oil leaks?	Yes
Does the quick hitch unlock correctly?	Yes
Does the quick hitch lock correctly?	Yes
Identification plate present?	Yes
Visual inspection for cracks?	Yes
Picks up attachment correctly?	Yes
Buzzer works?	Yes
Switch protected by cover/lock?	Yes
Hoses in good condition?	Yes
Free from excessive wear?	Yes

Service Completion

Service Date:	July 12, 2025 9:11 am	Report Generated:	July 12, 2025 9:11 am
Technician:	Lachlan Garde	RO Number:	E32277

STM Trucks & Machinery Pty Ltd | 20-26 Dunn Rd, Smeaton Grange NSW 2567 | 02 4647 4488 | ABN 36 142 316 916 / MD 038046

This service report has been reviewed and approved by our service department.