



## MACHINE SERVICE REPORT

RO Number: E33194 | Service Date: November 3, 2025 11:37 am

### Machine Details

|                       |               |                          |                  |
|-----------------------|---------------|--------------------------|------------------|
| <b>Customer:</b>      | Aussie hammer | <b>Hour Meter:</b>       | 1508             |
| <b>Model:</b>         | 135-7         | <b>Service Type:</b>     | 500              |
| <b>Serial Number:</b> | Yy09055165    | <b>Service Interval:</b> | 500 Hour Service |

Before Service Photos







### Parts Replaced/Service

| Part Type          | Status |
|--------------------|--------|
| Engine Oil Filters | Done   |
| Hydraulic Return   | Done   |
| Primary Fuel       | Done   |
| Fuel /Water        | Done   |
| Outer Air          | Done   |
| Grease             | Done   |
| Brake Cleaner      | Done   |

### Fluid Levels & Replacements

|                             |                                  |                        |
|-----------------------------|----------------------------------|------------------------|
| Engine Oil<br><b>20 LTS</b> | Final Drive Oil<br><b>20 LTS</b> | Grease<br><b>1 LTS</b> |
|-----------------------------|----------------------------------|------------------------|

## System Measurements

Charge Rate

**14 V**

## Service Checklist Completed

### 500 Hour Service:

Replace Engine Oil Fluid Replace Engine Oil Filter Replace Hydraulic Filter Replace Primary Fuel Filters Check Hydraulic Oil Level Check Slew Reduction Oil Level Check Final Drive Oil Level Check Coolant Radiator Level Check Engine Fan Belts Tension Check A/C Belt Tension Check / Adjust Track Tension Check Upper / Lower Rollers Check Machine Horn Operation Check Radiator Hoses, No Leaks Check 2 Speed Travel Operation Check Neutral Start Working Check Safety Lever Operation Check No Fault Codes Active Check E-Stop Operation Drain Water from Fuel Tank Check No Visual Oil Leaks Clean Outer Air Filter Clean Cabin Air Filters Check Flashing Light Operation Check Work Light Operation Visual Inspection Over Machine Check Wiper Bottle Water Level Check Quick Hitch Operation Check Quick Hitch Pins / Bolts Check Radiator Cap Condition Grease Machine - All Pins / Slew

Replace Fuel Water Filters Replace Primary Fuel Filter Replace Engine Outer Air Filter Clean Radiator Core Filters

Replace Final Drive Reduction Oils

### Service Completion:

Reset Machine Dash Hours Fit Next Service Sticker to Window

### Comments:

Rear handrails large bolts missing

Next Service Due:

2000

After Service Photos



## Quick Hitch Inspection

|                             |         |
|-----------------------------|---------|
| <b>Brand:</b>               | Doherty |
| <b>Model:</b>               | 135-140 |
| <b>Serial Number:</b>       | M52299  |
| <b>Inspection Interval:</b> | 500     |

### Inspection Results:

|   |            |
|---|------------|
| Is the quick hitch free from oil leaks? | <b>Yes</b> |
| Does the quick hitch unlock correctly?  | <b>Yes</b> |
| Does the quick hitch lock correctly?    | <b>Yes</b> |
| Identification plate present?           | <b>Yes</b> |
| Visual inspection for cracks?           | <b>Yes</b> |
| Picks up attachment correctly?          | <b>Yes</b> |
| Buzzer works?                           | <b>Yes</b> |
| Switch protected by cover/lock?         | <b>Yes</b> |
| Hoses in good condition?                | <b>Yes</b> |
| Free from excessive wear?               | <b>Yes</b> |

## Service Completion

|                      |                           |                          |                           |
|----------------------|---------------------------|--------------------------|---------------------------|
| <b>Service Date:</b> | November 3, 2025 11:37 am | <b>Report Generated:</b> | November 3, 2025 11:37 am |
| <b>Technician:</b>   | 728                       | <b>RO Number:</b>        | E33194                    |