



MACHINE SERVICE REPORT

RO Number: E34239 | Service Date: April 10, 2026 10:02 am

Machine Details

Customer:	AHSH	Hour Meter:	1450
Model:	SK225SR-7	Service Type:	500
Serial Number:	YB09020014	Service Interval:	500 Hour Service



KOMATSU

AUS: 1300 599 02

MACHINE MAKE & MODEL

PG200USLC-8

ATTACHMENT DESCRIPTION

HYDRAULIC TILTING OH

PART No.

7668-00-00

SERIAL NUMBER

KOMT-80-63

ATTACHMENT NET MASS (kg)

570

HOISTING EYE CAPACITY (kg)

8500

BUILD DATE

1 AUGUST 2011

MIN

PIN CENTRE RANGE (mm)

MAX











Parts Replaced/Service

Part Type	Status
Engine Oil Filters	Done
Hydraulic Return	Done
Primary Fuel	Done
Fuel /Water	Done
Outer Air	Done
Grease	Done
Brake Cleaner	Done

Fluid Levels & Replacements

Engine Oil 24 LTS	Final Drive Oil 15 LTS	Grease 1 LTS
-----------------------------	----------------------------------	------------------------

System Measurements

Charge Rate

28 V

Service Checklist Completed

500 Hour Service:

- Replace Engine Oil Fluid
- Replace Engine Oil Filter
- Replace Hydraulic Filter
- Replace Primary Fuel Filters
- Check Hydraulic Oil Level
- Check Slew Reduction Oil Level
- Check Final Drive Oil Level
- Check Coolant Radiator Level
- Check Engine Fan Belts Tension
- Check A/C Belt Tension
- Check / Adjust Track Tension
- Check Upper / Lower Rollers
- Check Machine Horn Operation
- Check Radiator Hoses, No Leaks
- Check 2 Speed Travel Operation
- Check Neutral Start Working
- Check Safety Lever Operation
- Check No Fault Codes Active
- Check E-Stop Operation
- Drain Water from Fuel Tank
- Check No Visual Oil Leaks
- Clean Outer Air Filter
- Clean Cabin Air Filters
- Check Flashing Light Operation
- Check Work Light Operation
- Visual Inspection Over Machine
- Check Wiper Bottle Water Level
- Check Quick Hitch Operation
- Check Quick Hitch Pins / Bolts
- Check Radiator Cap Condition
- Grease Machine - All Pins / Slew
- Replace Fuel Water Filters
- Replace Primary Fuel Filter
- Replace Engine Outer Air Filter
- Clean Radiator Core Filters
- Replace Final Drive Reduction Oils

Service Completion:

- Reset Machine Dash Hours
- Fit Next Service Sticker to Window

Next Service Due:

1950

After Service Photos









Quick Hitch Inspection

Brand:	Komatsu
Model:	Tilt hitch
Serial Number:	Komt-80-63
Inspection Interval:	500

Inspection Results:

Is the quick hitch free from oil leaks?	Yes
Does the quick hitch unlock correctly?	Yes
Does the quick hitch lock correctly?	Yes
Identification plate present?	Yes
Visual inspection for cracks?	Yes
Picks up attachment correctly?	Yes
Buzzer works?	Yes
Switch protected by cover/lock?	Yes
Hoses in good condition?	Yes
Free from excessive wear?	Yes

Service Completion

Service Date:	April 10, 2026 10:02 am	Report Generated:	April 10, 2026 10:02 am
Technician:	705	RO Number:	E34239