



MACHINE SERVICE REPORT

RO Number: 49217 | Service Date: February 9, 2026 11:51 am

Machine Details

Customer:	Australian Hammer Supplies	Hour Meter:	1104
	Hire	Service Type:	1000 hour
Model:	SK135SR-7	Service Interval:	1000 Hour Service
Serial Number:	YY09053635		

Parts Replaced/Service

Part Type	Status
Engine Oil Filters	Done
Hydraulic Return	Done
Primary Fuel	Done
Fuel /Water	Done
Outer Air	Done
Inner Air	Done
Breather	Done
A/C Filter x1	Done
A/C Filter x1	Done
Oil Sample Kits	Done
Grease	Done
Brake Cleaner	Done

Fluid Levels & Replacements

Engine Oil 17 LTS	Final Drive Oil 6 LTS	Hydraulic Oil 0 LTS	Coolant 1 LTS	Grease 1 LTS
-----------------------------	---------------------------------	-------------------------------	-------------------------	------------------------

System Measurements

Charge Rate 28 V	Pump 1 343 BAR	Pump 2 343 BAR
----------------------------	--------------------------	--------------------------

Service Checklist Completed

1000 Hour Service:

Replace Engine Oil Fluid
Replace Engine Oil Filter
Check Hydraulic Oil Level
Check Coolant Radiator Level
Check Engine Fan Belts Tension
Check A/C Belt Tension
Check Machine Horn Operation
Check Radiator Hoses, No Leaks
Check Neutral Start Working
Check Safety Lever Operation
Check No Fault Codes Active
Check E-Stop Operation
Drain Water from Fuel Tank
Check No Visual Oil Leaks
Check Flashing Light Operation
Check Work Light Operation
Visual Inspection Over Machine
Check Wiper Bottle Water Level
Check Quick Hitch Operation
Check Quick Hitch Pins / Bolts
Check Radiator Cap Condition
Grease Machine - All Pins / Slew
Replace Fuel Water Filters
Replace Primary Fuel Filter
Replace Engine Outer Air Filter
Clean Radiator Core Filters
Replace Final Drive Reduction Oils
Carry Out Oil Sampling - Warranty
Replace Hydraulic Return Filter
Replace Engine Inner Air Filter
Replace Cabin A/C Filters

Service Completion:

Reset Machine Dash Hours
Fit Next Service Sticker to Window

Comments:

Replace slew oil
Could not lift machine and properly check undercarriage due to limited room

Next Service Due:

1500 hours









Quick Hitch Inspection

Brand:	Doherty
Model:	DH140
Serial Number:	M52656-1
Inspection Interval:	1000

Inspection Results:

Is the quick hitch free from oil leaks?	Yes
Does the quick hitch unlock correctly?	Yes
Does the quick hitch lock correctly?	Yes
Identification plate present?	Yes
Visual inspection for cracks?	Yes
Picks up attachment correctly?	Yes
Buzzer works?	Yes
Switch protected by cover/lock?	Yes
Hoses in good condition?	Yes
Free from excessive wear?	No

Hitch Comments/Repairs Required:

Missing one stop see photo

Service Completion

Service Date:	February 9, 2026 11:51 am	Report Generated:	February 9, 2026 11:51 am
Technician:	Jason	RO Number:	49217