



MACHINE SERVICE REPORT

RO Number: E32817 | Service Date: October 7, 2025 9:35 am

Machine Details

Customer:	AHSH	Hour Meter:	627
Model:	Sk135sr-7	Service Type:	500
Serial Number:	YY09053635	Service Interval:	500 Hour Service

Before Service Photos



Parts Replaced/Service

Part Type	Status
Engine Oil Filters	Done
Hydraulic Return	Done
Primary Fuel	Done
Fuel /Water	Done
Fuel /Water	Done
Outer Air	Done
Grease	Done
Brake Cleaner	Done

Fluid Levels & Replacements

Engine Oil 20 LTS	Final Drive Oil 10 LTS	Hydraulic Oil 5 LTS	Grease 1 LTS
-----------------------------	----------------------------------	-------------------------------	------------------------

System Measurements

Charge Rate 28 V

Service Checklist Completed

500 Hour Service:

Replace Engine Oil Fluid
Replace Engine Oil Filter
Replace Hydraulic Filter
Replace Primary Fuel Filters
Check Hydraulic Oil Level
Check Slew Reduction Oil Level
Check Final Drive Oil Level
Check Coolant Radiator Level
Check Engine Fan Belts Tension
Check A/C Belt Tension
Check / Adjust Track Tension
Check Upper / Lower Rollers
Check Machine Horn Operation
Check Radiator Hoses, No Leaks
Check 2 Speed Travel Operation
Check Neutral Start Working
Check Safety Lever Operation
Check No Fault Codes Active
Check E-Stop Operation
Drain Water from Fuel Tank
Check No Visual Oil Leaks
Clean Outer Air Filter
Clean Cabin Air Filters
Check Flashing Light Operation
Check Work Light Operation
Visual Inspection Over Machine
Check Wiper Bottle Water Level
Check Quick Hitch Operation
Check Quick Hitch Pins / Bolts
Check Radiator Cap Condition
Grease Machine - All Pins / Slew
Replace Fuel Water Filters
Replace Primary Fuel Filter
Replace Engine Outer Air Filter
Clean Radiator Core Filters
Replace Final Drive Reduction Oils

Service Completion:

Reset Machine Dash Hours
Fit Next Service Sticker to Window

Next Service Due:

1127

After Service Photos





KOBELCO

Model : SK135SR-7

Serial Number : YY09053635

YM T02489P1



! DANGER
CRUSH



Quick Hitch Inspection

Brand:	Doherty
Model:	standard
Serial Number:	M52656
Inspection Interval:	500

Inspection Results:

Is the quick hitch free from oil leaks?	Yes
Does the quick hitch unlock correctly?	Yes
Does the quick hitch lock correctly?	Yes
Identification plate present?	Yes
Visual inspection for cracks?	Yes
Picks up attachment correctly?	Yes
Buzzer works?	Yes
Switch protected by cover/lock?	Yes
Hoses in good condition?	Yes
Free from excessive wear?	Yes

Service Completion

Service Date:	October 7, 2025 9:35 am	Report Generated:	October 7, 2025 9:35 am
Technician:	Mitchell	RO Number:	E32817