



MACHINE SERVICE REPORT

RO Number: 34855 | Service Date: August 10, 2026 10:28 am

Machine Details

Customer:	AHS	Hour Meter:	1579
Model:	Sk225sr-7	Service Type:	500
Serial Number:	0049	Service Interval:	500 Hour Service

Before Service Photos

Front Left Corner



Front Right Corner



Back Left Corner



Back Right Corner



Serial Plate



Hour Meter



Parts Replaced/Service

Part Type	Status
Engine Oil Filters	Done
Hydraulic Return	Done
Primary Fuel	Done
Fuel /Water	Done
Outer Air	Done
Grease	Done
Brake Cleaner	Done

Fluid Levels & Replacements

Engine Oil 24 LTS	Final Drive Oil 15 LTS	Hydraulic Oil 0 LTS	Coolant 0 LTS	Grease 2 LTS
----------------------	---------------------------	------------------------	------------------	-----------------

System Measurements

Charge Rate 26 V

Service Checklist Completed

500 Hour Service:

Replace Engine Oil Fluid
Replace Engine Oil Filter
Replace Hydraulic Filter
Replace Primary Fuel Filters
Check Hydraulic Oil Level
Check Slew Reduction Oil Level
Check Final Drive Oil Level
Check Coolant Radiator Level
Check Engine Fan Belts Tension
Check A/C Belt Tension
Check / Adjust Track Tension
Check Upper / Lower Rollers
Check Machine Horn Operation
Check Radiator Hoses, No Leaks
Check 2 Speed Travel Operation
Check Neutral Start Working
Check Safety Lever Operation
Check No Fault Codes Active
Check E-Stop Operation
Drain Water from Fuel Tank
Check No Visual Oil Leaks
Clean Outer Air Filter
Clean Cabin Air Filters
Check Flashing Light Operation
Check Work Light Operation
Visual Inspection Over Machine
Check Wiper Bottle Water Level
Check Quick Hitch Operation
Check Quick Hitch Pins / Bolts
Check Radiator Cap Condition
Grease Machine - All Pins / Slew
Replace Fuel Water Filters
Replace Primary Fuel Filter
Replace Engine Outer Air Filter
Clean Radiator Core Filters
Replace Final Drive Reduction Oils

Service Completion:

Reset Machine Dash Hours
Fit Next Service Sticker to Window

Next Service Due:

2000

After Service Photos

Front Left Corner



Front Right Corner



Back Left Corner



Back Right Corner



Hour Meter



Quick Hitch Inspection

Inspection Results:

Is the quick hitch free from oil leaks?	Yes
Does the quick hitch unlock correctly?	Yes
Does the quick hitch lock correctly?	Yes
Identification plate present?	Yes
Visual inspection for cracks?	Yes
Picks up attachment correctly?	Yes
Buzzer works?	Yes
Switch protected by cover/lock?	Yes
Hoses in good condition?	Yes
Free from excessive wear?	Yes

Service Completion

Service Date:	August 10, 2026 10:28 am	Report Generated:	August 10, 2026 10:28 am
Technician:	3057	RO Number:	34855

STM Trucks & Machinery Pty Ltd | 20-26 Dunn Rd, Smeaton Grange NSW 2567 | 02 4647 4488 | ABN 36 142 316 916 / MD 038046

This service report has been reviewed and approved by our service department.