



MACHINE SERVICE REPORT

RO Number: E33193 | Service Date: November 3, 2025 9:16 am

Machine Details

Customer:	Aussie hammer	Hour Meter:	158
Model:	135-7	Service Type:	First Service
Serial Number:	Yy09061223	Service Interval:	50 Hour Service

Before Service Photos





Parts Replaced/Service

Part Type	Status
Engine Oil Filters	Done
Hydraulic Return	Done
Primary Fuel	Done
Fuel /Water	Done
Grease	Done
Brake Cleaner	Done

Fluid Levels & Replacements

Engine Oil 20 LTS	Grease 1 LTS
----------------------	-----------------

System Measurements

Charge Rate
14 V

Service Checklist Completed

50 Hour Service:

Replace Engine Oil FluidReplace Engine Oil FilterReplace Hydraulic FilterReplace Primary Fuel FiltersCheck Hydraulic Oil LevelCheck Slew Reduction Oil LevelCheck Final Drive Oil LevelCheck Coolant Radiator LevelCheck Engine Fan Belts TensionCheck A/C Belt TensionCheck / Adjust Track TensionCheck Upper / Lower Rollers Check Machine Horn OperationCheck Radiator Hoses, No LeaksCheck 2 Speed Travel OperationCheck Neutral Start WorkingCheck Safety Lever OperationCheck No Fault Codes ActiveCheck E-Stop Operation Drain Water from Fuel Tank Check No Visual Oil Leaks Clean Outer Air FilterClean Cabin Air FiltersCheck Flashing Light OperationCheck Work Light OperationVisual Inspection Over MachineCheck Wiper Bottle Water LevelCheck Quick Hitch Operation Check Quick Hitch Pins / BoltsCheck Radiator Cap ConditionGrease Machine - All Pins / Slew

Service Completion:

Reset Machine Dash HoursFit Next Service Sticker to Window

Next Service Due: 500

After Service Photos



Quick Hitch Inspection

Brand:	A2
Model:	Sk135
Serial Number:	A20008987-5
Inspection Interval:	50

Inspection Results:

Is the quick hitch free from oil leaks?	Yes
Does the quick hitch unlock correctly?	Yes
Does the quick hitch lock correctly?	Yes
Identification plate present?	Yes
Visual inspection for cracks?	Yes
Picks up attachment correctly?	Yes
Buzzer works?	Yes
Switch protected by cover/lock?	Yes
Hoses in good condition?	Yes
Free from excessive wear?	Yes

Service Completion

Service Date:	November 3, 2025 9:16 am	Report Generated:	November 3, 2025 9:16 am
Technician:	728	RO Number:	E33193