



## MACHINE SERVICE REPORT

RO Number: E33372 | Service Date: November 26, 2025 12:21 pm

### Machine Details

<b>Customer:</b>	Australian hammer supplies	<b>Hour Meter:</b>	618
<b>Model:</b>	SK225SR-7	<b>Service Type:</b>	50
<b>Serial Number:</b>	YB0900053	<b>Service Interval:</b>	50 Hour Service

Before Service Photos





**KOBELCO**

Model : SK225SR-7

Serial Number : YB09020053

YN20T02489P1



**! DANGER**  
**CRUSH**  
**ZONE**  
Keep Clear

EX WD023



**! DANGER**  
**KEEP**





### Parts Replaced/Service

Part Type	Status
Engine Oil Filters	Done
Hydraulic Return	Done
Primary Fuel	Done

### Fluid Levels & Replacements

Engine Oil  
**22 LTS**

### System Measurements

Charge Rate  
**24 V**

## Service Checklist Completed

### 50 Hour Service:

Replace Engine Oil Fluid  
Replace Engine Oil Filter  
Replace Hydraulic Filter  
Replace Primary Fuel Filters  
Check Hydraulic Oil Level  
Check Slew Reduction Oil Level  
Check Final Drive Oil Level  
Check Coolant Radiator Level  
Check Engine Fan Belts Tension  
Check A/C Belt Tension  
Check / Adjust Track Tension  
Check Upper / Lower Rollers  
Check Machine Horn Operation  
Check Radiator Hoses, No Leaks  
Check 2 Speed Travel Operation  
Check Neutral Start Working  
Check Safety Lever Operation  
Check No Fault Codes Active  
Check E-Stop Operation  
Drain Water from Fuel Tank  
Check No Visual Oil Leaks  
Clean Outer Air Filter  
Clean Cabin Air Filters  
Check Flashing Light Operation  
Check Work Light Operation  
Visual Inspection Over Machine  
Check Wiper Bottle Water Level  
Check Quick Hitch Operation  
Check Quick Hitch Pins / Bolts  
Check Radiator Cap Condition  
Grease Machine - All Pins / Slew

### Service Completion:

Reset Machine Dash Hours  
Fit Next Service Sticker to Window

### Next Service Due:

---

After Service Photos









## Quick Hitch Inspection

<b>Brand:</b>	Doherty
<b>Model:</b>	Standard
<b>Inspection Interval:</b>	50

### Inspection Results:

Is the quick hitch free from oil leaks?	<b>Yes</b>
Does the quick hitch unlock correctly?	<b>Yes</b>
Does the quick hitch lock correctly?	<b>Yes</b>
Identification plate present?	<b>Yes</b>
Visual inspection for cracks?	<b>Yes</b>
Picks up attachment correctly?	<b>Yes</b>
Buzzer works?	<b>Yes</b>
Switch protected by cover/lock?	<b>Yes</b>
Hoses in good condition?	<b>Yes</b>
Free from excessive wear?	<b>Yes</b>

## Service Completion

<b>Service Date:</b>	November 26, 2025 12:21 pm	<b>Report Generated:</b>	November 26, 2025 12:21 pm
<b>Technician:</b>	Jerry	<b>RO Number:</b>	E33372