



MACHINE SERVICE REPORT

RO Number: E33117 | Service Date: October 31, 2025 9:25 am

Machine Details

Customer:	AHSH	Hour Meter:	143
Model:	SK225SR-7	Service Type:	first service
Serial Number:	YB09020055	Service Interval:	50 Hour Service

Before Service Photos



Parts Replaced/Service

Part Type	Status
Engine Oil Filters	Done
Hydraulic Return	Done
Primary Fuel	Done
Grease	Done
Brake Cleaner	Done

Fluid Levels & Replacements

Engine Oil 25 LTS	Grease 1 LTS
----------------------	-----------------

System Measurements

Charge Rate 28 V

Service Checklist Completed

50 Hour Service:

Replace Engine Oil Fluid
Replace Engine Oil Filter
Replace Hydraulic Filter
Replace Primary Fuel Filters
Check Hydraulic Oil Level
Check Slew Reduction Oil Level
Check Final Drive Oil Level
Check Coolant Radiator Level
Check Engine Fan Belts Tension
Check A/C Belt Tension
Check / Adjust Track Tension
Check Upper / Lower Rollers
Check Machine Horn Operation
Check Radiator Hoses, No Leaks
Check 2 Speed Travel Operation
Check Neutral Start Working
Check Safety Lever Operation
Check No Fault Codes Active
Check E-Stop Operation
Drain Water from Fuel Tank
Check No Visual Oil Leaks
Clean Outer Air Filter
Clean Cabin Air Filters
Check Flashing Light Operation
Check Work Light Operation
Visual Inspection Over Machine
Check Wiper Bottle Water Level
Check Quick Hitch Operation
Check Quick Hitch Pins / Bolts
Check Radiator Cap Condition
Grease Machine - All Pins / Slew

Service Completion:

Reset Machine Dash Hours
Fit Next Service Sticker to Window

Next Service Due:

500





KOBELCO

Model :

SK225SR-7

Serial Number :

YB09020055

W20T02489P1

! DANGER
CRUSHER





Quick Hitch Inspection

Brand:	Geith
Model:	Standard
Serial Number:	1017136
Inspection Interval:	50

Inspection Results:

Is the quick hitch free from oil leaks?	Yes
Does the quick hitch unlock correctly?	Yes
Does the quick hitch lock correctly?	Yes
Identification plate present?	Yes
Visual inspection for cracks?	Yes
Picks up attachment correctly?	Yes
Buzzer works?	Yes
Switch protected by cover/lock?	Yes
Hoses in good condition?	Yes
Free from excessive wear?	Yes

Service Completion

Service Date:	October 31, 2025 9:25 am	Report Generated:	October 31, 2025 9:25 am
Technician:	705	RO Number:	E33117