



## Service Inspection / Report

Australian Hammer Supplies Hire Pty Ltd  
34 Williamson Rd, Ingleburn NSW 2565  
Ph: 9826 6000 E: mitchell@australianhammer.com.au  
www.HammerHire.com.au  
ABN 70 143 092 228

|                                                                                        |          |
|----------------------------------------------------------------------------------------|----------|
| Report No:                                                                             | 1609     |
| Asset No:                                                                              | AttsH57  |
| Make:                                                                                  | Ausa     |
| Model:                                                                                 | D600APG  |
| Serial No:                                                                             | 64079974 |
| Date:                                                                                  | 19.4.23  |
| Mach. Hrs:                                                                             | 1266     |
| <input checked="" type="checkbox"/> On-Site <input checked="" type="checkbox"/> W/Shop |          |

Customer Name: AttsH Location: Yard.

### ROPS Frame

Fitted ☐ Y ☐ N Serial No: Technician ID: Hayden.

### Attachment Fitted 1

Make: Model: Serial No:

#### ☒ or ☒ Stationary Checks/Serviceing

##### Fluid / Oil Level Check / Adjust

- ☒ Battery electrolyte
- ☒ Hydraulic Oil
- ☒ 50% Coolant / Antifreeze
- ☒ Engine oil
- ☒ Differential case
- ☒ Front hubs & gear case LH & RH
- ☒ Windscreen washer reservoir
- ☒ All drain & fill plugs tight

##### Engine check / adjust

- ☒ Air element fit & seal
- ☒ Cab filters fit & seal
- ☒ Fan, alternator & A/C belts
- ☒ Hoses & clamps secure & sealing
- ☒ Pressure test cooling system
- ☒ Radiator screen
- ☒ Pre-cleaner

##### Electrical check / adjust

- ☒ Battery terminals & battery secure
- ☒ Wiring harness routing & security

##### Tracks check / adjust

- ☒ Track condition/wear
- ☒ Track tension

##### Hydraulics check / adjust

- ☒ Cylinder rods - Nil rust / scratches
- ☒ Hydraulic hoses, lines & fittings secure

##### General check / adjust

- ☒ General nut & bolt torque
- ☒ ROPS mounting secure
- ☒ Hydraulic quick hitch & pins
- ☒ Driver belts
- ☒ Torque blade bolts

#### Grease & Lubricate

- ☒ Battery terminals
- ☒ Cables
- ☒ Hitch & linkage components
- ☒ Pedal / lever shafts & pivots
- ☒ Pins & bushes
- ☒ Seat slides & door hinges

#### Operational inspection controls and safety locks

- ☒ Battery charger rate
- ☒ Engine speed low idle
- ☒ Engine speed high
- ☒ Engine shut off
- ☒ Safety interlock function
- ☒ Set clock & audio system
- ☒ Set service intervals
- ☒ Air Conditioner / heater
- ☒ Horn, hazard & warning devices
- ☒ Hour & tachometer
- ☒ Instruments & gauges
- ☒ Lights - interior
- ☒ Lights - head, signal, stop & work
- ☒ Lights - warning
- ☒ Switches & controls
- ☒ Windscreen wipers & washers
- ☒ Seat belt operation & mounting
- ☒ Flow test hyd system (Ref. WSM)
- ☒ Main relief pressure check: PSI =
- ☒ Safety Decals
- ☒ E-STOPS

- ☒ Hydraulic auxiliary operation
- ☒ Verify relief valve setting (Attach)
- ☒ Attachment controls
- ☒ Quick hitch
- ☒ No coolant leaks
- ☒ No exhaust leaks
- ☒ No fuel system leaks
- ☒ No oil leaks

#### Final inspection check / adjust

- ☒ Accessories, badges & logos
- ☒ Adjust all latches, locks & doors
- ☒ Panels fitment & paint work
- ☒ Safety decals & guards in place
- ☒ Steps & handles secure
- ☒ Check & rectify and fault code
- ☒ Risk Assessment
- ☒ Cab/Operator platform clean

#### Hydraulic Attachments

- ☒ Hydraulic hose condition
- ☒ Fitted with spiral wrap
- ☒ Inspect body & adaptor for cracks
- ☒ Inspect for hydraulic oil leak
- ☒ Inspect bush & chisel wear
- ☒ Check nitrogen gas pressure

#### Consumables:

|              |                                                                  |       |    |
|--------------|------------------------------------------------------------------|-------|----|
| Engine Oil:- | <input checked="" type="checkbox"/> Y <input type="checkbox"/> N | Lts:- | 15 |
| Hyd.Oil:-    | <input type="checkbox"/> Y <input checked="" type="checkbox"/> N | Lts:- |    |
| Coolant:-    | <input type="checkbox"/> Y <input checked="" type="checkbox"/> N | Lts:- |    |
| Gear Oil:-   | <input checked="" type="checkbox"/> Y <input type="checkbox"/> N | Lts:- | 3  |

#### Work Completed:

Carried out minor Service - Replaced engine oil & filter - Replaced primary fuel filter - Replaced secondary fuel filter - Replaced outer air filter - Replaced final drive oil - Carried out Safety check.

| Qty | Part No.     | Description           | Qty | Part No. | Description |
|-----|--------------|-----------------------|-----|----------|-------------|
| 1   | HAICO-32430  | Engine oil filter     |     |          |             |
| 1   | 12581-43012  | Primary fuel filter   |     |          |             |
| 1   | 11C011-43062 | Secondary fuel filter |     |          |             |
| 1   | 859700-26112 | Outer Air filter      |     |          |             |

|                    |                   |             |              |
|--------------------|-------------------|-------------|--------------|
| Customer Signature | Tech Signature    | Time Start: | Time Finish: |
|                    | HWH               |             |              |
| Print Name         | Next Service Due: | 1500        |              |