

PM 1 PERFORM (250 HOURS INTERVAL)

PM Checklist

● 2 ● 0 ● 6 ● 0

Inspection Number	22443706	Customer No	2969824372
Serial Number	NDJ20530	Customer Name	2969824372
Make	CATERPILLAR	Work Order	SU31924
Model	325F	Completed On	30/04/2025 6:22:50 PM
Equipment Family	Medium Hydraulic Excavator	Inspector	Francesco Stefanetto
Asset ID	AHSH63	PDF Generated On	30/04/2025
SMU	5321 Hours	Location	Alpine Way, Khancoban, New South Wales 2642, Australia
Coordinates	0, 0, 0		
Technician			

General Info & Comments

● General info/Comments ACTION

Comments: 250 hours service and inspection performed
DEF pump filter needs replacing
Right track assembly pads missing and som mounting bolts loose



Image Comment(s):Loose mounting bolts



Image Comment(s):2x missing track pads right side assembly

PM 1 PERFORM (250 HOURS INTERVAL)

● **1.1 TAKE & ANALYZE SOS SAMPLE FROM ENGINE OIL**

NORMAL

Job : 008
Modifier :
Quantity :
WorkApp :
JobLocation :
JobCond :
CabType :
Part Number : SOS
Part Quantity : 1.0

● **1.2 TAKE & ANALYZE SOS SAMPLE FROM FINAL DRIVE OIL**

NORMAL

Job : 008
Modifier : OC
Quantity :
WorkApp :
JobLocation :
JobCond :
CabType :
Part Number : SOS
Part Quantity : 2.0

● **1.3 LUBRICATE SWING GEAR/BEARING BEARING**

NORMAL

Job : 086
Modifier : BD
Quantity :
WorkApp :
JobLocation :
JobCond :
CabType :

● **1.4 CLEAN REFRIGERANT CONDENSER**

NORMAL

Job : 070
Modifier :
Quantity :
WorkApp :
JobLocation :
JobCond :
CabType :

● **1.5 CHECK FINAL DRIVE FLUID LEVEL**

NORMAL

Job : 535
Modifier : FLV
Quantity :

WorkApp :
JobLocation :
JobCond :
CabType :

1.6 CHECK SWING DRIVE FLUID LEVEL *NORMAL*

Job : 535
Modifier : FLV
Quantity :
WorkApp :
JobLocation :
JobCond :
CabType :

1.7 PERFORM PM 1 *ACTION*

Comments: DEF filter over hours for replacement.

Job : 540
Modifier :
Quantity :
WorkApp :
JobLocation :
JobCond :
CabType :




Image Comment(s):Def filter hours over