

5000 SERVICE HOUR MAINTENANCE PERFORM (5000 HOURS INTERVAL)

PM Checklist

● 1 ● 0 ● 3 ● 0

Inspection Number	18668486	Customer No	2969824372
Serial Number	SGJ20702	Customer Name	AUSTRALIAN HAMMER SUPPLIES HIRE PTY LTD
Make	CATERPILLAR	Completed On	20/08/2024 1:51:51 PM
Model	335	Inspector	Michael Parsey
Equipment Family	Medium Hydraulic Excavator	PDF Generated On	20/08/2024
Asset ID	AHSH69	SMU	4922.79 Hours
Location	32 Williamson Rd, Ingleburn, New South Wales 2565, Australia	Coordinates	0, 0, 0




Technician

[Signature]

General Info & Comments

● General info/Comments ACTION

Comments: Active diagnostic code 3575-5
Oil leak around hydraulic pumps



5000 SERVICE HOUR MAINTENANCE PERFORM (5000 HOURS INTERVAL)

● **1.1 REPLACE WITH NEW DIESEL EXHAUST FLUID FILTER**

NORMAL

Job : 511
Modifier :
Quantity :
WorkApp :
JobLocation :
JobCond :
CabType :
Part Number : 3783187
Part Quantity : 1.0

● **1.2 REPLACE WITH NEW DIESEL EXHAUST FLUID INJECTOR**

NORMAL

Job : 511
Modifier :
Quantity :
WorkApp :
JobLocation :
JobCond :
CabType :
Part Number : 4609257
Part Quantity : 1.0

● **1.3 PERFORM 5000 SERVICE HOUR MAINTENANCE**

NORMAL

Job : 540
Modifier :
Quantity :
WorkApp :
JobLocation :
JobCond :
CabType :
