

PM 1 PERFORM (250 HOURS INTERVAL)

PM Checklist

● 1 ● 0 ● 5 ● 2

Inspection Number	16213249	Serial Number	SGJ20702
Make	CATERPILLAR	Model	335F
Equipment Family	EXCAVATORS	SMU	4308 Hours
Location	Croom, NSW	Coordinates	90.4584293365479, - 34.5883292472312, 150.819684192679
Completed On	22/02/2024 3:47:38 PM	Inspector	Harry Pillow
PDF Generated On	22/02/2024		
Technician	HK		

General Info & Comments

● General info/Comments ACTION

Comments: PS47275, PS54424, PS54481, PS54689, PS54931 all need to be attentioned.

Hyd imp pump has various leaks requiring prongs to reseal hoses.

Hammer lines leaking with a recommended line replacement and creating a route for lines to have same mobility but less chance of getting caught/ damaged.



PM 1 PERFORM (250 HOURS INTERVAL)

● 1.1 TAKE & ANALYZE SOS SAMPLE FROM ENGINE OIL NORMAL

Job : 008
 Modifier :
 Quantity :
 WorkApp :
 JobLocation :
 JobCond :
 CabType :
 Part Number : SOS

● **1.2 LUBRICATE SWING GEAR/BEARING BEARING** *NORMAL*

Job : 086
Modifier :
Quantity :
WorkApp :
JobLocation :
JobCond :
CabType :

● **1.3 TAKE & ANALYZE SOS SAMPLE FROM FINAL DRIVE OIL** *N/A*

Job : 008
Modifier :
Quantity :
WorkApp :
JobLocation :
JobCond :
CabType :
Part Number : SOS
Part Quantity : 2.0

● **1.4 CLEAN REFRIGERANT CONDENSER** *N/A*

Job : 070
Modifier :
Quantity :
WorkApp :
JobLocation :
JobCond :
CabType :

● **1.5 CHECK FINAL DRIVE FLUID LEVEL** *NORMAL*

Job : 535
Modifier :
Quantity :
WorkApp :
JobLocation :
JobCond :
CabType :

● **1.6 CHECK SWING DRIVE FLUID LEVEL** *NORMAL*

Job : 535
Modifier :
Quantity :

WorkApp :
JobLocation :
JobCond :
CabType :



1.7 PERFORM PM 1

NORMAL

Job : 540
Modifier :
Quantity :
WorkApp :
JobLocation :
JobCond :
CabType :
