



Service Inspection / Report

Australian Hammer Supplies Hire Pty Ltd
 34 Williamson Rd, Ingleburn NSW 2565
 Ph: 9826 6000 E: mitchell@australianhammer.com.au
 www.HammerHire.com.au
 ABN 70 143 092 228

Report No:	2068
Asset No:	AHSH71
Make:	Ausa
Model:	D1000 APG
Serial No:	
Date:	22/08/2023
Mach. Hrs:	1569.6
<input checked="" type="checkbox"/> On-Site <input checked="" type="checkbox"/> W/Shop	

Customer Name: AHSH Location: Ingleburn

ROPS Frame
 Fitted Y N Serial No: _____ Technician ID:- Milesh

Attachment Fitted 1
 Make: _____ Model: _____ Serial No: _____

- or Stationary Checks/Serviceing
- Fluid / Oil Level Check / Adjust**
- Battery electrolyte
- Hydraulic Oil
- 50% Coolant / Antifreeze
- Engine oil
- Differential case
- Front hubs & gear case LH & RH
- Windscreen washer reservoir
- All drain & fill plugs tight
- Engine check / adjust**
- Air element fit & seal
- Cab filters fit & seal
- Fan, alternator & A/C belts
- Hoses & clamps secure & sealing
- Pressure test cooling system
- Radiator screen
- Pre-cleaner
- Electrical check / adjust**
- Battery terminals & battery secure
- Wiring harness routing & security
- Tracks check / adjust**
- Track condition/wear
- Track tension
- Hydraulics check / adjust**
- Cylinder rods - Nil rust / scratches
- Hydraulic hoses, lines & fittings secure
- General check / adjust**
- General nut & bolt torque
- ROPS mounting secure
- Hydraulic quick hitch & pins
- Driver belts
- Torque blade bolts

- Grease & Lubricate**
- Battery terminals
- Cables
- Hitch & linkage components
- Pedal / lever shafts & pivots
- Pins & bushes
- Seat slides & door hinges
- Operational inspection controls and safety locks**
- Battery charger rate
- Engine speed low idle
- Engine speed high
- Engine shut off
- Safety interlock function
- Set clock & audio system
- Set service intervals
- Air Conditioner / heater
- Horn, hazard & warning devices
- Hour & tachometer
- Instruments & gauges
- Lights - interior
- Lights - head, signal, stop & work
- Lights - warning
- Switches & controls
- Windscreen wipers & washers
- Seat belt operation & mounting
- Flow test hyd system (Ref. WSM)
- Main relief pressure check: PSI = _____
- Safety Decals
- E-STOPS

- Hydraulic auxiliary operation
- Verify relief valve setting (Attach)
- Attachment controls
- Quick hitch
- No coolant leaks
- No exhaust leaks
- No fuel system leaks
- No oil leaks

- Final inspection check / adjust**
- Accessories, badges & logos
- Adjust all latches, locks & doors
- Panels fitment & paint work
- Safety decals & guards in place
- Steps & handles secure
- Check & rectify and fault code
- Risk Assessment
- Cab/Operator platform clean

Hydraulic Attachments

- Hydraulic hose condition
- Fitted with spiral wrap
- Inspect body & adaptor for cracks
- Inspect for hydraulic oil leak
- Inspect bush & chisel wear
- Check nitrogen gas pressure

Consumables:

Engine Oil:-	<input checked="" type="checkbox"/> Y <input type="checkbox"/> N	Lts:-	<u>18L</u>
Hyd.Oil:-	<input checked="" type="checkbox"/> Y <input type="checkbox"/> N	Lts:-	<u>60L</u>
Coolant:-	<input type="checkbox"/> Y <input checked="" type="checkbox"/> N	Lts:-	
Gear Oil:-	<input checked="" type="checkbox"/> Y <input type="checkbox"/> N	Lts:-	<u>5L</u>

Work Completed: Replaced engine oil & hydraulic oil Replaced engine oil filter fuel filter Air inner & outer filter etc. Done the greasing of m/c.

Qty	Part No.	Description	Qty	Part No.	Description
01	C-1122	Engine Oil Filter	01	FC-5201	Fuel Filter
01	A-554L	Air Outer Filter	01	A-5540	Air Inner Filter
01	HF28853	Hydraulic Filter	01	EFG-15010	Filter

Customer Signature: _____ Tech Signature: [Signature]

Print Name: _____ Time Start: 14:00 Time Finish: 17:30

Next Service Due: 1850 Hrs.