



Service Inspection / Report

Australian Hammer Supplies Hire Pty Ltd
 34 Williamson Rd, Ingleburn NSW 2565
 Ph: 9826 6000 E: mitchell@australianhammer.com.au
 www.HammerHire.com.au
 ABN 70 143 092 228

Report No:	2004
Asset No:	AUSH72
Make:	KUBOTA
Model:	SUL65-2
Serial No:	HL1014366
Date:	27-11-23
Mach. Hrs:	1958.3
<input checked="" type="checkbox"/> On-Site <input checked="" type="checkbox"/> W/Shop	

Customer Name: HAMMER HIRE Location: WORKSHOP

ROPS Frame

Fitted Y N Serial No: _____ Technician ID:- Shaun.

Attachment Fitted 1

Make: _____ Model: _____ Serial No: _____

or Stationary Checks/Servicing

Fluid / Oil Level Check / Adjust

- Battery electrolyte
- Hydraulic Oil
- 50% Coolant / Antifreeze
- Engine oil
- Differential case
- Front hubs & gear case LH & RH
- Windscreen washer reservoir
- All drain & fill plugs tight

Engine check / adjust

- Air element fit & seal
- Cab filters fit & seal
- Fan, alternator & A/C belts
- Hoses & clamps secure & sealing
- Pressure test cooling system
- Radiator screen
- Pre-cleaner

Electrical check / adjust

- Battery terminals & battery secure
- Wiring harness routing & security

Tracks check / adjust

- Track condition/wear
- Track tension

Hydraulics check / adjust

- Cylinder rods - Nil rust / scratches
- Hydraulic hoses, lines & fittings secure

General check / adjust

- General nut & bolt torque
- ROPS mounting secure
- Hydraulic quick hitch & pins
- Driver belts
- Torque blade bolts

Grease & Lubricate

- Battery terminals
- Cables
- Hitch & linkage components
- Pedal / lever shafts & pivots
- Pins & bushes
- Seat slides & door hinges

Operational inspection controls and safety locks

- Battery charger rate
- Engine speed low idle
- Engine speed high
- Engine shut off
- Safety interlock function
- Set clock & audio system
- Set service intervals
- Air Conditioner / heater
- Horn, hazard & warning devices
- Hour & tachometer
- Instruments & gauges
- Lights - interior
- Lights - head, signal, stop & work
- Lights - warning
- Switches & controls
- Windscreen wipers & washers
- Seat belt operation & mounting
- Flow test hyd system (Ref. WSM)
- Main relief pressure check:
PSI = _____
- Safety Decals
- E-STOPS

- Hydraulic auxiliary operation
- Verify relief valve setting (Attach)
- Attachment controls
- Quick hitch
- No coolant leaks
- No exhaust leaks
- No fuel system leaks
- No oil leaks

Final inspection check / adjust

- Accessories, badges & logos
- Adjust all latches, locks & doors
- Panels fitment & paint work
- Safety decals & guards in place
- Steps & handles secure
- Check & rectify and fault code
- Risk Assessment
- Cab/Operator platform clean

Hydraulic Attachments

- Hydraulic hose condition
- Fitted with spiral wrap
- Inspect body & adaptor for cracks
- Inspect for hydraulic oil leak
- Inspect bush & chisel wear
- Check nitrogen gas pressure

Consumables:

Engine Oil:-	<input checked="" type="checkbox"/> Y <input type="checkbox"/> N	Lts:-	6.8L
Hyd.Oil:-	<input checked="" type="checkbox"/> Y <input type="checkbox"/> N	Lts:-	35L
Coolant:-	<input type="checkbox"/> Y <input type="checkbox"/> N	Lts:-	
Gear Oil:-	<input checked="" type="checkbox"/> Y <input type="checkbox"/> N	Lts:-	2L

Work Completed:

Qty	Part No.	Description	Qty	Part No.	Description
1	T1855-71600	OUTER AC FILTER	1	11947-43171	FUEL FILTER
2	6A671-75090	INNER AC FILTER	1	V0631-51880	FUEL/WATER SEPARATOR
1	5980-26110	OUTER AIR FILTER	1	HL110-32430	ENG OIL FILTER
1	3A111-10180	INNER AIR FILTER	1	HL1A0-34900	WST FILTER
1	R0411-62150	HYD SEPARATOR FILTER	1	V0521-65450	HYD SEPARATOR FUEL
			1	V0521-65150	FUEL RETURN

Customer Signature: N/A

Tech Signature: [Signature]

Print Name: SHAUN THOMPSON

Time Start: 7:00 Time Finish: _____

Next Service Due: 2250 HRS.