


3000 SERVICE HOUR MAINTENANCE PERFORM (3000 HOURS INTERVAL)

PM Checklist

● 0 ● 0 ● 4 ● 1

Inspection Number	13674508	Customer Name	AHSH
Make	CATERPILLAR	Customer Email	hirebookings2@hammerhire.com.au
Serial Number	YCP20067	Work Order	SC66224
Model	320	Completed On	3/08/2023 2:12:28 PM
Equipment Family	EXCAVATORS	Inspector	Collin Graham
Asset ID	AHSH78	PDF Generated On	3/08/2023
SMU	2972 Hours	Location	Cammeray, NSW
Coordinates	78.9811550536632, -33.8277346334715, 151.214057506371		
Technician			

General Info & Comments

● General info/Comments

NORMAL

Comments: Damage to panel rhs rear





3000 SERVICE HOUR MAINTENANCE PERFORM (3000 HOURS INTERVAL)

● 1.1 REPLACE WITH NEW FUMES DISPOSAL ELEMENT NORMAL

Job : 511
 Modifier :
 Quantity :
 WorkApp :
 JobLocation :
 JobCond :
 CabType :
 Part Number : 3391048
 Part Quantity : 1.0

● 1.2 REPLACE WITH NEW HYDRAULIC OIL FILTER RETURN NORMAL

Job : 511
 Modifier :
 Quantity :
 WorkApp :
 JobLocation :
 JobCond :
 CabType :
 Part Number : 5909787
 Part Quantity : 1.0

● 1.3 REPLACE WITH NEW SEAT BELT N/A

Job : 511
 Modifier :
 Quantity :
 WorkApp :
 JobLocation :
 JobCond :
 CabType :
 Part Number : 5287420
 Part Quantity : 1.0

● 1.4 PERFORM 3000 SERVICE HOUR MAINTENANCE

NORMAL

Job : 540

Modifier :

Quantity :

WorkApp :

JobLocation :

JobCond :

CabType :
