

PM 1 (250 HOUR INTERVAL)

PM Checklist

● 0 ● 0 ● 5 ● 0

Inspection Number	15683247	Customer Name	AHSH
Serial Number	RAZ10993	Customer Email	hirebookings2@hammerhire.com.au
Make	CATERPILLAR	Work Order	SC68465
Model	323	Completed On	11/01/2024 10:00:58 AM
Equipment Family	EXCAVATORS	Inspector	Collin Graham
Asset ID	AHSH79	PDF Generated On	10/01/2024
SMU	3236 Hours	Location	28-30 Williamson Rd, Ingleburn, NSW
Coordinates	29.400239944458, -33.9900980508054, 150.85863543962		
Technician			

General Info & Comments

● **General info/Comments** NORMAL

Comments: Requires hydraulic oil top up





PM 1 (250 HOUR INTERVAL)

- 1.1 TAKE & ANALYZE S-O-S SAMPLE FR ENGINE OIL *NORMAL*

- 1.2 TAKE & ANALYZE S-O-S SAMPLE FR ENGINE COOLANT LEVEL ONE *NORMAL*

- 1.3 TAKE & ANALYZE S-O-S SAMPLE FR FINAL DRIVE *NORMAL*

- 1.4 PERFORM PM 1 *NORMAL*
