

FITFLEET-EXCAVATOR-250HR-CVA

Inspection Number 18318166 Customer No 2969824372

Serial Number RAZ10993 Customer Name AUSTRALIAN HAMMER

SUPPLIES HIRE PTY

MONITOR

LTD

Make CATERPILLAR Customer Email hirebookings2@hammer

hire.com.au

Model 323 Work Order SC71441

Equipment Family Medium Hydraulic Excavator Completed On 25/07/2024 2:43:14 PM

Asset ID AHSH79 Inspector Collin Graham SMU 3683 Hours PDF Generated On 25/07/2024

Location Orchard Hills, Australia 2748 Coordinates 0, 0, 0

Technician

General Info & Comments

General info/Comments

Comments: Monitor hydraulic oil conditioning 25ltrs added to bring to correct level














Form Order Report Serial Number : RAZ10993 Asset ID : AHSH79 Page 1 of 10













| TASK SAFETY INSTRUCTIONS - Revision Number: 02 Date: 25th September 2023 | |
|--|------|
| 1.1 Wear Correct PPE at all times | PASS |
| 1.2 All isolation and safe work procedures must be followed | PASS |
| 1.3 Identify task hazards and controls utilising hierarchy or controls model | PASS |
| 1.4 Ensure a competent operator and spotter is utilised to move mobile equipment | PASS |
| 1.5 Ensure all mobile equipment is fundamentally stable | PASS |
| 1.6 Ensure three points of contact is maintained during access and egress | PASS |
| 1.7 Ensure acceptable housekeeping standards are maintained at all times | PASS |
| MACHINE GENERAL RUNNING CHECKS | |
| 2.1 Check all work lights, beacon & reverse alarm for operation | PASS |

Form Order Report Serial Number: RAZ10993 Asset ID: AHSH79 Page 3 of 10

| 2.2 Test all dash warning lights, gauges and audible alarms for correct operation | PASS |
|--|------|
| 2.3 Check idle timer for correct shut down operation | PASS |
| 2.4 Check operation of all three emergency stop buttons | PASS |
| 2.5 Check operation of horn | PASS |
| 2.6 Check operation of reverse camera | PASS |
| 2.7 Check alternator charge voltage - ACTUALV | PASS |
| 2.8 Check operation of auto grease system by manually activating timer | N/A |
| 2.9 Check fire system control panel for 'Normal' | N/A |
| 2.10 Test hydraulic lock out function operation | PASS |
| 2.11 Check window wiper and washer operation | PASS |
| PM SAFETY GENERAL INSPECTION | |
| 3.1 Visually ensure all guards, shields and covers are in place and in good condition to ensure personal are protected from rotating parts | PASS |
| 3.2 Check condition of machine identification signage | PASS |
| 3.3 Inspect ROPS/FOPS condition | PASS |
| PM BRAKING SYSTEM | |
| 4.1 Test travel brakes – Ensure the machine comes to a stop when travel controls are released | PASS |
| 4.2 Test travel brakes – Ensure the brakes hold on a suitable slope | PASS |
| PM FIRE SUPPRESSION SYSTEM | |
| | |

| | 5.1 Ensure fire suppression bottle and components are securely mounted and in good condition | N/A |
|----|--|------|
| | 5.2 Ensure fire suppression is correctly charged | N/A |
| • | 5.3 Inspect last charge date - ACTUAL | N/A |
| • | 5.4 Check all fire extinguishers are securely mounted and in good condition | PASS |
| • | 5.5 Check all fire extinguishers are correctly charged | PASS |
| • | 5.6 Inspect last charge date - ACTUAL | PASS |
| PI | M ENGINE | |
| | 6.1 Perform engine valve set | N/A |
| • | 6.2 Inspect air intake system hoses, pipes, clamps for signs of dirt ingress | PASS |
| • | 6.3 Inspect engine for oil or fuel leaks | PASS |
| | 6.4 Inspect engine components for missing clamps | PASS |
| • | 6.5 Inspect exhaust system for signs of leaks, loose bolts or missing clamps | PASS |
| | 6.6 Inspect turbo for security and signs of leaks | PASS |
| • | 6.7 Inspect condition of exhaust lagging | PASS |
| | 6.8 Inspect engine mounts for condition and loose hardware | PASS |
| • | 6.9 Inspect alternator mount condition and adjustment | PASS |
| | 6.10 Inspect wiring condition and security | PASS |
| | 6.11 Inspect engine belts | PASS |

| PM ENGINE COOLING SYSTEM | |
|---|------|
| 7.1 Check coolant level | PASS |
| 7.2 Check condition of radiator cap | PASS |
| 7.3 Check condition of radiator core | PASS |
| 7.4 Check cooling system for signs of leaks | PASS |
| 7.5 Check hose and clamp condition | PASS |
| 7.6 Inspect fan condition and operation | PASS |
| 7.7 Inspect radiator and fan guard condition | PASS |
| PM SWING TRANSMISSION | |
| 8.1 Inspect swing transmission for signs of leaks | PASS |
| 8.2 Inspect swing transmission oil level | PASS |
| PM HYDRAULIC SYSTEM | |
| 9.1 Check hydraulic oil level | FAIL |
| Comments: Topped up 25ltrs | |
| 9.2 Inspect hydraulic cylinders for leaks and security | PASS |
| 9.3 Inspect hydraulic hoses for leaks, damage, security | PASS |
| 9.4 Inspect hydraulic pump condition, leaks, security | PASS |
| 9.5 Check Pilot Accumulator operation as per OEM Maintenance Procedure - Test Boom Down Functionality with engine off | PASS |
| | |

| PM FINAL DRIVES | |
|---|------|
| 10.1 Inspect LHS final drive mount condition for leaks and security | PASS |
| 10.2 Inspect LHS oil level and mag plug condition | PASS |
| 10.3 Inspect RHS final drive mount condition for leaks and security | PASS |
| 10.4 Inspect RHS oil level and mag plug condition | PASS |
| PM UNDERCARRIAGE | |
| 11.1 Inspect LHS track tension | PASS |
| 11.2 Inspect RHS track tension | PASS |
| 11.3 Inspect tracks for loose/missing bolts | PASS |
| 11.4 Inspect load and carrier rollers for signs of leaks | PASS |
| 11.5 Inspect idlers for signs of leaks | PASS |
| 11.6 Inspect sprocket segments condition | PASS |
| 11.7 Inspect track frame for cracks, lose or missing hardware | PASS |
| PM FRAME AND BODY | |
| 12.1 Check panels for damage and security | PASS |
| 12.2 Check access steps and walkway condition | PASS |
| 12.3 Inspect boom condition – cracks, missing clamps, damaged pipes, excessive movement, lubrication | PASS |
| 12.4 Inspect stick condition – cracks, missing clamps, damaged pipes, excessive movement, lubrication | PASS |
| | |

Form Order Report Serial Number: RAZ10993 Asset ID: AHSH79 Page 7 of 10

| 12.5 Inspect quick hitch condition and operation | PASS |
|--|------|
| 12.6 Inspect bucket condition – cracks, wear, damage, mounts | PASS |
| 12.7 Inspect GET condition and hardware | PASS |
| PM ELECTRICAL SYSTEM | |
| 13.1 Check battery condition | PASS |
| 13.2 Check battery terminal condition | PASS |
| 13.3 Check battery security | PASS |
| 13.4 Check battery box drain is clear | PASS |
| 13.5 Check wiring condition and security | PASS |
| PM GREASE SYSTEM | |
| 14.1 Check all points for acceptable lubrication | PASS |
| 14.2 Inspect grease system operation | N/A |
| 14.3 Check grease line condition | PASS |
| 14.4 Refill grease tank | N/A |
| 14.5 Lubricate bucket linkage | PASS |
| 14.6 Lubricate blade linkage | PASS |
| 14.7 Lubricate boom & stick linkage | PASS |
| 14.8 Lubricate swing bearing | PASS |
| | |

| PM OPERATOR STATION | |
|---|------|
| 15.1 Check all doors for correct opening and closing adjustments and operation | PASS |
| 15.2 Inspect condition of door seals | PASS |
| 15.3 Check window glass and seal condition | PASS |
| 15.4 Check mirror condition and adjustments | PASS |
| 15.5 Fill window washer reservoir | PASS |
| 15.6 Inspect air con vents condition | PASS |
| 15.7 Inspect seat belt and mounting hardware | PASS |
| 15.8 Inspect seat condition, operation and mounting | PASS |
| 15.9 Replace cabin A/C filter | PASS |
| OIL SAMPLING | |
| 16.1 Engine | PASS |
| PM POST SERVICE INSPECTION CHECKS | |
| 17.1 All inspections have been completed and rectified as required | PASS |
| 17.2 All safety related defects have been repaired or reported | PASS |
| 17.3 All defects have been noted and reported | PASS |
| 17.4 All fluids are at correct level and drain plugs tight | PASS |
| 17.5 All oil samples have visually been inspected and any notable signs of contamination have been reported | PASS |
| | |

Form Order Report Serial Number : RAZ10993 Asset ID : AHSH79 Page 9 of 10

| 17.6 All replaced filters have been cut and inspected and photos added to CAT Inspect and reported to supervisor | PASS |
|--|-----------|
| 17.7 Machine has been recommissioned and ready for operation | PASS |
| 17.8 PM service notification marked off in Vision Link | COMPLETED |
| DEFECTS IDENTIFIED | |
| 18.1 DEFECTS IDENTIFIED | PASS |

Form Order Report Serial Number: RAZ10993 Asset ID: AHSH79 Page 10 of 10