

# Australian Hammer Supplies Hire Unit 3/32 Williamson Road

Unit 3/32 Williamson Road Ingleburn NSW 2565

## **CATERPILLAR 330GC**

**Minor Service** 

2

11

85

**7** 

Inspection Number

Serial Number

RP055921

FEK20201

Customer No

200000

**Customer Name** 

AUSTRALIAN HAMMER

SUPPLIES HIRE

Make

**CATERPILLAR** 

Customer Email

RP055921

Model

Equipment Family

CAT330 GC

Works Order Completed On

5/12/2025 3:47:12 PM

Asset ID

AHSH103

Inspector

Collin Graham

Location

AUSTRAILAN HAMMER SUPPLIES HIRE

30.1-34.9T HYDRAULIC EXCAVATOR

Unit 3/32 WILLIAMSON RD

PDF Generated On 05/12/2025

05/40/0005

INGLEBURN

2565

Machine Hours

4711

**Next Meter** 

4781

Customer

## **General Info & Comments**

**General Info/Comments** 

250hr service



#### TASK SAFETY INSTRUCTIONS

1.1 Wear Correct PPE at all times

PASS

1.2 All isolation and safe work procedures must be followed

PASS

Severity Report Serial Number: FEK20201 Asset ID: AHSH103 Page 1 of 8



	1.3 Identify task hazards and controls utilising hierarchy or controls model	PASS
	1.4 Ensure a competent operator and spotter is utilised to move mobile equipment	PASS
	1.5 Ensure all mobile equipment is fundamentally stable	PASS
	1.6 Ensure three points of contact is maintained during access and egress	PASS
	1.7 Ensure acceptable housekeeping standards are maintained at all times	PASS
M	ACHINE GENERAL RUNNINGCHECKS	
	2.1 Check all work lights, beacon & reverse alarmfor operation	PASS
	2.2 Test all dash warning lights, gauges and audible alarms for correct operation	PASS
	2.3 Check idle timer for correct shut down operation	PASS
	2.4 Check operation of all three emergency stop buttons	PASS
	2.5 Check operation of horn	PASS
	2.6 Check operation of reverse camera	PASS
	2.7 Check alternator charge voltage	PASS
	2.8 Check operation of auto grease systemby manually activating timer	N/A
	2.9 Check fire systemcontrol panel for 'Normal'	N/A
P	M FIRE SUPPRESSION SYSTEM	
	5.1 Ensure fire suppression bottle and components are securely mounted and in good condition	N/A
	5.2 Ensure fire suppression is correctly charged	N/A
	5.3 Inspect last charge date	DATE:2025-12- 05T00:00:00. 0000000
	5.4 Check all fire extinguishers are securely mounted and in good condition	PASS
	5.5 Check all fire extinguishers are correctly charged	PASS

Severity Report Serial Number: FEK20201 Asset ID: AHSH103 Page 2 of 8



**PASS** 

**PASS** 

**PASS** 

	5.6 Inspect last charge date	DATE:2025-12 05T00:00:00. 0000000
PI	M ENGINE	
	6.1 Performengine valve set	N/A
	6.2 Inspect air intake systemhoses, pipes, clamps for signs of dirt ingress	PASS
	6.3 Inspect engine for oil or fuel leaks	PASS
	6.4 Inspect engine components for missing clamps	PASS
	6.5 Inspect exhaust systemfor signs of leaks, loose bolts or missing clamps	PASS
	6.6 Inspect turbo for security and signs of leaks	PASS
	6.7 Inspect condition of exhaust lagging	PASS
	6.8 Inspect engine mounts for condition and loose hardware	PASS
	6.9 Inspect alternator mount condition and adjustment	PASS
	6.10 Inspect wiring condition and security	PASS
	6.11 Inspect engine belts	PASS
PI	M ENGINE COOLINGSYSTEM	
	7.1 Check coolant level	PASS
	7.2 Check condition of radiator cap	PASS
	7.3 Check condition of radiator core	PASS
	7.4 Check cooling systemfor signs of leaks	PASS
		D.1.0.0

# **PM SWINGTRANSMISSION**

7.5 Check hose and clamp condition

7.6 Inspect fan condition and operation

7.7 Inspect radiator and fan guard condition

Severity Report Serial Number: FEK20201 Asset ID: AHSH103 Page 3 of 8



8.1	nspect swing transmission for signs of leaks	PASS
8.2	nspect swing transmission oil level	PASS
РМ НҮІ	DRAULIC SYSTEM	
9.1	Check hydraulic oil level	PASS
9.2	nspect hydraulic cylinders for leaks and security	PASS
9.3	nspect hydraulic hoses for leaks, damage, security	PASS
9.4	nspect hydraulic pump condition, leaks, security	PASS
	Check Pilot Accumulator operation as per OEM Maintenance Procedure - Test m Down Functionality with engine off	PASS
PM FIN	AL DRIVES	
10.1	Inspect LHS final drive mount condition for leaks and security	PASS
10.2	Inspect LHS oil level and mag plug condition	PASS
10.3	Inspect RHS final drive mount condition for leaks and security	PASS
10.4	Inspect RHS oil level and mag plug condition	PASS
PM UNI	DERCARRIAGE	
11.1	Inspect LHS track tension	PASS
11.2	Inspect RHS track tension	PASS
11.3	Inspect tracks for loose/missing bolts	PASS
11.4	Inspect load and carrier rollers for signs of leaks	PASS
11.5	Inspect idlers for signs of leaks	PASS
11.6	Inspect sprocket segments condition	PASS

Severity Report Serial Number: FEK20201 Asset ID: AHSH103 Page 4 of 8

**PM FRAME AND BODY** 



12.1 Check panels for damage and security	FAIL
12.2 Check access steps and walkway condition	PASS
<ul> <li>12.3 Inspect boom condition – cracks, missing clamps, damaged pipes, excessive movement, lubrication</li> </ul>	PASS
<ul> <li>12.4 Inspect stick condition – cracks, missing clamps, damaged pipes, excessive movement, lubrication</li> </ul>	PASS
12.5 Inspect quick hitch condition and operation	PASS
12.6 Inspect bucket condition – cracks, wear, damage, mounts	PASS
12.7 Inspect GET condition and hardware	PASS
PM ELECTRICAL SYSTEM	
13.1 Check battery condition	PASS
13.2 Check battery terminal condition	PASS
13.3 Check battery security	PASS
13.4 Check battery box drain is clear	PASS
13.5 Check wiring condition and security	PASS
PM GREASE SYSTEM	
14.1 Check all points for acceptable lubrication	PASS
14.2 Inspect grease systemoperation	PASS
14.3 Check grease line condition	PASS
14.4 Refill grease tank	N/A
14.5 Lubricate bucket linkage	PASS
14.6 Lubricate blade linkage	PASS
14.7 Lubricate boom& stick linkage	PASS
14.8 Lubricate swing bearing	PASS

Severity Report Serial Number: FEK20201 Asset ID: AHSH103 Page 5 of 8



**DEFECTS IDENTIFIED** 

Severity Report

Australian Hammer Supplies Hire Unit 3/32 Williamson Road Ingleburn NSW 2565

PM OPERATOR STATION	
15.1 Check all doors for correct opening and closing adjustments and operation	FAIL
15.2 Inspect condition of door seals	PASS
15.3 Check window glass and seal condition	PASS
15.4 Check mirror condition and adjustments	PASS
15.5 Fill window washer reservoir	PASS
15.6 Inspect air con vents condition	PASS
15.7 Inspect seat belt and mounting hardware	PASS
15.8 Inspect seat condition, operation and mounting	PASS
15.9 Replace cabin A/C filter	N/A
OIL SAMPLING	
● 16.1 Engine	PASS
PM POST SERVICE INSPECTION CHECKS	PASS
	PASS  PASS
PM POST SERVICE INSPECTION CHECKS	
PM POST SERVICE INSPECTION CHECKS  17.1 All inspections have been completed and rectified as required	PASS
PM POST SERVICE INSPECTION CHECKS  17.1 All inspections have been completed and rectified as required  17.2 All safety related defects have been repaired or reported	PASS PASS
PM POST SERVICE INSPECTION CHECKS  17.1 All inspections have been completed and rectified as required  17.2 All safety related defects have been repaired or reported  17.3 All defects have been noted and reported	PASS PASS
PM POST SERVICE INSPECTION CHECKS  17.1 All inspections have been completed and rectified as required  17.2 All safety related defects have been repaired or reported  17.3 All defects have been noted and reported  17.4 All fluids are at correct level and drain plugs tight  17.5 All oil samples have visually been inspected and any notable signs of	PASS PASS PASS
PM POST SERVICE INSPECTION CHECKS  17.1 All inspections have been completed and rectified as required  17.2 All safety related defects have been repaired or reported  17.3 All defects have been noted and reported  17.4 All fluids are at correct level and drain plugs tight  17.5 All oil samples have visually been inspected and any notable signs of contamination have been reported  17.6 All replaced filters have been cut and inspected and photos added to CAT	PASS PASS PASS PASS

Serial Number: FEK20201

Asset ID: AHSH103

Page 6 of 8



18.1 DEFECTS IDENTIFIED

pump bay door damage evident from previous hires, operator seat lower suspension bushes worn, oil fill tube for engine has minor weep( monitor only)

Ol	L USED	
	19.1 Hydraulic oil	0
	19.2 Engine oil	1
	19.3 Slew oil	0
	19.4 Gear oil	0
	19.5 Coolant	0
	Site photo	

Severity Report Serial Number: FEK20201 Asset ID: AHSH103 Page 7 of 8



	Site photo
<u> </u>	Site photo
0	Site photo
<u> </u>	Site photo
<u> </u>	Site photo
<u> </u>	Site photo
	Site photo

Severity Report Serial Number: FEK20201 Asset ID: AHSH103 Page 8 of 8