



Service Inspection / Report

Australian Hammer Supplies Hire Pty Ltd
 34 Williamson Rd, Ingleburn NSW 2565
 Ph: 9826 6000 E: mitchell@australianhammer.com.au
 www.HammerHire.com.au
 ABN 70 143 092 228

Report No:	1627
Asset No:	AHSH115
Make:	Kubota
Model:	SVL 65-2
Serial No:	17082
Date:	20-7-23
Mach. Hrs:	991
<input checked="" type="checkbox"/> On-Site <input checked="" type="checkbox"/> W/Shop	

Customer Name: AHSH Location: Rozelle

ROPS Frame
 Fitted Y N Serial No: _____ Technician ID: Hayden

Attachment Fitted 1
 Make: _____ Model: _____ Serial No: _____

or Stationary Checks/Serviceing

Fluid / Oil Level Check / Adjust

- Battery electrolyte
- Hydraulic Oil
- 50% Coolant / Antifreeze
- Engine oil
- Differential case
- Front hubs & gear case LH & RH
- Windscreen washer reservoir
- All drain & fill plugs tight

Engine check / adjust

- Air element fit & seal
- Cab filters fit & seal
- Fan, alternator & A/C belts
- Hoses & clamps secure & sealing
- Pressure test cooling system
- Radiator screen
- Pre-cleaner

Electrical check / adjust

- Battery terminals & battery secure
- Wiring harness routing & security

Tracks check / adjust

- Track condition/wear
- Track tension

Hydraulics check / adjust

- Cylinder rods - Nil rust / scratches
- Hydraulic hoses, lines & fittings secure

General check / adjust

- General nut & bolt torque
- ROPS mounting secure
- Hydraulic quick hitch & pins
- Driver belts
- Torque blade bolts

Grease & Lubricate

- Battery terminals
- Cables
- Hitch & linkage components
- Pedal / lever shafts & pivots
- Pins & bushes
- Seat slides & door hinges

Operational inspection controls and safety locks

- Battery charger rate
- Engine speed low idle
- Engine speed high
- Engine shut off
- Safety interlock function
- Set clock & audio system
- Set service intervals
- Air Conditioner / heater
- Horn, hazard & warning devices
- Hour & tachometer
- Instruments & gauges
- Lights - interior
- Lights - head, signal, stop & work
- Lights - warning
- Switches & controls
- Windscreen wipers & washers
- Seat belt operation & mounting
- Flow test hyd system (Ref. WSM)
- Main relief pressure check:
PSI = _____
- Safety Decals
- E-STOPS

- Hydraulic auxiliary operation
- Verify relief valve setting (Attach)
- Attachment controls
- Quick hitch
- No coolant leaks
- No exhaust leaks
- No fuel system leaks
- No oil leaks

Final inspection check / adjust

- Accessories, badges & logos
- Adjust all latches, locks & doors
- Panels fitment & paint work
- Safety decals & guards in place
- Steps & handles secure
- Check & rectify and fault code
- Risk Assessment
- Cab/Operator platform clean

Hydraulic Attachments

- Hydraulic hose condition
- Fitted with spiral wrap
- Inspect body & adaptor for cracks
- Inspect for hydraulic oil leak
- Inspect bush & chisel wear
- Check nitrogen gas pressure

Consumables:

Engine Oil:-	<input checked="" type="checkbox"/> Y <input type="checkbox"/> N	Lts:-	12
Hyd.Oil:-	<input type="checkbox"/> Y <input checked="" type="checkbox"/> N	Lts:-	
Coolant:-	<input type="checkbox"/> Y <input checked="" type="checkbox"/> N	Lts:-	
Gear Oil:-	<input checked="" type="checkbox"/> Y <input type="checkbox"/> N	Lts:-	2

Work Completed:

- Carried out major service to machine - Replaced engine oil & filter
 - Replaced fuel filter - Replaced inner & outer air filter - Replaced
 Hyd Pilot & breather filter - Replaced inner & outer Cab filters
 - Hyd oil sample taken - Replaced final drive oil - Carried
 out battery check. Requires monitor & UTE.

Qty	Part No.	Description	Qty	Part No.	Description
1	HH100-32430	Engine oil filter	1	HHTA0-59900	Hyd Pilot filter
1	1K947-43172	Fuel filter	1	RD411-62150	Hyd Breather filter
1	Y0631-51880	Fuel/water sep filter	1	T1855-71600	Outer Cab filter
1	3AN11-19130	Inner air filter	2	GA671-75090	Inner Cab filter
1	859800-26110	Outer " "	1		Hyd oil sample kit

Customer Signature: _____

Print Name: _____

Tech Signature: HW

Time Start: _____ Time Finish: _____

Next Service Due: 1250 hrs.