



Service Inspection / Report

Australian Hammer Supplies Hire Pty Ltd
 34 Williamson Rd, Ingleburn NSW 2565
 Ph: 9826 6000 E: mitchelli@australianhammer.com.au
 www.HammerHire.com.au
 ABN 70 143 092 228

Report No:	1398
Work Order No:	AHSH118
Make:	Kubota
Model:	Kx057-4
Serial No:	22400
Date:	30.6.22
Mach. Hrs:	498 hrs.
<input checked="" type="checkbox"/> On-Site <input checked="" type="checkbox"/> W/Shop	

Customer Name: AHSH Location: Yard.

ROPS Frame Fitted Y N Serial No: _____ Technician ID: Hayden

Attachment Fitted 1 Make: _____ Model: _____ Serial No: _____

- or Stationary Checks/Serviceing
- Fluid / Oil Level Check / Adjust**
 - Battery electrolyte
 - Hydraulic Oil
 - 50% Coolant / Antifreeze
 - Engine oil
 - Differential case
 - Front hubs & gear case LH & RH
 - Windscreen washer reservoir
 - All drain & fill plugs tight
- Engine check / adjust**
 - Air element fit & seal
 - Cab filters fit & seal
 - Fan, alternator & A/C belts
 - Hoses & clamps secure & sealing
 - Pressure test cooling system
 - Radiator screen
 - Pre-cleaner
- Electrical check / adjust**
 - Battery terminals & battery secure
 - Wiring harness routing & security
- Tracks check / adjust**
 - Track condition/wear
 - Track tension
- Hydraulics check / adjust**
 - Cylinder rods - Nil rust / scratches
 - Hydraulic hoses, lines & fittings secure
- General check / adjust**
 - General nut & bolt torque
 - ROPS mounting secure
 - Hydraulic quick hitch & pins
 - Driver belts
 - Torque blade bolts
- Grease & Lubricate**
 - Battery terminals
 - Cables
 - Hitch & linkage components
 - Pedal / lever shafts & pivots
 - Pins & bushes
 - Seat slides & door hinges
- Operational inspection controls and safety locks**
 - Battery charger rate
 - Engine speed low idle
 - Engine speed high
 - Engine shut off
 - Safety interlock function
 - Set clock & audio system
 - Set service intervals
 - Air Conditioner / heater
 - Horn, hazard & warning devices
 - Hour & tachometer
 - Instruments & gauges
 - Lights - interior
 - Lights - head, signal, stop & work
 - Lights - warning
 - Switches & controls
 - Windscreen wipers & washers
 - Seat belt operation & mounting
 - Flow test hyd system (Ref. WSM)
 - Main relief pressure check: PSI = _____
 - Safety Decals
 - E-STOPS
- Hydraulic auxiliary operation**
 - Verify relief valve setting (Attach)
 - Attachment controls
 - Quick hitch
 - No coolant leaks
 - No exhaust leaks
 - No fuel system leaks
 - No oil leaks
- Final inspection check / adjust**
 - Accessories, badges & logos
 - Adjust all latches, locks & doors
 - Panels fitment & paint work
 - Safety decals & guards in place
 - Steps & handles secure
 - Check & rectify and fault code
 - Risk Assessment
 - Cab/Operator platform clean
- Hydraulic Attachments**
 - Hydraulic hose condition
 - Fitted with spiral wrap
 - Inspect body & adaptor for cracks
 - Inspect for hydraulic oil leak
 - Inspect bush & chisel wear
 - Check nitrogen gas pressure
- Consumables:**

Engine Oil:-	<input checked="" type="checkbox"/> Y <input type="checkbox"/> N	Lts:-	12
Hyd.Oil:-	<input checked="" type="checkbox"/> Y <input type="checkbox"/> N	Lts:-	2
Coolant:-	<input type="checkbox"/> Y <input checked="" type="checkbox"/> N	Lts:-	-

Gear oil: 2L

Work Completed:
 - Carried out 500hrs Major Service - Replaced engine oil & filter
 - Replaced fuel filter - Replaced inner & outer Air filter - Replaced
 Hyd Pilot & Return filters - Replaced final drive oil - hyd oil
 Sample taken. - Carried out Safety check.

Qty	Part No.	Description	Qty	Part No.	Description
1	AH110-32430	Engine oil filter	1	R1411-64930	Hyd pilot filter
1	15221-43170	Fuel filter	1		Oil sample kit.
1	R2401-42289	Inner Air filter			
1	R1401-42279	Outer Air filter			
1	R0457-62120	Hyd return filter			

Customer Signature	Tech Signature	<u>HW</u>
Print Name	Time Start:	Time Finish:
	Next Service Due:	750 hrs. Minor