



# Service Inspection / Report

Australian Hammer Supplies Hire Pty Ltd  
 34 Williamson Rd, Ingleburn NSW 2565  
 Ph: 9826 6000 E: mitchell@australianhammer.com.au  
 www.HammerHire.com.au  
 ABN 70 143 092 228

Report No:	1858
Asset No:	AHSH118
Make:	Kubota
Model:	Kubota KX057-4
Serial No:	22400
Date:	8.11.23
Mach. Hrs:	1387
<input checked="" type="checkbox"/> On-Site <input checked="" type="checkbox"/> W/Shop	

Customer Name: \_\_\_\_\_ Location: AHSH

**ROPS Frame**

Fitted  Y  N Serial No: \_\_\_\_\_ Technician ID:- Colin Matt

**Attachment Fitted 1**

Make: \_\_\_\_\_ Model: \_\_\_\_\_ Serial No: \_\_\_\_\_

or  Stationary Checks/Serviceing

**Fluid / Oil Level Check / Adjust**

- Battery electrolyte
- Hydraulic Oil
- 50% Coolant / Antifreeze
- Engine oil
- Differential case
- Front hubs & gear case LH & RH
- Windscreen washer reservoir
- All drain & fill plugs tight

**Engine check / adjust**

- Air element fit & seal
- Cab filters fit & seal
- Fan, alternator & A/C belts
- Hoses & clamps secure & sealing
- Pressure test cooling system
- Radiator screen
- Pre-cleaner

**Electrical check / adjust**

- Battery terminals & battery secure
- Wiring harness routing & security

**Tracks check / adjust**

- Track condition/wear
- Track tension

**Hydraulics check / adjust**

- Cylinder rods - Nil rust / scratches
- Hydraulic hoses, lines & fittings secure

**General check / adjust**

- General nut & bolt torque
- ROPS mounting secure
- Hydraulic quick hitch & pins
- Driver belts
- Torque blade bolts

**Grease & Lubricate**

- Battery terminals
- Cables
- Hitch & linkage components
- Pedal / lever shafts & pivots
- Pins & bushes
- Seat slides & door hinges

**Operational inspection controls and safety locks**

- Battery charger rate
- Engine speed low idle
- Engine speed high
- Engine shut off
- Safety interlock function
- Set clock & audio system
- Set service intervals
- Air Conditioner / heater
- Horn, hazard & warning devices
- Hour & tachometer
- Instruments & gauges
- Lights - interior
- Lights - head, signal, stop & work
- Lights - warning
- Switches & controls
- Windscreen wipers & washers
- Seat belt operation & mounting
- Flow test hyd system (Ref. WSM)
- Main relief pressure check: PSI =
- Safety Decals
- E-STOPS

- Hydraulic auxiliary operation
- Verify relief valve setting (Attach)
- Attachment controls
- Quick hitch
- No coolant leaks
- No exhaust leaks
- No fuel system leaks
- No oil leaks

**Final inspection check / adjust**

- Accessories, badges & logos
- Adjust all latches, locks & doors
- Panels fitment & paint work
- Safety decals & guards in place
- Steps & handles secure
- Check & rectify and fault code
- Risk Assessment
- Cab/Operator platform clean

**Hydraulic Attachments**

- Hydraulic hose condition
- Fitted with spiral wrap
- Inspect body & adaptor for cracks
- Inspect for hydraulic oil leak
- Inspect bush & chisel wear
- Check nitrogen gas pressure

**Consumables:**

Engine Oil:-	<input checked="" type="checkbox"/> Y <input type="checkbox"/> N	Lts:-	12L
Hyd.Oil:-	<input checked="" type="checkbox"/> Y <input type="checkbox"/> N	Lts:-	70L
Coolant:-	<input type="checkbox"/> Y <input checked="" type="checkbox"/> N	Lts:-	
Gear Oil:-	<input checked="" type="checkbox"/> Y <input type="checkbox"/> N	Lts:-	2.5L

Work Completed: Soohr service & final drive checked over

Qty	Part No.	Description	Qty	Part No.	Description
1	1S221-43170	Fuel filter	1	R1411-64930	Element
1	R1401-42279	Air filter outer	2	6A671-75090	Filter
1	R2401-42289	Air filter inner	1	MWC-MK	Oil Sample kit
1	HH1CO-32430	Cartridge oil filter			
1	RD451-62120	Return filter			

Customer Signature \_\_\_\_\_

Tech Signature [Signature]

Print Name \_\_\_\_\_

Time Start: \_\_\_\_\_ Time Finish: \_\_\_\_\_

Next Service Due: 1750hrs