

MACHINE SERVICE REPORT

RO Number: E32307 | Service Date: July 2, 2025 11:40 am

Machine Details

Customer:	Australian hammer	Hour Meter:	2712
Model:	Sk135-7	Service Type:	1000hr
Serial Number:	YY09046733	Service Interval:	1000 Hour Service

Before Service Photos



Parts Replaced/Service

Part Type	Status
Engine Oil Filters	Done
Hydraulic Return	Done
Primary Fuel	Done
Fuel /Water	Done
Outer Air	Done
Inner Air	Done
Breather	Done
A/C Filter x1	Done
A/C Filter x1	Done
Grease	Done
Brake Cleaner	Done

Fluid Levels & Replacements

Engine Oil 20 LTS	Final Drive Oil 20 LTS	Hydraulic Oil 0 LTS	Coolant 0 LTS	Grease 1 LTS
----------------------	---------------------------	------------------------	------------------	-----------------

Service Checklist Completed

Service Completion: Reset Machine Dash Hours Fit Next Service Sticker to Window




KOBELCO

Model : SK135SR-7

Serial Number : YY09046733

YN20T02489P1



vice hours.

service hours.

manuals.

YY20T01727P2



Quick Hitch Inspection

Brand:	A2
Model:	Quick hitch
Serial Number:	A20006132-1
Inspection Interval:	1000

Inspection Results:

Is the quick hitch free from oil leaks?	Yes
Does the quick hitch unlock correctly?	Yes
Does the quick hitch lock correctly?	Yes
Identification plate present?	Yes
Visual inspection for cracks?	Yes
Picks up attachment correctly?	Yes
Buzzer works?	Yes
Switch protected by cover/lock?	Yes
Hoses in good condition?	Yes
Free from excessive wear?	Yes

Service Completion

Service Date:	July 2, 2025 11:40 am	Report Generated:	July 2, 2025 11:40 am
Technician:	Lachlan Garde	RO Number:	E32307