



MACHINE SERVICE REPORT

RO Number: E32297 | Service Date: July 7, 2025 11:59 am

Machine Details

Customer:	AUSTRALIAN HAMMER	Hour Meter:	2961HRS
Model:	SK135SR-7	Service Type:	1000HRS
Serial Number:	YY09047237	Service Interval:	1000 Hour Service

Before Service Photos





Parts Replaced/Service

Part Type	Status
Engine Oil Filters	Done
Hydraulic Return	Done
Primary Fuel	Done
Fuel /Water	Done
Outer Air	Done
Inner Air	Done
A/C Filter x1	Done
Breather	Done
Brake Cleaner	Done
Grease	Done

Fluid Levels & Replacements

Engine Oil 20 LTS	Final Drive Oil 20 LTS	Hydraulic Oil 0 LTS	Coolant 0 LTS	Grease 1 LTS
----------------------	---------------------------	------------------------	------------------	-----------------

Service Checklist Completed

Service Completion:

Reset Machine Dash Hours
Fit Next Service Sticker to Window

After Service Photos





Quick Hitch Inspection

Brand:	A2
Model:	QUICK HITCH
Serial Number:	NO I'D PLATE
Inspection Interval:	1000

Inspection Results:

Is the quick hitch free from oil leaks?	Yes
Does the quick hitch unlock correctly?	Yes
Does the quick hitch lock correctly?	Yes
Identification plate present?	No
Visual inspection for cracks?	Yes
Picks up attachment correctly?	Yes
Buzzer works?	Yes
Switch protected by cover/lock?	Yes
Hoses in good condition?	Yes
Free from excessive wear?	Yes

Service Completion

Service Date:	July 7, 2025 11:59 am	Report Generated:	July 7, 2025 11:59 am
Technician:	631	RO Number:	E32297