



MACHINE SERVICE REPORT

RO Number: E32422 | Service Date: July 17, 2025 3:08 pm

Machine Details

Customer:	Australian hammer	Hour Meter:	3140
Model:	Sk135-7	Service Type:	1000hr
Serial Number:	YY09048083	Service Interval:	1000 Hour Service

Before Service Photos



Parts Replaced/Serviced

Part Type	Status
Engine Oil Filters	Done
Hydraulic Return	Done
Primary Fuel	Done
Fuel /Water	Done
Outer Air	Done
Inner Air	Done
Breather	Done
A/C Filter x1	Done
A/C Filter x1	Done
Oil Sample Kits	Done
Grease	Done
Brake Cleaner	Done

Fluid Levels & Replacements

Engine Oil 20 LTS	Final Drive Oil 20 LTS	Hydraulic Oil 20 LTS	Coolant 0 LTS	Grease 1 LTS
-----------------------------	----------------------------------	--------------------------------	-------------------------	------------------------

Service Checklist Completed

Service Completion:

Reset Machine Dash Hours
Fit Next Service Sticker to Window

After Service Photos



Quick Hitch Inspection

Brand:	A2
Model:	Quick hitch
Serial Number:	Can't read the plate
Inspection Interval:	1000

Inspection Results:

Is the quick hitch free from oil leaks?	Yes
Does the quick hitch unlock correctly?	Yes
Does the quick hitch lock correctly?	Yes
Identification plate present?	Yes
Visual inspection for cracks?	Yes
Picks up attachment correctly?	Yes
Buzzer works?	Yes
Switch protected by cover/lock?	Yes
Hoses in good condition?	Yes
Free from excessive wear?	Yes

Service Completion

Service Date:	July 17, 2025 3:08 pm	Report Generated:	July 17, 2025 3:08 pm
Technician:	Lachlan Garde	RO Number:	E32422