



MACHINE SERVICE REPORT

RO Number: E34257 | Service Date: June 12, 2026 12:27 pm

Machine Details

Customer:	Australian hammer	Hour Meter:	2950
Model:	Sk135-7	Service Type:	1000
Serial Number:	YY09048372	Service Interval:	1000 Hour Service













Parts Replaced/Serviceed

Part Type	Status
Engine Oil Filters	Done
Hydraulic Return	Done
Primary Fuel	Done
Fuel /Water	Done
Outer Air	Done
Inner Air	Done
A/C Filter x1	Done
A/C Filter x1	Done
Grease	Done
Brake Cleaner	Done

Fluid Levels & Replacements

Engine Oil 17 LTS	Final Drive Oil 6 LTS	Hydraulic Oil 20 LTS	Coolant 0 LTS	Grease 1 LTS
----------------------	--------------------------	-------------------------	------------------	-----------------

System Measurements

Charge Rate 28 V	Pump 1 240 BAR	Pump 2 240 BAR	Pump 3 240 BAR	Pilot 40 BAR
---------------------	-------------------	-------------------	-------------------	-----------------

Service Checklist Completed

1000 Hour Service:

Replace Engine Oil Fluid
Replace Engine Oil Filter
Replace Hydraulic Filter
Replace Primary Fuel Filters
Check Hydraulic Oil Level
Check Slew Reduction Oil Level
Check Final Drive Oil Level
Check Coolant Radiator Level
Check Engine Fan Belts Tension
Check A/C Belt Tension
Check / Adjust Track Tension
Check Upper / Lower Rollers
Check Machine Horn Operation
Check Radiator Hoses, No Leaks
Check 2 Speed Travel Operation
Check Neutral Start Working
Check Safety Lever Operation
Check No Fault Codes Active
Check E-Stop Operation
Drain Water from Fuel Tank
Check No Visual Oil Leaks
Clean Outer Air Filter
Clean Cabin Air Filters
Check Flashing Light Operation
Check Work Light Operation
Visual Inspection Over Machine
Check Wiper Bottle Water Level
Check Quick Hitch Operation
Check Quick Hitch Pins / Bolts
Check Radiator Cap Condition
Grease Machine - All Pins / Slew
Replace Fuel Water Filters
Replace Primary Fuel Filter
Replace Engine Outer Air Filter
Clean Radiator Core Filters
Replace Final Drive Reduction Oils
Carry Out Oil Sampling - Warranty
Replace Hydraulic Return Filter
Replace Engine Inner Air Filter
Replace Cabin A/C Filters
Carry Out Undercarriage Inspection

Service Completion:

Reset Machine Dash Hours
Fit Next Service Sticker to Window

Comments:

The right cab light bracket is snapped off and the light is in the cab

After Service Photos











KOBELCO

Model : SK135SR-7

Serial Number : YY09048372

YN20T02489P1



Quick Hitch Inspection

Brand: Salmon

Model: Tilt hitch

Serial Number: No plate

Inspection Interval: 1000

Inspection Results:

Is the quick hitch free from oil leaks? **Yes**

Does the quick hitch unlock correctly? **Yes**

Does the quick hitch lock correctly? **Yes**

Identification plate present? **No**

Visual inspection for cracks? **Yes**

Picks up attachment correctly? **Yes**

Buzzer works? **Yes**

Switch protected by cover/lock? **Yes**

Hoses in good condition? **Yes**

Free from excessive wear? **Yes**

Service Completion

Service Date: June 12, 2026 12:27 pm

Technician: Lachlan Garde

Report Generated: June 12, 2026 12:27 pm

RO Number: E34257