


## MACHINE SERVICE REPORT

RO Number: E32625 | Service Date: August 22, 2025 7:37 am


## **Machine Details**


Customer:	Aussie hammer	Hour Meter:	3004
Model:	Sk135sr-7	Service Type:	1000
Serial Number:	Yy09048749	Service Interval:	1000 Hour Service














# Parts Replaced/Serviced

Part Type	Status
Engine Oil Filters	Done
Hydraulic Return	Done
Primary Fuel	Done
Fuel /Water	Done
Outer Air	Done
Inner Air	Done
Breather	Done
A/C Filter x1	Done
Oil Sample Kits	Done
Grease	Done
Brake Cleaner	Done

## Fluid Levels & Replacements

Engine Oil
16 LTS

Final Drive Oil 5 LTS

Hydraulic Oil
10 LTS

### **System Measurements**

Charge Rate	Pump 1	Pump 2	Pump 3	Pilot
29 V	340 BAR	340 BAR	190 BAR	30 BAR

### **Service Checklist Completed**

#### 1000 Hour Service:

Replace Engine Oil Fluid

Replace Engine Oil Filter

Replace Hydraulic Filter

Replace Primary Fuel Filters

Check Hydraulic Oil Level

Check Slew Reduction Oil Level

Check Final Drive Oil Level

Check Coolant Radiator Level

Check Engine Fan Belts Tension

Check A/C Belt Tension

Check / Adjust Track Tension

Check Upper / Lower Rollers

Check Machine Horn Operation

Check Radiator Hoses, No Leaks

Check 2 Speed Travel Operation

Check Neutral Start Working

Check Safety Lever Operation

Check No Fault Codes Active

Check E-Stop Operation

Drain Water from Fuel Tank

Check No Visual Oil Leaks

Clean Outer Air Filter

Clean Cabin Air Filters

Check Flashing Light Operation

Check Work Light Operation

Visual Inspection Over Machine

Check Wiper Bottle Water Level

Check Quick Hitch Operation

Check Quick Hitch Pins / Bolts

Check Radiator Cap Condition

Grease Machine - All Pins / Slew

Replace Fuel Water Filters

Replace Primary Fuel Filter

Replace Engine Outer Air Filter

Clean Radiator Core Filters

Replace Final Drive Reduction Oils

Carry Out Oil Sampling - Warranty

Replace Hydraulic Return Filter

Replace Engine Inner Air Filter

Replace Cabin A/C Filters


Carry Out Undercarriage Inspection


#### **Service Completion:**


Reset Machine Dash Hours

Fit Next Service Sticker to Window


# After Service Photos











# **Quick Hitch Inspection**

Brand:	Salmon
Model:	Tilt hitch
Serial Number:	58997
Inspection Interval:	1000

### Inspection Results:

Is the quick hitch free from oil leaks?	Yes
Does the quick hitch unlock correctly?	Yes
Does the quick hitch lock correctly?	Yes
Identification plate present?	Yes
Visual inspection for cracks?	Yes
Picks up attachment correctly?	Yes
Buzzer works?	Yes
Switch protected by cover/lock?	Yes
Hoses in good condition?	Yes
Free from excessive wear?	Yes

# **Service Completion**

Service Date:	August 22, 2025 7:37 am	Report Generated:	August 22, 2025 7:37 am
Technician:	728	RO Number:	E32625

STM Trucks & Machinery Pty Ltd | 20-26 Dunn Rd, Smeaton Grange NSW 2567 | 02 4647 4488 | ABN 36 142 316 916 / MD 038046

This service report has been reviewed and approved by our service department.