



MACHINE SERVICE REPORT

RO Number: E32278 | Service Date: July 12, 2025 11:32 am

Machine Details

Customer:	AUSTRALIAN HAMMER	Hour Meter:	3185
Model:	Sk135-7	Service Type:	1000
Serial Number:	YY09048729	Service Interval:	1000 Hour Service

Before Service Photos







Parts Replaced/Service

Part Type	Status
Engine Oil Filters	Done
Hydraulic Return	Done
Primary Fuel	Done
Fuel /Water	Done
Fuel /Water	Done
Outer Air	Done
Inner Air	Done
Breather	Done
A/C Filter x1	Done
A/C Filter x1	Done
Grease	Done
Brake Cleaner	Done
Oil Sample Kits	Done

Fluid Levels & Replacements

Engine Oil 20 LTS	Final Drive Oil 20 LTS	Hydraulic Oil 0 LTS	Coolant 0 LTS	Grease 1 LTS
----------------------	---------------------------	------------------------	------------------	-----------------

Service Checklist Completed

Service Completion:

Reset Machine Dash Hours
Fit Next Service Sticker to Window

After Service Photos



Quick Hitch Inspection

Brand:	A2
Model:	Tilt hitch
Serial Number:	No I'd plate
Inspection Interval:	1000

Inspection Results:

Is the quick hitch free from oil leaks?	Yes
Does the quick hitch unlock correctly?	Yes
Does the quick hitch lock correctly?	Yes
Identification plate present?	No
Visual inspection for cracks?	Yes
Picks up attachment correctly?	Yes
Buzzer works?	Yes
Switch protected by cover/lock?	Yes
Hoses in good condition?	Yes
Free from excessive wear?	Yes

Service Completion

Service Date:	July 12, 2025 11:32 am	Report Generated:	July 12, 2025 11:32 am
Technician:	Lachlan Garde	RO Number:	E32278