



MACHINE SERVICE REPORT

RO Number: E32323 | Service Date: July 22, 2025 7:17 am

Machine Details

Customer:	AUSTRALIAN HAMMER	Hour Meter:	2909hrs
Model:	Sk330-10	Service Type:	1000hr
Serial Number:	LC14405069	Service Interval:	1000 Hour Service

Before Service Photos





Parts Replaced/Service

Part Type	Status
Engine Oil Filters	Done
Hydraulic Return	Done
Primary Fuel	Done
Primary Fuel	Done
Fuel /Water	Done
Outer Air	Done
Inner Air	Done
Breather	Done
A/C Filter x1	Done
A/C Filter x1	Done
Oil Sample Kits	Done
Grease	Done
Brake Cleaner	Done

Fluid Levels & Replacements

Engine Oil 40 LTS	Final Drive Oil 20 LTS	Hydraulic Oil 10 LTS	Coolant 1 LTS	Grease 1 LTS
----------------------	---------------------------	-------------------------	------------------	-----------------

System Measurements

Charge Rate 28 V

Service Checklist Completed

1000 Hour Service:

Replace Engine Oil Fluid
Replace Engine Oil Filter
Replace Hydraulic Filter
Replace Primary Fuel Filters
Check Hydraulic Oil Level
Check Slew Reduction Oil Level
Check Final Drive Oil Level
Check Coolant Radiator Level
Check Engine Fan Belts Tension
Check A/C Belt Tension
Check / Adjust Track Tension
Check Upper / Lower Rollers
Check Machine Horn Operation
Check Radiator Hoses, No Leaks
Check 2 Speed Travel Operation
Check Neutral Start Working
Check Safety Lever Operation
Check No Fault Codes Active
Check E-Stop Operation
Drain Water from Fuel Tank
Check No Visual Oil Leaks
Clean Outer Air Filter
Clean Cabin Air Filters
Check Flashing Light Operation
Check Work Light Operation
Visual Inspection Over Machine
Check Wiper Bottle Water Level
Check Quick Hitch Operation
Check Quick Hitch Pins / Bolts
Check Radiator Cap Condition
Grease Machine - All Pins / Slew
Replace Fuel Water Filters
Replace Primary Fuel Filter
Replace Engine Outer Air Filter
Clean Radiator Core Filters
Replace Final Drive Reduction Oils
Carry Out Oil Sampling - Warranty
Replace Hydraulic Return Filter
Replace Engine Inner Air Filter
Replace Cabin A/C Filters
Carry Out Undercarriage Inspection

Service Completion:

Reset Machine Dash Hours
Fit Next Service Sticker to Window

After Service Photos



SYDNEY TRUCKS & MACHINERY CENTRE
 Ph: (02) 4647 4488
 LAST SERVICE
 NEXT SERVICE
 Trans Oil Diff Oil Coolant
 HRS
 Date
 HRS
 Date
 Eng Oil

Quick Hitch Inspection

Brand: Doherty

Model: Hitch

Inspection Interval: 1000

Inspection Results:

Is the quick hitch free from oil leaks? **Yes**

Does the quick hitch unlock correctly? **Yes**

Does the quick hitch lock correctly? **Yes**

Identification plate present? **Yes**

Visual inspection for cracks? **Yes**

Picks up attachment correctly? **Yes**

Buzzer works? **Yes**

Switch protected by cover/lock? **Yes**

Hoses in good condition? **Yes**

Free from excessive wear? **Yes**

Service Completion

Service Date: July 22, 2025 7:17 am

Technician: 631 & 608

Report Generated: July 22, 2025 7:17 am

RO Number: E32323

STM Trucks & Machinery Pty Ltd | 20-26 Dunn Rd, Smeaton Grange NSW 2567 | 02 4647 4488 | ABN 36 142 316 916 / MD 038046

This service report has been reviewed and approved by our service department.