

## Field Service Inspection

CCR

● 0 ● 1 ● 7 ● 3

|                   |  |                  |   |
|-------------------|--|------------------|---|
| Inspection Number | 17488098   | Customer No      | 2969824372                              |
| Serial Number     | SGJ20461   | Customer Name    | AUSTRALIAN HAMMER SUPPLIES HIRE PTY LTD |
| Make              | CATERPILLAR  | Completed On     | 17/06/2024 11:18:45 AM                  |
| Model             | 335  | Inspector        | Oscar Forlico                           |
| Equipment Family  | Medium Hydraulic Excavator                                 | PDF Generated On | 17/06/2024                              |
| Asset ID          | AHSH160  | SMU              | 6290.64 Hours                           |
| Location          | 118 Yapunyah St, Barellan, New South Wales 2665, Australia | Coordinates      | 0, 0, 0                                 |

Technician



### General Info & Comments

● **General info/Comments** MONITOR

Comments: Final drives low oil level need top up

### Wheels / Tyres

● **1.1 Conditional check of Wheels and Tyres** N/A

### Undercarriage

● **2.1 Conditional Check of Undercarriage.** GOOD

### Engine

● **3.1 Conditional Check of Engine.** GOOD

### Transmission

● **4.1 Conditional Check of Transmission** N/A

### Differential

● **5.1 External Conditional Check of Differential.** N/A

## Hydraulics

- 6.1 Visual Conditional check of Hydraulics. *NORMAL*

## Frame & Body

- 7.1 Visual Inspection of Frame & Body. *NORMAL*

## Operator Station

- 8.1 Operational check of Operators Station. *NORMAL RECONDITION*

## G.E.T.

- 9.1 Visual inspection of G.E.T. *NORMAL*

9.1.1 Check measurement against what a full life component would measure as 100%.

## Electrical

- 10.1 Visual inspection of connectors & harness condition. *NORMAL*