



# MACHINE SERVICE REPORT

RO Number: E32294 | Service Date: July 7, 2025 12:59 pm

## Machine Details

Customer:	Australian hammer supplies hire holdings pty ptd	Hour Meter:	2065
Model:	Sk235sr-2	Service Type:	2000
Serial Number:	Yf06005182	Service Interval:	2000 Hour Service

## Parts Replaced/Service

Part Type	Status
Engine Oil Filters	Done
Hydraulic Return	Done
Primary Fuel	Done
Fuel /Water	Done
Outer Air	Done
Inner Air	Done
Breather	Done
A/C Filter x1	Done
A/C Filter x1	Done
Oil Sample Kits	Done
Grease	Done
Brake Cleaner	Done

## Fluid Levels & Replacements

Engine Oil 23 LTS	Final Drive Oil 20 LTS	Hydraulic Oil 180 LTS	Coolant 15 LTS	Grease 1 LTS
----------------------	---------------------------	--------------------------	-------------------	-----------------

## Service Checklist Completed

### Service Completion:

Reset Machine Dash Hours  
Fit Next Service Sticker to Window

## Quick Hitch Inspection

Brand:	Komatsu
Model:	Power tilt
Serial Number:	Komt-80-63
Inspection Interval:	2000

### Inspection Results:

Is the quick hitch free from oil leaks?	Yes
Does the quick hitch unlock correctly?	Yes
Does the quick hitch lock correctly?	Yes
Identification plate present?	Yes
Visual inspection for cracks?	Yes
Picks up attachment correctly?	Yes
Buzzer works?	Yes
Switch protected by cover/lock?	Yes
Hoses in good condition?	Yes
Free from excessive wear?	Yes

## Service Completion

Service Date:	July 7, 2025 12:59 pm	Report Generated:	July 7, 2025 12:59 pm
Technician:	Mitchell	RO Number:	E32294