



MACHINE SERVICE REPORT

RO Number: E33373 | Service Date: January 15, 2026 12:21 pm

Machine Details

Customer:	AHSH	Hour Meter:	2621
Model:	SK235SR-2	Service Type:	500
Serial Number:	YF06005182	Service Interval:	500 Hour Service

Before Service Photos







No. YF06005182

2432T1530

ER



Parts Replaced/Service

Part Type	Status
Engine Oil Filters	Done
Hydraulic Return	Done
Primary Fuel	Done
Fuel /Water	Done
Outer Air	Done
Grease	Done
Brake Cleaner	Done

Fluid Levels & Replacements

Engine Oil 25 LTS	Final Drive Oil 15 LTS	Hydraulic Oil 20 LTS	Grease 1 LTS
----------------------	---------------------------	-------------------------	-----------------

System Measurements

Charge Rate
28 V

Service Checklist Completed

500 Hour Service:

Replace Engine Oil Fluid
Replace Engine Oil Filter
Replace Hydraulic Filter
Replace Primary Fuel Filters
Check Hydraulic Oil Level
Check Slew Reduction Oil Level
Check Final Drive Oil Level
Check Coolant Radiator Level
Check Engine Fan Belts Tension
Check A/C Belt Tension
Check / Adjust Track Tension
Check Upper / Lower Rollers
Check Machine Horn Operation
Check Radiator Hoses, No Leaks
Check 2 Speed Travel Operation
Check Neutral Start Working
Check Safety Lever Operation
Check No Fault Codes Active
Check E-Stop Operation
Drain Water from Fuel Tank
Check No Visual Oil Leaks
Clean Outer Air Filter
Clean Cabin Air Filters
Check Flashing Light Operation
Check Work Light Operation
Visual Inspection Over Machine
Check Wiper Bottle Water Level
Check Quick Hitch Operation
Check Quick Hitch Pins / Bolts
Check Radiator Cap Condition
Grease Machine - All Pins / Slew
Replace Fuel Water Filters
Replace Primary Fuel Filter
Replace Engine Outer Air Filter
Clean Radiator Core Filters
Replace Final Drive Reduction Oils

Service Completion:

Reset Machine Dash Hours
Fit Next Service Sticker to Window

Comments:

Found missing retaining bolts for h-link / link arm pin
Fitted new bolt

Next Service Due:

3121

After Service Photos









Quick Hitch Inspection

Brand:	Geith
Model:	Tilt hitch
Serial Number:	1
Inspection Interval:	500

Inspection Results:

Is the quick hitch free from oil leaks?	Yes
Does the quick hitch unlock correctly?	Yes
Does the quick hitch lock correctly?	Yes
Identification plate present?	No
Visual inspection for cracks?	Yes
Picks up attachment correctly?	Yes
Buzzer works?	Yes
Switch protected by cover/lock?	Yes
Hoses in good condition?	Yes
Free from excessive wear?	Yes

Service Completion

Service Date:	January 15, 2026 12:21 pm	Report Generated:	January 15, 2026 12:21 pm
Technician:	705	RO Number:	E33373