



# MACHINE SERVICE REPORT

RO Number: E32839 | Service Date: September 18, 2025 10:50 am

## Machine Details

|                |                   |                   |                  |
|----------------|-------------------|-------------------|------------------|
| Customer:      | Australian hammer | Hour Meter:       | 2472             |
| Model:         | Sk380             | Service Type:     | 500              |
| Serial Number: | LR01000234        | Service Interval: | 500 Hour Service |



Before Service Photos











MODEL NO. 1032908  
SERIAL NUMBER 1032908  
MACHINE TYPE SK330/350  
HYDRAULIC FLOW RATE 5.8 GAL/MIN  
HYDRAULIC WORKING PRESSURE 26.6 T/MIN  
LIFT EYE SWL (KG) 5000  
WEIGHT (KG) 504





Parts Replaced/Service

| Part Type          | Status |
|--------------------|--------|
| Engine Oil Filters | Done   |
| Hydraulic Return   | Done   |
| Primary Fuel       | Done   |
| Fuel /Water        | Done   |
| Outer Air          | Done   |
| Brake Cleaner      | Done   |
| Grease             | Done   |

Fluid Levels & Replacements

|                      |                           |                        |                  |                 |
|----------------------|---------------------------|------------------------|------------------|-----------------|
| Engine Oil<br>40 LTS | Final Drive Oil<br>20 LTS | Hydraulic Oil<br>0 LTS | Coolant<br>0 LTS | Grease<br>1 LTS |
|----------------------|---------------------------|------------------------|------------------|-----------------|

## System Measurements

Charge Rate

**28 V**

## Service Checklist Completed

### 500 Hour Service:

- Replace Engine Oil Fluid
- Replace Engine Oil Filter
- Replace Hydraulic Filter
- Replace Primary Fuel Filters
- Check Hydraulic Oil Level
- Check Slew Reduction Oil Level
- Check Final Drive Oil Level
- Check Coolant Radiator Level
- Check Engine Fan Belts Tension
- Check A/C Belt Tension
- Check / Adjust Track Tension
- Check Upper / Lower Rollers
- Check Machine Horn Operation
- Check Radiator Hoses, No Leaks
- Check 2 Speed Travel Operation
- Check Neutral Start Working
- Check Safety Lever Operation
- Check No Fault Codes Active
- Check E-Stop Operation
- Drain Water from Fuel Tank
- Check No Visual Oil Leaks
- Clean Outer Air Filter
- Clean Cabin Air Filters
- Check Flashing Light Operation
- Check Work Light Operation
- Visual Inspection Over Machine
- Check Wiper Bottle Water Level
- Check Quick Hitch Operation
- Check Quick Hitch Pins / Bolts
- Check Radiator Cap Condition
- Grease Machine - All Pins / Slew
- Replace Fuel Water Filters
- Replace Primary Fuel Filter
- Replace Engine Outer Air Filter
- Clean Radiator Core Filters
- Replace Final Drive Reduction Oils

### Service Completion:

- Reset Machine Dash Hours
- Fit Next Service Sticker to Window



## After Service Photos



















Quick Hitch Inspection

|                      |             |
|----------------------|-------------|
| Brand:               | SBA         |
| Model:               | Quick hitch |
| Serial Number:       | 1032908     |
| Inspection Interval: | 500         |

Inspection Results:

|                                         |     |
|-----------------------------------------|-----|
| Is the quick hitch free from oil leaks? | Yes |
| Does the quick hitch unlock correctly?  | Yes |
| Does the quick hitch lock correctly?    | Yes |
| Identification plate present?           | Yes |
| Visual inspection for cracks?           | Yes |
| Picks up attachment correctly?          | Yes |
| Buzzer works?                           | Yes |
| Switch protected by cover/lock?         | Yes |
| Hoses in good condition?                | Yes |
| Free from excessive wear?               | Yes |

|                    |                             |                   |                             |
|--------------------|-----------------------------|-------------------|-----------------------------|
| Service Completion |                             |                   |                             |
| Service Date:      | September 18, 2025 10:50 am | Report Generated: | September 18, 2025 10:50 am |
| Technician:        | Lachlan Garde               | RO Number:        | E32839                      |