


MACHINE SERVICE REPORT

RO Number: E32356 | Service Date: July 8, 2025 1:04 pm

Machine Details

Customer:	AUSTRALIAN HAMMER	Hour Meter:	1485hrs
Model:	Sk380XDLC-10	Service Type:	500hr
Serial Number:	YC14405666	Service Interval:	500 Hour Service

Before Service Photos



Parts Replaced/Serviced

Part Type	Status
Engine Oil Filters	Done
Hydraulic Return	Done
Primary Fuel	Done
Fuel /Water	Done
Outer Air	Done
Grease	Done
Brake Cleaner	Done

Fluid Levels & Replacements

Engine Oil	Final Drive Oil	Grease
40 LTS	20 LTS	1 LTS
40 213	20 213	T LIS

System Measurements

Charge Rate

Service Checklist Completed


500 Hour Service:

Replace Engine Oil Fluid Replace Engine Oil Filter Replace Hydraulic Filter Replace Primary Fuel Filters Check Hydraulic Oil Level Check Slew Reduction Oil Level Check Final Drive Oil Level Check Coolant Radiator Level Check Engine Fan Belts Tension Check A/C Belt Tension Check / Adjust Track Tension Check Upper / Lower Rollers Check Machine Horn Operation Check Radiator Hoses, No Leaks Check 2 Speed Travel Operation Check Neutral Start Working Check Safety Lever Operation Check No Fault Codes Active Check E-Stop Operation Drain Water from Fuel Tank Check No Visual Oil Leaks Clean Outer Air Filter Clean Cabin Air Filters Check Flashing Light Operation Check Work Light Operation Visual Inspection Over Machine Check Wiper Bottle Water Level Check Quick Hitch Operation Check Quick Hitch Pins / Bolts Check Radiator Cap Condition Grease Machine - All Pins / Slew Replace Fuel Water Filters **Replace Primary Fuel Filter** Replace Engine Outer Air Filter Clean Radiator Core Filters Replace Final Drive Reduction Oils

Service Completion:

Reset Machine Dash Hours Fit Next Service Sticker to Window

After Service Photos







Quick Hitch Inspection

Brand:	Geith
Model:	Tilt
Inspection Interval:	500

Inspection Results:

Is the quick hitch free from oil leaks?	Yes
Does the quick hitch unlock correctly?	Yes
Does the quick hitch lock correctly?	Yes
Identification plate present?	Yes
Visual inspection for cracks?	Yes
Picks up attachment correctly?	Yes
Buzzer works?	Yes
Switch protected by cover/lock?	Yes
Hoses in good condition?	Yes
Free from excessive wear?	Yes

Service Date: July	y 8, 2025 1:04 pm	Report Generated:	July 8, 2025 1:04 pm
Technician: Ror	ry 608	RO Number:	E32356

STM Trucks & Machinery Pty Ltd | 20-26 Dunn Rd, Smeaton Grange NSW 2567 | 02 4647 4488 | ABN 36 142 316 916 / MD 038046

This service report has been reviewed and approved by our service department.