

MACHINE SERVICE REPORT

RO Number: E32869 | Service Date: September 24, 2025 9:08 am

Machine Details

Customer:	Australian hammer supplies	Hour Meter:	962
Model:	Sk135sr-7	Service Type:	1000
Serial Number:	Yy09053096	Service Interval:	1000 Hour Service

Before Service Photos



Parts Replaced/Service

Part Type	Status
Engine Oil Filters	Done
Hydraulic Return	Done
Primary Fuel	Done
Fuel /Water	Done
Fuel /Water	Done
Outer Air	Done
Inner Air	Done
Breather	Done
A/C Filter x1	Done
A/C Filter x1	Done
Oil Sample Kits	Done
Grease	Done
Brake Cleaner	Done

Fluid Levels & Replacements

Engine Oil 20 LTS	Final Drive Oil 20 LTS
----------------------	---------------------------

System Measurements

Charge Rate 28 V

Service Checklist Completed

1000 Hour Service:

Replace Engine Oil Fluid
Replace Engine Oil Filter
Replace Hydraulic Filter
Replace Primary Fuel Filters
Check Hydraulic Oil Level
Check Slew Reduction Oil Level
Check Final Drive Oil Level
Check Coolant Radiator Level
Check Engine Fan Belts Tension
Check A/C Belt Tension
Check / Adjust Track Tension
Check Upper / Lower Rollers
Check Machine Horn Operation
Check Radiator Hoses, No Leaks
Check 2 Speed Travel Operation
Check Neutral Start Working
Check Safety Lever Operation
Check No Fault Codes Active
Check E-Stop Operation
Drain Water from Fuel Tank
Check No Visual Oil Leaks
Clean Outer Air Filter
Clean Cabin Air Filters
Check Flashing Light Operation
Check Work Light Operation
Visual Inspection Over Machine
Check Wiper Bottle Water Level
Check Quick Hitch Operation
Check Quick Hitch Pins / Bolts
Check Radiator Cap Condition
Grease Machine - All Pins / Slew
Replace Fuel Water Filters
Replace Primary Fuel Filter
Replace Engine Outer Air Filter
Clean Radiator Core Filters
Replace Final Drive Reduction Oils
Carry Out Oil Sampling - Warranty
Replace Hydraulic Return Filter
Replace Engine Inner Air Filter
Replace Cabin A/C Filters
Carry Out Undercarriage Inspection

Service Completion:

Reset Machine Dash Hours
Fit Next Service Sticker to Window

Next Service Due:

1500

After Service Photos









KOBELCO

Model :

SK35SR-7

Serial Number :

YY09053096

YN20T02489P1



www.kobelco.com

Ph: 1-800-820-STIK

⚠ DANGER

**CRUSH
ZONE**
Keep Clear

EX WD025

727P3



STM
TRUCKS & MACHINERY

Call 1300 305 420
Or book online



Date of last service

24-9-25

Hours at last service

962hrs

Next service due


24-9-25

Hours due for service

1500hr

WARNING

One must NOT
operate the
machine until
all safety
implements
are in place
and park brake on
parking phone. WD105




safety@stm.com

WARNING

DRIVER ONLY
Strictly NO
passengers.
WD12

Regarding
the use of the
mechanical
structure
Because
disappearing
pipings or
attachments



Quick Hitch Inspection

Brand: Gieth

Model: Tilt

Inspection Interval: 1000

Inspection Results:

Is the quick hitch free from oil leaks? **Yes**

Does the quick hitch unlock correctly? **Yes**

Does the quick hitch lock correctly? **Yes**

Identification plate present? **No**

Visual inspection for cracks? **Yes**

Picks up attachment correctly? **Yes**

Buzzer works? **Yes**

Switch protected by cover/lock? **Yes**

Hoses in good condition? **Yes**

Free from excessive wear? **Yes**

Service Completion

Service Date: September 24, 2025 9:08 am

Technician: 565

Report Generated: September 24, 2025 9:08 am

RO Number: E32869