

MACHINE SERVICE REPORT

RO Number: E35458 | Service Date: September 11, 2026 7:46 am

Machine Details


Customer:	Australian hammer supplies	Hour Meter:	2029
Model:	Sk135sr-7	Service Type:	2000
Serial Number:	Yy09053096	Service Interval:	2000 Hour Service

Before Service Photos

Front Left Corner



Front Right Corner




Back Left Corner




Back Right Corner



Serial Plate



Hour Meter



Parts Replaced/Service

Part Type	Status
Engine Oil Filters	Done
Hydraulic Return	Done
Primary Fuel	Done
Fuel /Water	Done
Outer Air	Done
Inner Air	Done
Breather	Done
A/C Filter x1	Done
A/C Filter x1	Done
Oil Sample Kits	Done

Fluid Levels & Replacements

Engine Oil 17 LTS	Final Drive Oil 5 LTS	Hydraulic Oil 90 LTS	Coolant 10 LTS
----------------------	--------------------------	-------------------------	-------------------

System Measurements

Charge Rate 28 V

Service Checklist Completed

2000 Hour Service:

Replace Engine Oil Fluid
Replace Engine Oil Filter
Replace Hydraulic Filter
Replace Primary Fuel Filters
Check Hydraulic Oil Level
Check Slew Reduction Oil Level
Check Final Drive Oil Level
Check Coolant Radiator Level
Check Engine Fan Belts Tension
Check A/C Belt Tension
Check / Adjust Track Tension
Check Upper / Lower Rollers
Check Machine Horn Operation
Check Radiator Hoses, No Leaks
Check 2 Speed Travel Operation
Check Neutral Start Working
Check Safety Lever Operation
Check No Fault Codes Active
Check E-Stop Operation
Drain Water from Fuel Tank
Check No Visual Oil Leaks
Clean Outer Air Filter
Clean Cabin Air Filters
Check Flashing Light Operation
Check Work Light Operation
Visual Inspection Over Machine
Check Wiper Bottle Water Level
Check Quick Hitch Operation
Check Quick Hitch Pins / Bolts
Check Radiator Cap Condition
Grease Machine - All Pins / Slew
Replace Fuel Water Filters
Replace Primary Fuel Filter
Replace Engine Outer Air Filter
Clean Radiator Core Filters
Replace Final Drive Reduction Oils
Carry Out Oil Sampling - Warranty
Replace Hydraulic Return Filter
Replace Engine Inner Air Filter
Replace Cabin A/C Filters
Carry Out Undercarriage Inspection
Replace Hydraulic Tank Breather
Replace Radiator Coolant
Replace Engine Fan Belts
Replace Engine A/C Belts
Refill Grease Bath - Slew
Replace Case Drain Filter
Replace Radiator Cap
Check Slew Ring Bolts

Service Completion:

Reset Machine Dash Hours
Fit Next Service Sticker to Window

Comments:

Hour meter damaged


Spare connector above engine fan damaged (now tapped off)

After Service Photos

Front Left Corner



Front Right Corner




Back Left Corner




Back Right Corner



Hour Meter



Additional Photos



Quick Hitch Inspection

Brand:	A2
Model:	Standard
Inspection Interval:	2000

Inspection Results:

Is the quick hitch free from oil leaks?	Yes
Does the quick hitch unlock correctly?	Yes
Does the quick hitch lock correctly?	Yes
Identification plate present?	Yes
Visual inspection for cracks?	Yes
Picks up attachment correctly?	Yes
Buzzer works?	Yes
Switch protected by cover/lock?	Yes
Hoses in good condition?	Yes
Free from excessive wear?	Yes

Service Completion

Service Date:	September 11, 2026 7:46 am	Report Generated:	September 11, 2026 7:46 am
Technician:	Jerry	RO Number:	E35458

STM Trucks & Machinery Pty Ltd | 20-26 Dunn Rd, Smeaton Grange NSW 2567 | 02 4647 4488 | ABN 36 142 316 916 / MD 038046

This service report has been reviewed and approved by our service department.