



MACHINE SERVICE REPORT

RO Number: E32790 | Service Date: September 11, 2025 11:05 am

Machine Details

Customer:	Australian hammer supplies	Hour Meter:	1495
Model:	Sk225sr-7	Service Type:	500
Serial Number:	Yb09015287	Service Interval:	500 Hour Service

Before Service Photos







Parts Replaced/Service

Part Type	Status
Engine Oil Filters	Done
Hydraulic Return	Done
Primary Fuel	Done
Fuel /Water	Done
Outer Air	Done
Grease	Done
Brake Cleaner	Done

Fluid Levels & Replacements

Engine Oil 25 LTS	Final Drive Oil 15 LTS
----------------------	---------------------------

System Measurements

Charge Rate

28 V

Service Checklist Completed

500 Hour Service:

- Replace Engine Oil Fluid
- Replace Engine Oil Filter
- Replace Hydraulic Filter
- Replace Primary Fuel Filters
- Check Hydraulic Oil Level
- Check Slew Reduction Oil Level
- Check Final Drive Oil Level
- Check Coolant Radiator Level
- Check Engine Fan Belts Tension
- Check A/C Belt Tension
- Check / Adjust Track Tension
- Check Upper / Lower Rollers
- Check Machine Horn Operation
- Check Radiator Hoses, No Leaks
- Check 2 Speed Travel Operation
- Check Neutral Start Working
- Check Safety Lever Operation
- Check No Fault Codes Active
- Check E-Stop Operation
- Drain Water from Fuel Tank
- Check No Visual Oil Leaks
- Clean Outer Air Filter
- Clean Cabin Air Filters
- Check Flashing Light Operation
- Check Work Light Operation
- Visual Inspection Over Machine
- Check Wiper Bottle Water Level
- Check Quick Hitch Operation
- Check Quick Hitch Pins / Bolts
- Check Radiator Cap Condition
- Grease Machine - All Pins / Slew
- Replace Fuel Water Filters
- Replace Primary Fuel Filter
- Replace Engine Outer Air Filter
- Clean Radiator Core Filters
- Replace Final Drive Reduction Oils

Service Completion:

- Reset Machine Dash Hours
- Fit Next Service Sticker to Window

After Service Photos









Quick Hitch Inspection

Brand: Geith

Model: Tilt

Inspection Interval: 500

Inspection Results:

Is the quick hitch free from oil leaks? **Yes**

Does the quick hitch unlock correctly? **Yes**

Does the quick hitch lock correctly? **Yes**

Identification plate present? **No**

Visual inspection for cracks? **Yes**

Picks up attachment correctly? **Yes**

Buzzer works? **Yes**

Switch protected by cover/lock? **Yes**

Hoses in good condition? **Yes**

Free from excessive wear? **Yes**

Service Completion

Service Date: September 11, 2025 11:05 am

Technician: Jerry

Report Generated: September 11, 2025 11:05 am

RO Number: E32790