



MACHINE SERVICE REPORT

RO Number: E33588 | Service Date: January 9, 2026 12:25 pm

Machine Details

Customer:	Australian hammer	Hour Meter:	2070
Model:	Sk225-7	Service Type:	2000
Serial Number:	YB09015287	Service Interval:	2000 Hour Service

Before Service Photos







Parts Replaced/Service

Part Type	Status
Engine Oil Filters	Done
Hydraulic Return	Done
Primary Fuel	Done
Fuel /Water	Done
Outer Air	Done
Inner Air	Done
A/C Filter x1	Done
Breather	Done
A/C Filter x1	Done
Oil Sample Kits	Done
Grease	Done
Brake Cleaner	Done

Fluid Levels & Replacements

Engine Oil 25 LTS	Final Drive Oil 20 LTS	Hydraulic Oil 160 LTS	Coolant 20 LTS	Grease 1 LTS
-----------------------------	----------------------------------	---------------------------------	--------------------------	------------------------

System Measurements

Charge Rate 18 V	Pump 1 250 BAR	Pump 2 250 BAR	Pump 3 250 BAR	Pilot 40 BAR
----------------------------	--------------------------	--------------------------	--------------------------	------------------------

Service Checklist Completed

2000 Hour Service:

Replace Engine Oil Fluid
Replace Engine Oil Filter
Replace Hydraulic Filter
Replace Primary Fuel Filters
Check Hydraulic Oil Level
Check Slew Reduction Oil Level
Check Final Drive Oil Level
Check Coolant Radiator Level
Check Engine Fan Belts Tension
Check A/C Belt Tension
Check / Adjust Track Tension
Check Upper / Lower Rollers
Check Machine Horn Operation
Check Radiator Hoses, No Leaks
Check 2 Speed Travel Operation
Check Neutral Start Working
Check Safety Lever Operation
Check No Fault Codes Active
Check E-Stop Operation
Drain Water from Fuel Tank
Check No Visual Oil Leaks
Clean Outer Air Filter
Clean Cabin Air Filters
Check Flashing Light Operation
Check Work Light Operation
Visual Inspection Over Machine
Check Wiper Bottle Water Level
Check Quick Hitch Operation
Check Quick Hitch Pins / Bolts
Check Radiator Cap Condition
Grease Machine - All Pins / Slew

Replace Fuel Water Filters
Replace Primary Fuel Filter
Replace Engine Outer Air Filter
Clean Radiator Core Filters
Replace Final Drive Reduction Oils
Carry Out Oil Sampling - Warranty
Replace Hydraulic Return Filter
Replace Engine Inner Air Filter
Replace Cabin A/C Filters
Carry Out Undercarriage Inspection
Replace Hydraulic Tank Breather
Replace Radiator Coolant
Replace Engine Fan Belts
Replace Engine A/C Belts
Refill Grease Bath - Slew
Replace Case Drain Filter
Replace Radiator Cap
Check Slew Ring Bolts

Service Completion:

Reset Machine Dash Hours
Fit Next Service Sticker to Window

Comments:

The clip on road pads are all loose and because of that the bolts are all bent or snapped I recommend replacing there are also a few pads missing

Next Service Due:

2500

After Service Photos







Quick Hitch Inspection

Brand:	Geith
Model:	Tilt hitch
Serial Number:	No plate
Inspection Interval:	2000

Inspection Results:

Is the quick hitch free from oil leaks?	Yes
Does the quick hitch unlock correctly?	Yes
Does the quick hitch lock correctly?	Yes
Identification plate present?	No
Visual inspection for cracks?	Yes
Picks up attachment correctly?	Yes
Buzzer works?	Yes
Switch protected by cover/lock?	Yes
Hoses in good condition?	Yes
Free from excessive wear?	Yes

Service Completion

Service Date:	January 9, 2026 12:25 pm	Report Generated:	January 9, 2026 12:25 pm
Technician:	Lachlan Garde	RO Number:	E33588