

MACHINE SERVICE REPORT

RO Number: E35009 | Service Date: July 20, 2026 11:30 am

Machine Details

Customer:	Australian hammer supplies	Hour Meter:	2947
	hire	Service Type:	1000
Model:	SK225SR-7	Service Interval:	1000 Hour Service
Serial Number:	YB09015287		

Before Service Photos

Front Left Corner



Front Right Corner




Back Left Corner



Back Right Corner



Serial Plate



Hour Meter



Parts Replaced/Serviced

Part Type	Status
Engine Oil Filters	Done
Hydraulic Return	Done
Primary Fuel	Done
Fuel /Water	Done
Outer Air	Done
Inner Air	Done
Oil Sample Kits	Done
Breather	Done
A/C Filter x1	Done
A/C Filter x1	Done
Grease	Done
Brake Cleaner	Done

Fluid Levels & Replacements

Engine Oil 24 LTS	Final Drive Oil 15 LTS	Hydraulic Oil 10 LTS	Coolant 1 LTS	Grease 1 LTS
----------------------	---------------------------	-------------------------	------------------	-----------------

System Measurements

Charge Rate 28 V

Service Checklist Completed

1000 Hour Service:

Replace Engine Oil Fluid
Replace Engine Oil Filter
Replace Hydraulic Filter
Replace Primary Fuel Filters
Check Hydraulic Oil Level
Check Slew Reduction Oil Level
Check Final Drive Oil Level
Check Coolant Radiator Level
Check Engine Fan Belts Tension
Check A/C Belt Tension
Check / Adjust Track Tension
Check Upper / Lower Rollers
Check Machine Horn Operation
Check Radiator Hoses, No Leaks
Check 2 Speed Travel Operation
Check Neutral Start Working
Check Safety Lever Operation
Check No Fault Codes Active
Check E-Stop Operation
Drain Water from Fuel Tank
Check No Visual Oil Leaks
Clean Outer Air Filter
Clean Cabin Air Filters
Check Flashing Light Operation
Check Work Light Operation
Visual Inspection Over Machine
Check Wiper Bottle Water Level
Check Quick Hitch Operation
Check Quick Hitch Pins / Bolts
Check Radiator Cap Condition
Grease Machine - All Pins / Slew
Replace Fuel Water Filters
Replace Primary Fuel Filter
Replace Engine Outer Air Filter
Clean Radiator Core Filters
Replace Final Drive Reduction Oils
Carry Out Oil Sampling - Warranty
Replace Hydraulic Return Filter
Replace Engine Inner Air Filter
Replace Cabin A/C Filters
Carry Out Undercarriage Inspection

Service Completion:

Reset Machine Dash Hours
Fit Next Service Sticker to Window

Comments:

Right rear top roller bent

Next Service Due:

3447

After Service Photos

Front Left Corner



Front Right Corner



Back Left Corner




Back Right Corner




Hour Meter



Additional Photos





Quick Hitch Inspection

Brand:	Geith
Model:	Tilt hitch
Serial Number:	1134331
Inspection Interval:	1000

Inspection Results:

Is the quick hitch free from oil leaks?	Yes
Does the quick hitch unlock correctly?	Yes
Does the quick hitch lock correctly?	Yes
Identification plate present?	Yes
Visual inspection for cracks?	Yes
Picks up attachment correctly?	Yes
Buzzer works?	Yes
Switch protected by cover/lock?	Yes
Hoses in good condition?	Yes
Free from excessive wear?	Yes

Service Completion

Service Date:	July 20, 2026 11:30 am	Report Generated:	July 20, 2026 11:30 am
Technician:	705	RO Number:	E35009