



MACHINE SERVICE REPORT

RO Number: E34714 | Service Date: June 18, 2026 9:43 am

Machine Details

Customer:	Australian hammer supplies	Hour Meter:	1530
Model:	Sk135sr-7	Service Type:	500
Serial Number:	Yy09054228	Service Interval:	500 Hour Service

Before Service Photos









KOBELCO

Model :

SK135SR-7

Serial Number :

Y109054228

YN20T02489P1



▲ DANGER

**CRUSH
ZONE**

Keep Clear

By KSD025





thread snapped

Parts Replaced/Service

Part Type	Status
Engine Oil Filters	Done
Hydraulic Return	Done
Primary Fuel	Done
Fuel /Water	Done
Fuel /Water	Done
Outer Air	Done

Fluid Levels & Replacements

Engine Oil 17 LTS	Final Drive Oil 6 LTS
----------------------	--------------------------

System Measurements

Charge Rate 28 V

Service Checklist Completed

500 Hour Service:

Replace Engine Oil Fluid
Replace Engine Oil Filter
Replace Hydraulic Filter
Replace Primary Fuel Filters
Check Hydraulic Oil Level
Check Slew Reduction Oil Level
Check Final Drive Oil Level
Check Coolant Radiator Level
Check Engine Fan Belts Tension
Check A/C Belt Tension
Check / Adjust Track Tension
Check Upper / Lower Rollers
Check Machine Horn Operation
Check Radiator Hoses, No Leaks
Check 2 Speed Travel Operation
Check Neutral Start Working
Check Safety Lever Operation
Check No Fault Codes Active
Check E-Stop Operation
Drain Water from Fuel Tank
Check No Visual Oil Leaks
Clean Outer Air Filter
Clean Cabin Air Filters
Check Flashing Light Operation
Check Work Light Operation
Visual Inspection Over Machine
Check Wiper Bottle Water Level
Check Quick Hitch Operation
Check Quick Hitch Pins / Bolts
Check Radiator Cap Condition
Grease Machine - All Pins / Slew
Replace Fuel Water Filters
Replace Primary Fuel Filter
Replace Engine Outer Air Filter
Clean Radiator Core Filters
Replace Final Drive Reduction Oils

Service Completion:

Reset Machine Dash Hours
Fit Next Service Sticker to Window

Comments:

Hyd Breather housing thread damaged
Missing 3 bolts on hammer hard line on boom replaced
Missing grease nipple in h link replaced

Next Service Due:

2000

After Service Photos











KOBELCO

Model :

SK135SR-7

Serial Number :

Y109054228

YN20T02489P1



▲ DANGER

**CRUSH
ZONE**

Keep Clear

By KSD025







thread snapped



Quick Hitch Inspection

Brand: Salmon

Model: Tilt

Inspection Interval: 500

Inspection Results:

Is the quick hitch free from oil leaks? **Yes**

Does the quick hitch unlock correctly? **Yes**

Does the quick hitch lock correctly? **Yes**

Identification plate present? **Yes**

Visual inspection for cracks? **Yes**

Picks up attachment correctly? **Yes**

Buzzer works? **Yes**

Switch protected by cover/lock? **Yes**

Hoses in good condition? **Yes**

Free from excessive wear? **Yes**

Service Completion

Service Date: June 18, 2026 9:43 am

Report Generated: June 18, 2026 9:43 am

Technician: Jerry

RO Number: E34714

STM Trucks & Machinery Pty Ltd | 20-26 Dunn Rd, Smeaton Grange NSW 2567 | 02 4647 4488 | ABN 36 142 316 916 / MD 038046

This service report has been reviewed and approved by our service department.