



MACHINE SERVICE REPORT

RO Number: E33382 | Service Date: November 26, 2025 2:16 pm

Machine Details

Customer:	Australian hammer	Hour Meter:	221
Model:	Sk135-7	Service Type:	50
Serial Number:	YY09060911	Service Interval:	50 Hour Service

Before Service Photos



Parts Replaced/Service

Part Type	Status
Engine Oil Filters	Done
Hydraulic Return	Done
Primary Fuel	Done
Fuel /Water	Done
Fuel /Water	Done
Grease	Done
Brake Cleaner	Done

Fluid Levels & Replacements

Engine Oil 20 LTS	Final Drive Oil 0 LTS	Hydraulic Oil 0 LTS	Coolant 0 LTS	Grease 1 LTS
-----------------------------	---------------------------------	-------------------------------	-------------------------	------------------------

System Measurements

Charge Rate
28 V

Service Checklist Completed

50 Hour Service:

- Replace Engine Oil Fluid
- Replace Engine Oil Filter
- Replace Hydraulic Filter
- Replace Primary Fuel Filters
- Check Hydraulic Oil Level
- Check Slew Reduction Oil Level
- Check Final Drive Oil Level
- Check Coolant Radiator Level
- Check Engine Fan Belts Tension
- Check A/C Belt Tension
- Check / Adjust Track Tension
- Check Upper / Lower Rollers
- Check Machine Horn Operation
- Check Radiator Hoses, No Leaks
- Check 2 Speed Travel Operation
- Check Neutral Start Working
- Check Safety Lever Operation
- Check No Fault Codes Active
- Check E-Stop Operation
- Drain Water from Fuel Tank
- Check No Visual Oil Leaks
- Clean Outer Air Filter
- Clean Cabin Air Filters
- Check Flashing Light Operation
- Check Work Light Operation
- Visual Inspection Over Machine
- Check Wiper Bottle Water Level
- Check Quick Hitch Operation
- Check Quick Hitch Pins / Bolts
- Check Radiator Cap Condition
- Grease Machine - All Pins / Slew

Service Completion:

- Reset Machine Dash Hours
- Fit Next Service Sticker to Window

After Service Photos





Quick Hitch Inspection

Brand:	A2
Model:	Quick hitch
Serial Number:	23881-3
Inspection Interval:	50

Inspection Results:

Is the quick hitch free from oil leaks?	Yes
Does the quick hitch unlock correctly?	Yes
Does the quick hitch lock correctly?	Yes
Identification plate present?	Yes
Visual inspection for cracks?	Yes
Picks up attachment correctly?	Yes
Buzzer works?	Yes
Switch protected by cover/lock?	Yes
Hoses in good condition?	Yes
Free from excessive wear?	Yes

Service Completion

Service Date:	November 26, 2025 2:16 pm	Report Generated:	November 26, 2025 2:16 pm
Technician:	Lachlan Garde	RO Number:	E33382